

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24070182/DMA3Q2**Date:** 14/01/2025REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MCV0009112
Claimant Vehicle No : SHC7899S **Insured Vehicle No :** PD1631L
 Date of Loss: 04/07/2024 Nature of Claim: TP Claim No: MCV2024D0007810

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC7899S**
 Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2C13921
 Reg. Date: 15/05/2019 (Man. Year: 2018) Chassis No: JTDKB3FU703080345
 Colour: Yellow Odometer: 0 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
 Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,848.66	13,866.09	12,982.57	48.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,620.00	2,030.00	3,590.00	63.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,468.66	15,896.09	16,572.57	51.04
Approved Total (Overridden) (S\$)		14,300.00		
(S\$)	32,468.66	14,300.00	18,168.66	55.96
+ GST 9.00/9.00% (S\$)	2,922.18	1,287.00	1,635.18	55.96
Nett Amount (S\$)	35,390.84	15,587.00	19,803.84	55.96
+ Car Rental (12.0 x S\$115.95/day) (S\$)		1,391.40		
+ Loss of Earnings (12.0 x S\$40.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		27.25		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		17,565.65		
Global Sum Settlement (S\$)		17,500.00		

INSPECTION

Date of Assignment: 11/07/2024
 Date Inspected: 11/07/2024 Inspected At: BIFROST AUTO PTE LTD - LOYANG (HQ)
 59 Loyang Drive Level 4 Room 7
 Singapore 508969
 Estimated Period of Repair: 10.0 days

Adjuster: BRYAN TANI**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2025)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC7899S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK LID COVER	Buckled	1,303.29 FL	*1,303.29 FL
2	1		*REAR TRUNK LID LOCK	Damaged	530.79 FL	*530.79 FL
3	1		*REAR TRUNK LID LOCK COVER	Not Necessary	129.80 FL	*- FL
4	1		*REAR TRUNK LID LOCK SWITCH	Not Necessary	468.90 FL	*- FL
5	1		*REAR TRUNK LID COVER TRIM BOARD	Broken	254.40 FL	*254.40 FL
6	1		*BOOT LID TRIMBOARD CENTRE	Cut	159.60 FL	*159.60 FL
7	2		*BOOT LID TRIMBOARD SIDE (LH/RH)	Not Necessary	185.00 FL	*- FL
8	1		*BOOT LID TRIMBOARD REAR	Not Necessary	124.80 FL	*- FL
9	1		*BOOT HANDLE	Not Necessary	31.80 FL	*- FL
10	1		*REAR TRUNK LID RUBBER	Deformed	365.20 FL	*365.20 FL
11	1		*REAR TRUNK LID GLASS (BLACK COLOR)	Shattered	969.70 FL	*969.70 FL
12	1		*GARNISH SUB-ASSY BACK DOOR OUTSIDE	Broken	1,054.71 FL	*913.60 FL
13	1		*REAR TRUNK LID LOGO (PRIUS)	Necessary	62.14 FL	*62.14 FL
14	1		*REAR TRUNK LID LOGO (HYBRID)	Necessary	62.14 FL	*62.14 FL
15	1		*REAR TRUNK LID LOGO (TOYOTA STAR)	Necessary	81.43 FL	*81.43 FL
16	1		*THIRD BRAKE LIGHT	Broken / Dislodged	394.70 FL	*394.70 FL
17	1		*REAR TRUNK LID STRIKER	Repair	98.70 FL	*- FL
18	2		*REAR TRUNK LID HINGE (LH/RH)	Repair	379.00 FL	*- FL
19	2		*REAR TRUNK LID ABSORBER (LH/RH)	Not Necessary	575.00 FL	*- FL
20	2		*REAR TRUNK LID ABSORBER BRACKET (LH/RH)	Not Necessary	255.80 FL	*- FL
21	2		*REAR TRUNK LID STOPPER (LH/RH)	Not Necessary	169.60 FL	*- FL
22	1		*SPOILERSUB-ASSY ,REAR	Broken / Dislodged	1,787.79 FL	*1,278.15 FL
23	1		*REAR WINDSCREEN GLASS W/MOULDING	Shattered	1,884.32 FL	*1,884.32 FL
24	1		*ROOF TOP CENTER COVER BLACK	Broken	956.30 FL	*956.30 FL
25	1		*ROOF TOP GARNISH SUB,LH	Dislodged	136.80 FL	*136.80 FL
26	1		*ROOF TOP GARNISH SUB,RH	Dislodged	136.80 FL	*136.80 FL
27	2		*REAR NO PLATE LAMP LH/RH	Not Necessary	327.00 FL	*- FL
28	1		*MOTOR ASSY ,REAR WIPER	Not Necessary	734.60 FL	*- FL
29	1		*ARM ASSY ,REAR WIPER	Not Necessary	84.70 FL	*- FL
30	1		*BLADE ASSY ,REAR WIPER	Not Necessary	55.00 FL	*- FL
31	1		*REAR BUMPER	Broken	503.04 FL	*503.04 FL
32	1		*REAR BUMPER REINFORCEMENT	Broken	378.32 FL	*378.32 FL
33	1		*REAR BUMPER LOWER COVER	Broken	654.96 FL	*654.96 FL
34	2		*REAR BUMPER SIDE RETAINER	Serviceable	225.40 FL	*- FL
35	1		*REAR BUMPER TOWING COVER	Broken	82.70 FL	*82.70 FL
36	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
37	2		*REAR BUMPER SIDE CLIP	Not Necessary	50.00 FL	*- FL
38	2		*REAR BUMPER UPPER STOPPER (LH/RH)	Not Necessary	152.80 FL	*- FL
39	2		*SEAL ,REAR BUMPER SIDE,LH/RH	Not Necessary	296.80 FL	*- FL
40	2		*REAR BUMPER UNDER SIDE COVER (LH/RH)	Not Necessary	464.00 FL	*- FL
41	2		*ARM SUB-ASSY ,REAR BUMPER (LH/RH)	Not Necessary	279.20 FL	*- FL
42	1		*REAR BUMPER REVERSE SENSOR	Damaged	235.70 FL	*235.70 FL
43	1		*REAR BUMPER UNDER COVER (CENTER)	Deformed / Cracked	773.64 FL	*773.64 FL
44	1		*TAIL LAMP ASSY (UPPER)	O/S Broken / N/S Not Necessary	1,115.80 FL	*557.90 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*TAIL LAMP ASSY (LOWER)	O/S Broken / N/S Not Necessary	1,140.00 FL	*570.00 FL
46	1		*TAIL LAMP QAUARTER PANEL	O/S Dented / N/S Not Necessary	432.00 FL	*216.00 FL
47	2		*TAIL LAMP SIDE COVER	Not Necessary	512.00 FL	*- FL
48	1		*REAR TAILLAMP GUIDE WHITE	Not Necessary	95.30 FL	*- FL
49	1		*REAR END PANEL	Dented	738.96 FL	*738.96 FL
50	1		*REAR END PANEL GARNISH	Deformed	294.80 FL	*294.80 FL
51	1		*REAR SPARE TYRE PANEL	Repair	960.80 FL	*- FL
52	1		*REAR END PANEL GARNISH COVER	Not Necessary	138.90 FL	*- FL
53	1		*REAR SPARE TYRE CUSHION (FLR BOARD CENTRE)	Not Necessary	668.90 FL	*- FL
54	1		*REAR FIBER TOOL BOX TRIM (LH/RH)	O/S Broken / N/S Not Necessary	1,196.00 FL	*598.00 FL
55	1		*REAR FIBER TOOL BOX CENTER	Not Necessary	186.20 FL	*- FL
56	1		*SPARE TYRE LOCK NUT	Not Necessary	88.40 FL	*- FL
57	1		*SPARE TYRE LOCK NUT BRACKET	Not Necessary	113.50 FL	*- FL
58	2		*SPARE TYRE SIDE PANEL (LH/RH)	Not Necessary	574.60 FL	*- FL
59	1		*REAR EXHAUST PIPE RH	Not Necessary	1,163.40 FL	*- FL
60	1		*REAR EXHAUST PIPE HANGER	Not Necessary	40.70 FL	*- FL
61	1		*REAR EXHAUST PIPE INSULATOR	Not Necessary	314.60 FL	*- FL
62	1		*REAR FENDER RH	Buckled	992.04 FL	*992.04 FL
63	1		*FRONT FENDER UPPER GARNISH (RH)	Not Necessary	267.50 FL	*- FL
64	1		*REAR FENDER SHIELD (RH)	Not Necessary	174.20 FL	*- FL
65	1		*REAR FENDER TRIMBOARD (RH)	Not Necessary	725.00 FL	*- FL
66	1		*REAR FENDER TOP COVER (BLACK COLOR) (RH)	Not Necessary	301.10 FL	*- FL
67	1		*REAR FENDER AIR DUCT	Deformed	165.10 FL	*165.10 FL
68	1		*REVERSE CAMERA ASSY	Serviceable	380.00 FS	*- FS
69	1		*REAR TRUNK LOWER W/S MOULDING	Not Necessary	180.00 FS	*- FS
70	1		*REAR LOWER W/S SEALANT	Necessary	46.00 FS	*46.00 FS
71	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
72	1		*REAR NO PLATE WITH COVER	Bent	100.00 FS	*45.00 FS
73	1		*REAR TRUNK LID APPS STICKER	Necessary	40.00 FS	*40.00 FS
74	1		*REAR TRUNK LID COMFORT & TEL NO STICKER	Necessary	60.00 FS	*60.00 FS
75	1		*REAR BUMPER RUBBER MAT	Deformed	50.00 FS	*50.00 FS
76	1		*REAR FENDER DVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
77	1		*FRONT WHEEL RIM	Cut	1,570.55 FL	*1,555.60 FL
78	1		*FRONT WHEEL RIM CAP	Not fitted	189.60 FL	*- FL
79	1		*FRONT TYRE (LH) (50%)	Cut	216.00 FS	*108.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	33,256.32	18,323.12
- List Item Discount on L Items 20.00/25.00% (\$\$)	6,407.66	4,457.03
Total Parts (\$\$)	26,848.66	13,866.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,400.00	1,000.00
2	SPRAY PAINTING CHARGE	New	2,000.00	800.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE /REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	240.00	80.00
8	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (\$\$)			5,620.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >