

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMV 8265E

	REPLACEMENT OF PARTS			
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	TORN	\$1,365.70	\$1,185.00
1	FRONT BUMPER LOWER AIR GUARD	NOT NECESSARY	\$140.10	\$0.00
1	FRONT BUMPER FOG LAMP COVER	TORN	\$90.60	\$90.60
1	FRONT BUMPER LOWER GRILLE	TORN	\$185.30	\$185.30
2	FRONT BUMPER SIDE RETAINER @\$89.60	NOT NECESSARY	\$179.20	\$0.00
1	FRONT BUMPER BRACE PANEL	NOT NECESSARY	\$135.80	\$0.00
1	FRONT BUMPER SPONGE	NOT NECESSARY	\$80.40	\$0.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	\$312.50	\$0.00
1	FRONT BUMPER UNDER COVER GARNISH	NOT NECESSARY	\$189.60	\$0.00
1	HEADLAMP (HID)	NOT NECESSARY	\$3,348.90	\$0.00
1	FRONT UPPER GRILLE	NOT NECESSARY	\$803.60	\$0.00
1	FRONT GRILLE (COMPLETE SET)	NOT NECESSARY	\$1,156.30	\$0.00
1	FRONT SUPPORT PANEL	NOT NECESSARY	\$1,734.50	\$0.00
2	AIR CON CONDENSER SIDE GARNISH @\$98.60	NOT NECESSARY	\$197.20	\$0.00
1	AIR CON CONDENSER	NOT NECESSARY	\$1,153.30	\$0.00
1	HORN	NOT NECESSARY	\$115.30	\$0.00
	LESS 25.00% DISCOUNT		(\$2,797.08)	(\$365.23)
			\$8,391.22	\$1,095.67

	Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	\$50.00	\$0.00	
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	\$30.00	\$30.00	
1	SET FRONT BUMPER UNDER COVER GARNISH CLIP (SN)	NOT NECESSARY	\$30.00	\$0.00	
1	SET FRONT SUPPORT PANEL COVER GARNISH CLIP (SN)	NOT NECESSARY	\$30.00	\$0.00	
1	RADIATOR COOLANT (SN)	NOT NECESSARY	\$60.00	\$0.00	
		\$200.00	\$30.00		

Labour			
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
PANEL BEATING, REMOVING AND REPLACING PARTS		\$1,200.00	\$200.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Labour				
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$	
SPRAY PAINTING TO AFFECTED AREA		\$1,200.00	\$200.00	
TUFF COAT	NOT NECESSARY	\$250.00	\$0.00	
WIRING CHECK	NOT NECESSARY	\$80.00	\$0.00	
REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	NOT NECESSARY	\$120.00	\$0.00	
REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	NOT NECESSARY	\$100.00	\$0.00	
REFOCUS HEADLAMP BEAM	NOT NECESSARY	\$60.00	\$0.00	
TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	NOT NECESSARY	\$180.00	\$0.00	
		\$3,190.00	\$400.00	
GRAND TOTAL		\$11,781.22	\$1,525.67	
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$1,200.00	
Report Ref No: CS/INC24070191/Aqh3				

TOTAL FOR SPARE PARTS: \$ 8,591.22 \$ 1,125.67
TOTAL FOR LABOUR: \$ 3,190.00 \$ ,400.00
TOTAL REPAIR COST: \$11,781.22 \$ 1,525.67

## **LWP**

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.