



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO JSP 6663

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FORK	BENT/TWISTED	\$350.00	\$350.00
1	FORK T-UNDER BRACKET	BENT	\$280.00	\$280.00
1	STEERING CONE	NECESSARY	\$150.00	\$60.00
1	FRONT SPORT RIM	WARPED	\$280.00	\$280.00
1	FRONT TYRE SHAFT	BENT	\$120.00	\$50.00
1	FRONT DISC BRAKE	SERVICEABLE	\$180.00	\$0.00
1	FRONT CALIPER	NOT NECESSARY	\$250.00	\$0.00
1	FRONT SPEEDO GEAR	NOT NECESSARY	\$150.00	\$0.00
1	FRONT SPEEDO CABLE	NOT NECESSARY	\$120.00	\$0.00
1	RADIATOR	PUNCTURE	\$350.00	\$350.00
1	SPARE COOLANT TANK	NOT NECESSARY	\$180.00	\$0.00
1	INNER PANEL 1	CRACKED	\$200.00	\$160.00
1	FRONT PANEL COVER	CRACKED	\$180.00	\$140.00
1	SET FRONT SIGNAL LIGHT	CRACKED	\$380.00	\$168.00
1	HANDLE BAR	BENT	\$280.00	\$148.00
1	SET MIRROR	BROKEN	\$120.00	\$80.00
1	STARTER SWITCH	NOT NECESSARY	\$100.00	\$0.00
1	FRONT FAIRING TUNER COVER	CRACKED	\$80.00	\$50.00
1	BODY UNDER COVER R	DISTORTED	\$120.00	\$120.00
1	BODY UNDER COVER L	DISTORTED	\$120.00	\$120.00
1	BASKET	NOT NECESSARY	\$100.00	\$0.00
1	BRAKE LEVER	CUT	\$120.00	\$120.00
1	FRONT TYRE	SERVICEABLE	\$150.00	\$0.00
1	FRONT FOOTREST RUBBER	TORN	\$50.00	\$50.00
1	BRAKE PEDAL	TO REPAIR SEE LABOUR	\$150.00	\$0.00
1	EXHAUST PIPE	TO REPAIR SEE LABOUR	\$500.00	\$0.00
1	EXHAUST PROTECTOR (FRONT)	SERVICEABLE	\$180.00	\$0.00
1	EXHAUST PROTECTOR (REAR)	SERVICEABLE	\$150.00	\$0.00
1	FRONT HEAD LAMP	NOT NECESSARY	\$250.00	\$0.00
1	SET REAR SIGNAL LIGHT	CRACKED	\$180.00	\$75.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BOX	SERVICEABLE	\$350.00	\$0.00
1	REAR BOX BRACKET	TO REPAIR SEE LABOUR	\$250.00	\$0.00
1	REAR NUMBER PLATE	SERVICEABLE	\$30.00	\$0.00
1	COVERSET	CRACKED	\$480.00	\$480.00
1	FRONT FOOTREST BAR	BENT	\$200.00	\$118.00
	<b>LESS 10.00% DISCOUNT</b>		(\$713.00)	(\$319.90)
			<b>\$6,417.00</b>	<b>\$2,879.10</b>

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	BODY ALIGNMENT	NOT NECESSARY	\$700.00	\$0.00
	LABOUR. INCLUSIVE OF THE REPAIR OF BRAKE PEDAL, EXHAUST PIPE AND REAR BOX BRACKET		\$600.00	\$350.00
			<b>\$1,300.00</b>	<b>\$350.00</b>

<b>GRAND TOTAL</b>			<b>\$7,717.00</b>	<b>\$3,229.10</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>\$1,400.00</b>

Report Ref No: CS/AGI24070194/Unh3m4

## CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.