



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBN 5529L

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	LAMP TAIL ASSY	CRACKED	\$254.00	\$254.00
1	MUDGUARD REAR	DISTORTED	\$57.00	\$57.00
1	PLATE NUMBER REAR (6.5 INCH X 9 INCH)	BENT	\$31.00	\$31.00
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$34.20)
			\$342.00	\$307.80
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR		\$170.00	\$100.00
	TRANSPORT CHARGES	NOT NECESSARY	\$62.00	\$0.00
			\$232.00	\$100.00
GRAND TOTAL			\$574.00	\$407.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$320.00
Report Ref No: CS/GAI24070197/Uvh3				

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.