

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|--|---|--|----------------|---------------------|--|
| MS | GREAT AMERICAN | INSURANCE COMPANY | Ref: | CS/GAI24070197/Uvh3 | |
| | 3 TEMASEK AVENU | | Date: | 10/07/2024 | |
| | #16-01 CENTENNIA SINGAPORE 03919 | | Code: | GAI | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SMG 3854S | Veh. Inspected | FBN 5529L | |
| | Policy No. | - | Coverage | 0 | |
| | Claim No. | CLMOMVP000001563 | Excess | \$0.00 | |
| | Assign From | JEANNIE ANG | Assign Date | 10/07/2024 | |
| 2. Vehicle Details | | | | | |
| | Make & Model | YAMAHA NMAX155 ABS | C.C | 155 | |
| | Engine No. | G3H6E0011000 | Year of Reg. | 24/10/2018 | |
| | Chassis No. | MH3SG431000008517 | Colour | WHITE | |
| | Odometer | 124837 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | General | GOOD | |
| | Modification(s) | RIMS: SPORTS RIM | | | |
| 3. | 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance (mm) | |
| | R/H Front Tyre | 110/70-13 | MAXXIS | 6 | |
| | L/H Front Tyre | | | | |
| | R/H Rear Tyre | 130/70-13 | MAXXIS | 6 | |
| | L/H Rear Tyre | | | | |
| 4. | Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | | |
| DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | |
| | Accident Date | cident Date 01/07/2024 Inspection Date 11/07/2024 | | | |
| | Survey held at | BAN HOCK HIN CO.PTE LTD - BLK 8 DEFU SOUTH STREET 1, #04-28 JTC DEFU INDUSTRIAL CITY, SINGAPORE 533758 | | | |
| 5a. Remarks | | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| | | | | | |
| 5b. | | Estimate Day | s of Repair | | |

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days