



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 7973B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR DOOR (SN)	DENTED	2,200.00	1,400.00
1	REAR DOOR LOCK BAR (SN)	NOT NECESSARY	480.00	-
3	REAR DOOR LOCK BAR BRACKET @\$100.00 (SN)	NOT NECESSARY	300.00	-
1	REAR DOOR LOCK HANDLE (SN)	NOT NECESSARY	380.00	-
2	REAR DOOR HINGE @\$350.00 (SN)	BENT	700.00	500.00
1	REAR DOOR PILLAR (SN)	TO REPAIR SEE LABOUR	1,200.00	-
1	SIDE BODY PANEL LOWER (SN)	DENTED	3,000.00	1,600.00
			8,260.00	3,500.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING, REMOVE AND REFIT PARTS. INCLUSIVE OF THE REPAIR OF REAR DOOR PILLAR. SPRAY PAINTING TO AFFECTED AREA.		1,200.00	500.00
	WIRING CHECK.	NOT NECESSARY	1,000.00	-
	TO APPLY TUFF COAT.	NOT NECESSARY	50.00	-
		NOT NECESSARY	200.00	-
			2,450.00	500.00
<b>GRAND TOTAL</b>			<b>10,710.00</b>	<b>4,000.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,200.00</b>

Report Ref No. CS/SMO24070198/Anp3m4(N)

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.