

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070200/UMA3Q2**Date:** 11/10/2024**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900077316
Claimant Vehicle No : GBF1691T **Insured Vehicle No :** SMJ7091J
Date of Loss: 05/07/2024 Nature of Claim: TP Claim No: 5574671676SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF1691T**
Make & Model: MITSUBISHI CANTER, 3.0 D FEA01BR2SDEB (CBU) (M) Engine No: 4P10C22106
Reg. Date: 15/07/2016 (Man. Year: 2016) Chassis No: FEA01BA20236
Colour: White Odometer: 141814 km
Engine Capacity: 2998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15 (D)
Front Left Side: Austone 6 mm Rear Left Side: Austone 6/6 mm
Front Right Side: Austone 6 mm Rear Right Side: Austone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,342.30	2,699.08	2,643.22	49.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	920.00	700.00	220.00	23.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,262.30	3,399.08	2,863.22	45.72
Approved Total (Overridden) (S\$)		2,700.00		
Nett Amount (S\$)	6,262.30	2,700.00	3,562.30	56.88
+ Loss of Use (3.0 x S\$90.00/day) (S\$)		270.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		2,972.18		
Global Sum Settlement (S\$)		2,970.00		

INSPECTION

Date of Assignment: 12/07/2024
Date Inspected: 12/07/2024 Inspected At: Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ)
Singapore 417883, Kaki Bukit
Singapore 417883
Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Badly Dented	2,001.50 F	*1,804.38 FL
2	1		*FRONT RH DOOR OUTER GARNISH	Torn	370.00 F	*370.00 FL
3	1		*FRONT RH DOOR HANDLE	Not Necessary	136.00 F	*- FL
4	1		*FRONT RH BUMPER SIDE (N/S Not Necessary)	O/S Deformed / Torn	883.40 F	*369.81 FL
5	2		*SET FRONT RH BUMPER SIDE CLIPS	Not Necessary	90.00 FS	*- FS
6	1		*FRONT RH SIGNAL LAMP	O/S Cracked	627.20 F	*288.21 FL
7	1		*SET FRONT RH SIGNAL LAMP CLIPS	Not Necessary	40.00 FS	*- FS
8	1		*FRONT RH SIDE LAMP O/S	Cracked	581.00 F	*187.50 FL
9	1		*FRONT RH STEP PANEL LOWER (O/S)	Damaged	613.20 F	*578.87 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,342.30	3,598.77
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	899.69
Total Parts (\$)	5,342.30	2,699.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	20.00	20.00
2	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	500.00	380.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	400.00	300.00
Gross Labour Cost (\$\$)			920.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >