
NCVI INVOLVING A STATIONARY 5 TON (MID20800) ONBOARD RAMPPOWERED LIGHTER (RPL) TOWARDS TEKONG FERRY TERMINAL ON 10 JUL 2024 AT AROUND 0700H

OFFICIAL (CLOSED) \setminus SENSITIVE NORMAL

Incident Site




Figure A-1




Dual-Voc driver drove the 5 TON up the RPL and was ground guided by RPL crew to park down on the left lane behind the Big Civilian Lorry, as shown above. DV dismounted the 5 TON.

Figure A-2




RPL Crew briefed the Contractor to park his Civilian Lorry in the space between the 5 TON and the Garbage Truck to even out the weight on the left and right sides of the RPL, as per the RPL Company's SOP. Contractor complied and drove the Civilian Lorry forward up the RPL ramp and onto the middle lane of the RPL.

Figure A-3



Contractor starts to reverse and turns the Civilian Lorry in to parallel park into the space behind the stationary 5 TON.

Figure A-4



Contractor attempts to straighten the Civilian Lorry. The left side-view mirror of the Civilian Lorry collides with the 5 TON's right rear reflective disc, knocking it off.

Figure A-5



Figure B-1: Front View of MID20800



Figure B-2: Rear View of MID20800



Figure B-3: Left Side View of MID20800



Figure B-4: Right Side View of MID20800



Damage Assessment:

eflective disc knocked of

1. Right rear reflective disc of the 5 TON was entirely knocked off.

Figure B-5: Close-up View of MID20800 Damages



Close-up view of the damages sustained

Damage Assessment: The left side-view mirror of the civilian lorry sustained scratches at multiple points.

Figure B-6: Close-up View of Civilian Lorry GBA9765M Damages

INTEPRETED BY RANK DATE SIGN RECORDED BY RANK TIME DATE SIGN I, 3WO NG WEI CHIEN, IS WRITING THIS STATEMENT FOR THE INCIDENT RELATED TO MID 20800. WHILE WAITING FOR THE RPL TO MOVE OFF FROM MAINLAND TO TEKONG, VEHICLE 5-TON MID 20800 WAS PARKED AND WHEEL CHOKE APPLIED. AT 0700 HRS, CIVILIAN VEHICLE GBA 9765M WAS REVERSING INTO OPEN SPACE BEHIND THE 5-TON, WHILE MANDELY PRING		3WO NG W				ALIASI	S		
DIALECT LANGUAGE SPOKEN ADDRESS INTEPRETED BY RANK DATE SIGN RECORDED BY RANK TIME DATE SIGN I, 3WO NG WEI CHIEN, IS WRITING THIS STATEMENT FOR THE INCIDENT RELATED TO MID 20800. WHILE WAITING FOR THE RPL TO MOVE OFF FROM MAINLAND TO TEKONG, VEHICLE 5-TON MID 20800 WAS PARKED AND WHEEL CHOKE APPLIED. AT 0700 HRS, CIVILIAN VEHICLE 5-TON MID 20800 WAS REVERSING INTO OPEN SPACE BEHIND THE 5-TON, WHILE MANEUVERING THE CONTRACTOR KNOCKED ONTO THE RIGHT HAND REAR OF THE VEHICLE 5-TON MID 20800 AND THAT CAUSES THE RED LIGHT MARKER TO DROP AND DENT THE VEHICLE. THAT IS					T/00512/19	MALE	FEMALE		CAN
ADDRESS INTERRETED BY RANK DATE SIGN RECORDED BY RANK TIME DATE SIGN II. 3WO NG WEI CHIEN, IS WRITING THIS STATEMENT FOR THE INCIDENT RELATED TO MID 20800. WHILE WAITING FOR THE RPL TO MOVE OFF FROM MAINLAND TO TEKONG, VEHICLE 5-TON MID 20800 WAS PARKED AND WHEEL CHOKE APPLIED. AT 0700 HRS, CIVILIAN VEHICLE GBA 9765M WAS REVERSING INTO OPEN SPACE BEHIND THE 5-TON, WHILE MANEUVERING THE CONTRACTOR KNOCKED ONTO THE RIGHT HAND REAR OF THE VEHICLE 5-TON MID 20800 AND THAT CAUSES THE RED LIGHT MARKER TO DROP AND DENT THE VEHICLE. THAT IS		NLO.	LICENCE NO	190000000000000000000000000000000000000				SINGAPOI	EAN
ADDRESS INTERRETED BY RANK RECORDED BY RANK TIME DATE SIGN 1, 3WO NG WEI CHIEN, IS WRITING THIS STATEMENT FOR THE INCIDENT RELATED TO MID 20800. WHILE WAITING FOR THE RPL TO MOVE OFF FROM MAINLAND TO TEKONG, VEHICLE 5-TON MID 20800 WAS PARKED AND WHEEL CHOKE APPLIED. AT 0700 HRS, CIVILIAN VEHICLE GBA 9765M WAS REVERSING INTO OPEN SPACE BEHIND THE 5-TON, WHILE MANEUVERING THE CONTRACTOR KNOCKED ONTO THE RIGHT HAND REAR OF THE VEHICLE 5-TON MID 20800 AND THAT CAUSES THE RED LIGHT MARKER TO DROP AND DENT THE VEHICLE. THAT IS	DIALECT			ENGLIS	H	TEL NO)	- T	
RECORDED BY RANK TIME DATE SIGN 1, 3WO NG WEI CHIEN, IS WRITING THIS STATEMENT FOR THE INCIDENT RELATED TO MID 20800. WHILE WAITING FOR THE RPL TO MOVE OFF FROM MAINLAND TO TEKONG, VEHICLE 5-TON MID 20800 WAS PARKED AND WHEEL CHOKE APPLIED. AT 0700 HRS, CIVILIAN VEHICLE GBA 9765M WAS REVERSING INTO OPEN SPACE BEHIND THE 5-TON, WHILE MANEUVERING THE CONTRACTOR KNOCKED ONTO THE RIGHT HAND REAR OF THE VEHICLE 5-TON MID 20800 AND THAT CAUSES THE RED LIGHT MARKER TO DROP AND DENT THE VEHICLE. THAT IS	ADDRESS								
I, 3WO NG WEI CHIEN, IS WRITING THIS STATEMENT FOR THE INCIDENT RELATED TO MID 20800. WHILE WAITING FOR THE RPL TO MOVE OFF FROM MAINLAND TO TEKONG, VEHICLE 5-TON MID 20800 WAS PARKED AND WHEEL CHOKE APPLIED. AT 0700 HRS, CIVILIAN VEHICLE GBA 9765M WAS REVERSING INTO OPEN SPACE BEHIND THE 5-TON, WHILE MANEUVERING THE CONTRACTOR KNOCKED ONTO THE RIGHT HAND REAR OF THE VEHICLE 5-TON MID 20800 AND THAT CAUSES THE RED LIGHT MARKER TO DROP AND DENT THE VEHICLE. THAT IS	The state of the s				TIME			The state of the s	-
20800. WHILE WAITING FOR THE RPL TO MOVE OFF FROM MAINLAND TO TEKONG, VEHICLE 5-TON MID 20800 WAS PARKED AND WHEEL CHOKE APPLIED. AT 0700 HRS, CIVILIAN VEHICLE GBA 9765M WAS REVERSING INTO OPEN SPACE BEHIND THE 5-TON, WHILE MANEUVERING THE CONTRACTOR KNOCKED ONTO THE RIGHT HAND REAR OF THE VEHICLE 5-TON MID 20800 AND THAT CAUSES THE RED LIGHT MARKER TO DROP AND DENT THE VEHICLE. THAT IS		HIEN, IS WR				HE INCIDE	NT RELA	TED TO MI	D
					· ·				
	1								
ALCONOM.	an townsta.								
TAN CONTRACT.	AND THE STATE OF								
AND THAT CAN	SE CONTRA.								
	ALCOVERS A								
	31 147N1105								
	THE CAPPETING			#		4	△		
	AND THAT A					4	4		
	AND THE STATE OF					4	→		
						4	4		
	THE CAPACITAN			*		4	→		

Figure C-1: Statement of Driver

NOTE: Accident/ Incident Reporting must be reported to HR department within 72 hours for any occurrences. ACCIDENT/ INCIDENT INVESTIGATION Cleaner Reporting Date and Time after the Accident: 10 July 2024 7.20am and Time after the Accident: 11 July 2024 4.50pm and Time after the Accident: 12 July 2024 4.50pm and Time after the Accident: 11 April 2022 Project Address: P. Tekong Ferry Terminal Date and Time of Accident 11 April 2022 Project Address: P. Tekong Ferry Terminal Site Team Leader: Spencer Ong Exact location of accident incident: Inquired-Person/ Property Owner's Name: SAF In	6 TAGORE DRIVE #B1-02 TAGOR TEL: 6250 4328 CO. REG. NO: 199103080W	GST RE	254 4803 G. NO: M2-0100402-X		
Cleaner Reporting Date and Time after the Accident: Project: Army East Selarang Camp Project Address: P.Tekong Ferry Terminal Date and Time after the Accident: Date and Time of Accident 11 April 2022 Operation Manager: Garale Ong Site Team Leader: Spencer Ong Exact location of accident/ incident: Injury: No injury Investigation Report by: Garale Ong Date of Report: Date of Report: Date of Report: Date of Report: Photographs - Scene of the Incident Witness Statements Plant & Equipment MOM Supplemental Accident Reports (iReport) Dangerous Occurrence Fatality Dangerous Occurrence MOM Reportable Fratality Dangerous Occurrence MOM Reportable Incident Description Daty 2024 Serious Near Miss Accident MOM Reportable Incident Description Daly 2024	NOTE: Accident/ Incident Reporting must be repany occurrences.	orted t	o HR department w	ithin <u>72</u> hou	rs for
Time after the Accident: Project: Army East Selarang Camp Project Address: P. Tekong Ferry Terminal Date and Time of Accident Date and Time of Accident 11 April 2022 Deration Manager: Garale Ong Site Team Leader: Spencer Ong Exact location of accident incident: Injured-Person/ Property Owner's Name: SAF Injury: No injury: No injury: No injury: Date of Report: 10 July 2024 1. Summary of Appendices Photographs - Scene of the Incident Witness Statements Plant & Equipment MOM Supplemental Accident Reports (iReport) 2. Accident Type – not applicable Fatality 3 Day Reportable Serious Near Miss Accident Specified Major Injury Dangerous Occurrence MOM Reportable Incident Description 10 July 2024 At approximately 0720ins, a marshal directed Saravanan to proceed into the RPL and park his vehicle. The marshal instructed Saravanan to park between a Rubbish Truck and a 5 Tomer belong to SAF MID:20800. Saravanan assessed the situation using his left side mirror and rear mirrors and believed it was clear to reverse. While reversing, he heard a knock sound and immediately stopped to investigate. To assess the situation, requesting Saravanan's driving license, IC, and mobile number for records. Saravanan provided the necessary Appendix The Accident Type — Indicated The Stoner Camp Camp And Indicated Saravanan's driving license, IC, and mobile number for records. Saravanan provided the necessary	ACCIDENT/ INCIDEN	IT IN	/ESTIGATION		
Selarang Camp Project Address: P.Tekong Ferry Terminal Exact location of accident/incident: Injured Person/ Property Owner's Name: SAF Injury: No injury Investigation Report by: Garale Ong Date of Report: 10 July 2024 1. Summary of Appendices Photographs - Scene of the Incident Witness Statements Plant & Equipment MOM Supplemental Accident Reports (iReport) 2. Accident Type – not applicable Fatality Specified Major Injury Dangerous Occurrence MOM Reportable Incident Description 10 July 2024 Sockalingam Saravanan drove the 10-foot lorry (GBA9765M) into SAF Ferry Terminal to take the 0730hrs RPL to Pulatt Tekong Camp. At approximately 0720hrs, a marshal directed Saravanan to proceed into the RPL and park his vehicle. The marshal instructed Saravanan to park between a Rubbish Truck and a 5 Tonner belong to SAF MID20800. Saravanan assessed the situation using his left side mirror and rear mirrors and believed it was clear to reverse. While reversing, he heard a knock sound and immediately stopped to investigate. Upon inspection, he found that the rear reflector (colored ed) of the 5 Tonner was on the ground. The driver of the 5 Tonner came down to assess the situation, requesting Saravanan's driving license, IC, and mobile number for records. Saravanan provided the necessary	Cleaner Reporting Date and Time after the Accident: 10 July 2024 7.20am			10 July 2024 4	50pm
Project Address: P.Tekong Ferry Terminal Exact location of accident/ incident: Injured Person/ Property Owner's Name: SAF Injury: No injury Investigation Report by: Garale Ong Date of Report: 10 July 2024 1. Summary of Appendices Photographs - Scene of the Incident Witness Statements Plant & Equipment MOM Supplemental Accident Reports (iReport) 2. Accident Type - not applicable Fatality 3 Day Reportable Serious Near Miss Accident Specified Major Injury Dangerous Occurrence MOM Reportable Incident Description Sockalingam Saravanan drove the 10-foot lorry (GBA9765M) into SAF Ferry Terminal to take the 0730hrs RPL to Pulan Tekong Camp. At approximately 0720hrs, a marshal directed Saravanan to proceed into the RPL and park his vehicle. The marshal instructed Saravanan to park between a Rubbish Truck and a 5 Tonner belong to SAF MID20800. Saravanan an assessed the struation using his left side mirror and rear mirrors and betieved it was clear to reverse. While reversing, he heard a knock sound and immediately stopped to investigate. Upon inspection, he found that the rear reflector (colored red) of the 5 Tonner was on the ground. The driver of the 5 Tonner came down to assess the situation, requesting Saravanan's driving license, IC, and mobile number for records. Saravanan provided the necessary		Date a	nd Time of Accident	11 April 2022	
Exact location of accident/ incident: Injured-Person/ Property Owner's Name: SAF Injury: No injury Investigation Report by: Garale Ong Date of Report: 10 July 2024 1. Summary of Appendices		Opera	tion Manager:	Garale Ong	
accident/ incident: Injured Person/ Property Owner's Name: SAF Injury: No injury Investigation Report by: Garale Ong Date of Report: 10 July 2024 1. Summary of Appendices Appendices Appendix Reference (Please Insert) Photographs - Scene of the Incident Witness Statements Plant & Equipment MOM Supplemental Accident Reports (iReport) 2. Accident Type - not applicable Fatality 3 Day Reportable Serious Near Miss Accident Specified Major Injury Dangerous Occurrence MOM Reportable Incident Description 10 July 2024 Sockalingam Saravanan drove the 10-foot lorry (GBA9765M) into SAF Ferry Terminal to take the 0730hrs RPL to Pulau Tekong Camp. At approximately 0720hrs, a marshal directed Saravanan to proceed into the RPL and park his vehicle. The marshal instructed Saravanan to park between a Rubbish Truck and a 5 Tonner belong to SAF MID20800. Saravanan assessed the situation using his left side mirror and believed it was clear to reverse. While reversing, he heard a knock sound and immediately stopped to investigate. Upon inspection, he found that the rear reflector (colored red) of the 5 Tonner was on the ground. The driver of the 5 Tonner came down details. They also note playtors of the 5 Tonner Lives intention, requesting Saravanan provided the necessary	Project Address: P. Tekong Ferry Terminal	Site Te	eam Leader:	Spencer Ong	
Injury: No injury Investigation Report by: Garale Ong Date of Report: 10 July 2024 1. Summary of Appendices Appendix Reference (Please Insert) Photographs - Scene of the Incident Witness Statements Plant & Equipment MOM Supplemental Accident Reports (iReport) 2. Accident Type – not applicable Fatality 3 Day Reportable Serious Near Miss Accident Specified Major Injury Dangerous Occurrence MOM Reportable Incident Description 10 July 2024 Sockalingam Saravanan drove the 10-foot lorry (GBA9765M) into SAF Ferry Terminal to take the 0730hrs RPL to Pulau Tekong Camp. At approximately 0720hrs, a marshal directed Saravanan to park between a Rubbish Truck and a 5 Tonner belong to SAF MID20800. Saravanan assessed the situation using his left side mirror and betieved it was clear to reverse. While reversing, he heard a knock sound and immediately stopped to investigate. Upon inspection, he found that the rear reflector (colored red) of the 5 Tonner was on the ground. The driver of the 5 Tonner came down to assess the situation, requesting Saravanan's triving license, IC, and mobile number for records. Saravanan provided the necessary					
Injury: No injury Investigation Report by: Garale Ong Date of Report: 10 July 2024 1. Summary of Appendices Appendix Reference (Please Insert) Photographs - Scene of the Incident Witness Statements Plant & Equipment MOM Supplemental Accident Reports (iReport) 2. Accident Type – not applicable Fatality 3 Day Reportable Serious Near Miss Accident Specified Major Injury Dangerous Occurrence MOM Reportable Incident Description 10 July 2024 Sockalingam Saravanan drove the 10-foot lorry (GBA9765M) into SAF Ferry Terminal to take the 0730hrs RPL to Pulau Tekong Campate proximately 0720hrs, a marshal directed Saravanan to proceed into the RPL and park his vehicle. The marshal instructed Saravanan to park between a Rubbish Truck and a 5 Tonner belong to SAF MID20800. Saravanan assessed the situation using his left side mirror and rear mirrors and believed it was clear to reverse. While reversing, he heard a knock sound and immediately stopped to investigate. Upon inspection, he found that the rear reflector (colored red) of the 5 Tonner was on the ground. The driver of the 5 Tonner came down details. They also took physics of the 5 Tonner Library Campanan and provided the necessary details. They also took physics of the 5 Tonner Library Campanan and provided the necessary				I I I I I I I	A PERMIT
1. Summary of Appendices Photographs - Scene of the Incident Witness Statements Plant & Equipment MOM Supplemental Accident Reports (iReport) 2. Accident Type – not applicable Fatality 3 Day Reportable Serious Near Miss Accident Specified Major Injury Dangerous Occurrence MOM Reportable Incident Description 10 July 2024 Sockalingam Saravanan drove the 10-foot lorry (GBA9765M) into SAF Ferry Terminal to take the 0730hrs RPL to Pulau Tekong Campata proximately 0720hrs, a marshal directed Saravanan to park between a Rubbish Truck and a 5 Tonner belong to SAF MID20800. Saravanan assessed the situation using his left side mirror and believed it was clear to reverse. While reversing, he heard a knock sound and immediately stopped to investigate. Upon inspection, he found that the rear reflector (colored red) of the 5 Tonner was on the ground. The driver of the 5 Tonner came down to assess the situation, requesting Saravanan's driving license, IC, and mobile number for records. Saravanan provided the necessary					
Photographs - Scene of the Incident Witness Statements Plant & Equipment MOM Supplemental Accident Reports (iReport) 2. Accident Type – not applicable Fatality 3 Day Reportable Serious Near Miss Accident Specified Major Injury Dangerous Occurrence MOM Reportable Incident Description 10 July 2024 Sockalingam Saravanan drove the 10-foot lorry (GBA9765M) into SAF Ferry Terminal to take the 0730hrs RPL to Pulau Tekong Campata proving the	Investigation Report by: Garale Ong	Date o	f Report: 10 July 2024		
Witness Statements Plant & Equipment MOM Supplemental Accident Reports (iReport) 2. Accident Type – not applicable Fatality 3 Day Reportable Serious Near Miss Accident Specified Major Injury Dangerous Occurrence MOM Reportable Incident Description 10 July 2024 Sockalingam Saravanan drove the 10-foot lorry (GBA9765M) into SAF Ferry Terminal to take the 0730hrs RPL to Pulau Tekong Camp. At approximately 0720hrs, a marshal directed Saravanan to proceed into the RPL and park his vehicle. The marshal instructed Saravanan to park between a Rubbish Truck and a 5 Tonner belong to SAF MID20800. Saravanan assessed the situation using his left side mirror and believed it was clear to reverse. While reversing, he heard a knock sound and immediately stopped to investigate. Upon inspection, he found that the rear reflector (colored red) of the 5 Tonner was on the ground. The driver of the 5 Tonner came down to assess the situation, requesting Saravanan's driving license, IC, and mobile number for records. Saravanan provided the necessary	Summary of Appendices	1	Appendix Refer	ence (Please Ir	sert)
Plant & Equipment MOM Supplemental Accident Reports (iReport) 2. Accident Type – not applicable Fatality 3 Day Reportable Serious Near Miss Accident Specified Major Injury Dangerous Occurrence MOM Reportable Incident Description 10 July 2024 Sockalingam Saravanan drove the 10-foot lorry (GBA9765M) into SAF Ferry Terminal to take the 0730hrs RPL to Pulau Tekong Camp. At approximately 0720hrs, a marshal directed Saravanan to proceed into the RPL and park his vehicle. The marshal instructed Saravanan to park between a Rubbish Truck and a 5 Tonner belong to SAF MID20800. Saravanan assessed the situation using his left side mirror and believed it was clear to reverse. While reversing, he heard a knock sound and immediately stopped to investigate. Upon inspection, he found that the rear reflector (colored red) of the 5 Tonner was on the ground. The driver of the 5 Tonner came down to assess the situation, requesting Saravanan's driving license, IC, and mobile number for records. Saravanan provided the necessary	Photographs - Scene of the Incident				
MOM Supplemental Accident Reports (iReport) 2. Accident Type – not applicable Fatality 3 Day Reportable Serious Near Miss Accident MOM Reportable Incident Description 10 July 2024 Sockalingam Saravanan drove the 10-foot lorry (GBA9765M) into SAF Ferry Terminal to take the 0730hrs RPL to Pulau Tekong Camparate approximately 0720hrs, a marshal directed Saravanan to proceed into the RPL and park his vehicle. The marshal instructed Saravanan part rear mirrors and believed it was clear to reverse. While reversing, he heard a knock sound and immediately stopped to investigate. Upon inspection, he found that the rear reflector (colored red) of the 5 Tonner was on the ground. The driver of the 5 Tonner came down assess the situation, requesting Saravanan's driving license, IC, and mobile number for records. Saravanan provided the necessary	Witness Statements		THE RESERVE TO SERVE	TOTAL TELL	
2. Accident Type – not applicable Fatality 3 Day Reportable Serious Near Miss Accident Specified Major Injury Dangerous Occurrence MOM Reportable incident Description 10 July 2024 Sockalingam Saravanan drove the 10-foot lorry (GBA9765M) into SAF Ferry Terminal to take the 0730hrs RPL to Pulau Tekong Camp. At approximately 0720hrs, a marshal directed Saravanan to proceed into the RPL and park his vehicle. The marshal instructed Saravanan to park between a Rubbish Truck and a 5 Tonner belong to SAF MID20800. Saravanan assessed the situation using his left side mirror and believed it was clear to reverse. While reversing, he heard a knock sound and immediately stopped to investigate. Upon inspection, he found that the rear reflector (colored red) of the 5 Tonner was on the ground. The driver of the 5 Tonner came down to assess the situation, requesting Saravanan's driving license, IC, and mobile number for records. Saravanan provided the necessary	Plant & Equipment		THE STATE OF THE S		
Fatality Specified Major Injury Dangerous Occurrence MOM Reportable Incident Description July 2024 Sockalingam Saravanan drove the 10-foot lorry (GBA9765M) into SAF Ferry Terminal to take the 0730hrs RPL to Pulau Tekong Camp. At approximately 0720hrs, a marshal directed Saravanan to proceed into the RPL and park his vehicle. The marshal instructed Saravanan to park between a Rubbish Truck and a 5 Tonner belong to SAF MID20800. Saravanan assessed the situation using his left side mirror and believed it was clear to reverse. While reversing, he heard a knock sound and immediately stopped to investigate. Upon inspection, he found that the rear reflector (colored red) of the 5 Tonner was on the ground. The driver of the 5 Tonner came down to assess the situation, requesting Saravanan's driving license, IC, and mobile number for records. Saravanan provided the necessary	MOM Supplemental Accident Reports (iReport)			N FEET	1390
Specified Major Injury Dangerous Occurrence MOM Reportable Incident Description July 2024 Sockalingam Saravanan drove the 10-foot lorry (GBA9765M) into SAF Ferry Terminal to take the 0730hrs RPL to Pulau Tekong Camp. At approximately 0720hrs, a marshal directed Saravanan to proceed into the RPL and park his vehicle. The marshal instructed Saravanan to park between a Rubbish Truck and a 5 Tonner belong to SAF MID20800. Saravanan assessed the situation using his left side mirror and rear mirrors and believed it was clear to reverse. While reversing, he heard a knock sound and immediately stopped to investigate. Upon inspection, he found that the rear reflector (colored red) of the 5 Tonner was on the ground. The driver of the 5 Tonner came down assess the situation, requesting Saravanan's driving license, IC, and mobile number for records. Saravanan provided the necessary details. They also took photos of the 5 Tonner. Upon inspection, he found that the rear reflector (colored red) of the 5 Tonner was on the ground. The driver of the 5 Tonner came down assess the situation, requesting Saravanan's driving license, IC, and mobile number for records. Saravanan provided the necessary	2. Accident Type – not applicable				
Sockalingam Saravanan drove the 10-foot lorry (GBA9765M) into SAF Ferry Terminal to take the 0730hrs RPL to Pulau Tekong Camp. At approximately 0720hrs, a marshal directed Saravanan to proceed into the RPL and park his vehicle. The marshal instructed Saravanan to park between a Rubbish Truck and a 5 Tonner belong to SAF MID20800. Saravanan assessed the situation using his left side mirror and believed it was clear to reverse. While reversing, he heard a knock sound and immediately stopped to investigate. Upon inspection, he found that the rear reflector (colored red) of the 5 Tonner was on the ground. The driver of the 5 Tonner came down to assess the situation, requesting Saravanan's driving license, IC, and mobile number for records. Saravanan provided the necessary	Fatality 3 Day Reportable	3 Day Reportable Serious Near Miss Accident			
Sockalingam Saravanan drove the 10-foot lorry (GBA9765M) into SAF Ferry Terminal to take the 0730hrs RPL to Pulau Tekong Camp. At approximately 0720hrs, a marshal directed Saravanan to proceed into the RPL and park his vehicle. The marshal instructed Saravanan to park between a Rubbish Truck and a 5 Tonner belong to SAF MID20800. Saravanan assessed the situation using his left side mirror and rear mirrors and believed it was clear to reverse. While reversing, he heard a knock sound and immediately stopped to investigate. Upon inspection, he found that the rear reflector (colored red) of the 5 Tonner was on the ground. The driver of the 5 Tonner came down assess the situation, requesting Saravanan's driving license, IC, and mobile number for records. Saravanan provided the necessary	Specified Major Injury Dangerous Occurrence		MOM Reportable		
Sockalingam Saravanan drove the 10-foot lorry (GBA9765M) into SAF Ferry Terminal to take the 0730hrs RPL to Pulau Tekong Camp. At approximately 0720hrs, a marshal directed Saravanan to proceed into the RPL and park his vehicle. The marshal instructed Saravanan to park between a Rubbish Truck and a 5 Tonner belong to SAF MID20800. Saravanan assessed the situation using his left side mirror and rear mirrors and believed it was clear to reverse. While reversing, he heard a knock sound and immediately stopped to investigate. Upon inspection, he found that the rear reflector (colored red) of the 5 Tonner was on the ground. The driver of the 5 Tonner came down to assess the situation, requesting Saravanan's driving license, IC, and mobile number for records. Saravanan provided the necessary	Incident Description				
	Sockalingam Saravanan drove the 10-foot lorry (GBA9765M) into SAI At approximately 0720hrs, a marshal directed Saravanan to proceed into park between a Rubbish Truck and a 5 Tonner belong to SAF MID20 and rear mirrors and believed it was clear to reverse. While reversing, he Upon inspection, he found that the rear reflector (colored red) of the 5 To assess the situation, requesting Saravanan's driving license, IC, and notes affecting the strength of the Saravanan's driving license. IC, and notes affecting the saravanan's driving license.	to the RPI 0800. San te heard a Tonner wan nobile nur	and park his vehicle. The revanan assessed the situation knock sound and immediates on the ground. The driver the for records. Saravanan	marshal instructed in using his left si ely stopped to inv of the 5 Tonner provided the nec	d Saravanan de mirror restigate. came down ressary

Figure C-2: Statement of Civilian Lorry GBA9765M Driver

RANK & NAME	AWANG YOG	1 SETIAN	MAU		
NRIC	791L	AGE	31	GENDER	M
NATIONALITY	INDONESIAN	TYPE OF SERVICE	officer	DRIVING PERMIT NO.	-
VOCATION	-	UNIT	TIAN SAN	CONTACT	
DATE OF ENLISTMENT	-	ORD	-		
ADDRESS					
WITNESSED /RECORDED BY	3000 Norous San	DATE	11 July 24	SIGN	tony
to guide the The reason fo Of the weigh On the 5-too Provided and the long dru	ncident happed long to the or r parking the nt on the left of n and the gark ugh space for a ver, he did not	designated lorry there and right page truck the lorry to pollow my	parking sport re was to end on the RPL.T was 8 meta to park. How hand actual	t behind the state of the space beers apart.	he 6-ton. ability between which s guided
to guide the The reason fo Of the weigh On the 5-tor Provided and the long dru Instanct. j the vehicle of From his righ and saw his mirror that	clorry to the or parking the on the lept of and the gark ugh space for wer, he did not tried to alert house fast. As it hand rear to see yen really the stone point.	designated lorry there and right page truck the lorry to pollow my nin while h one lorry wi by Telling h near to the	parking sport re was to ena conthe RPL. T was 8 meta p park. How hand signal newar reversi indow was are indow was are indo top the totop. As a presenting dis	t behind the state of the space beers apoure. cover when can fallowing, but he ready open, a Vehicle of the state of the s	he 6-ton. ability etween which s guided into his own was driving i alert him s I glance ept handsit
to guide the The reason fo Of the weigh On the 5-tor Provided onor the lorry driv Instinct. f the vehicle of Thom his righ and saw his mirror that thave time a	clorry to the or parking the on the lept of and the gark ugh space for wer, he did not tried to alore he quiet fast. As it had rear to so verille very rather 5 ton Right of stop Him. At the	designated lorry the lorry to the lorry wing telling he lorry wing telling he hand rear to the hand rear to	parking sport re was to ena conthe RPL. T was 8 meta to park. How hand signal hewar reversit who was an indow was an indow was an indow has a reflective dis the incident,	t behind the state of the space beers apoure. cover when can fallowing, but he ready open, a Vehicle of the state of the s	he 6-ton. ability etween which s guided into his own was driving i alert him s I glance ept handsit
to guide the The reason fo Of the weigh On the 5-tor Provided and the lorry drive Instinct. f the vehicle of Thom his right and saw his mirror that thave time a in the vehicle DATE	clorry to the or parking the on the lept of and the gark ugh space for wer, he did not tried to alert house fast. As it hand rear to see yen really the stone point.	designated lorry the lorry to the lorry wing thing have lorry wing telling he hand rear the them hand rear the time of	parking sport re was to end on the RPL. T was 8 meta to park. How hand signal hewar reversifiedow was an him to stop the ston. As a reflective dis the incident,	t behind the state of the space beers apoure. cover when can fallowing, but he ready open, a Vehicle of the state of the s	he 6-ton. ability etween which s guided into his own was driving i alert him s I glance ept handsit

Figure C-3: Statement of RPL Crew Marshal





Police Station Of Origin:

No. of Pedestrians Injured: NIL

1 of 3

Traffic Police 10 Ubi Avenu Tel No: 65470	e 3 SINGA	APORE	408865						Repo	rt No. T/20240711/707	
REPORT OF A	TRAFFIC	ACCIDE	NT								
Date/Time R 11/07/2024 1		e:		Vide R	eport No.:				S	Station Diary No.:	
Informant's F	Particulars										
Name of Info NG WEI CHI				Addres	ss:						
ID Type / ID No.: NRIC NO / 835H			Contact No.:								
Nationality: SINGAPORE	CITIZEN			Email:							
Sex: Male			Type of Informant: Driver								
Race: Chinese				Language: English							
Occupation: Singapore armed forces personnel			Driving Class:	Licence Info	rmati		ate of	Expiry	:		
General Inform	nation of th	ne Accid	lent			- 0	2 10211 2			Water - 100	
Type of Acci		n-Injury overnme	ent Vehicle	7.5	Drink Drive No		ate/Time of 0/07/2024 0		ent:	Type of Location: RPL	
Location:	-										
NICOLL DRI	VE										
Weather: Clear				Road S	Surface:						
Traffic Flow: One Way									100000000000000000000000000000000000000	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle			a					nyone conveyed by mbulance: lo			
Details of Ve	hicle Invol	ved									
Vehicle No.	Туре		Make	I	Model	Col	or	Conc	dition	No of Passenger	
MID20800	Military (5-Ton)	Vehicle			-ton GS	Gre		Sligh		1	
Details of Pe	Electric de la constitución de l	2010		7							

Figure D-1

Use of Pedestrian Crossing: NA





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 2 of 3 Report No. T/20240711/7070

CONTINUATION OF REPORT

Driver						
Name	NG WEI CHIEN	NG WEI CHIEN).	835H
Related Vehicle	NIL			Conta	act No.	
Hospital/Clinic	NIL			Class Drivin Licen Expir	ıg	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	NIL			NIL	
No. of Days grante	ed Medical Leave (MC)	NIL	Degree of	Injury	NIL	

Brief Details.

Description of Incident:

While waiting for the RPL to move off from Mainland to Tekong, Vehicle (5-ton, MID20800) was parked and wheel choke applied. At 0700, Civilian vehicle (GBA9765M) was reversing into the open space behind the 5-ton, while maneuvering he knocked into the right rear side of the vehicle (5-ton) and that causes the red light marker to drop and dent the vehicle. No personnel was injured during the process.

Figure D-2





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 3 of 3 Report No. T/20240711/7070

CONTINUATION OF REPORT

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 11/07/2024 15:12
Officer In Charge Of Case: TP / AEIT / PHNG KAR SOON Contact No.: 65476439	Classification Of Case:
NP168	

Figure D-3