

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24070204/KPA3Q2

Date: 28/05/2025

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070151280-03
Claimant Vehicle No :	SML3614S	Insured Vehicle No :	SML355J
Date of Loss:	14/06/2024	Nature of Claim:	TP
		Claim No:	9604288426SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML3614S	Engine No:	L15B4530288
Make & Model:	HONDA HR-V, 1.5 DX CVT (A)	Chassis No:	JHMRU1810GX200289
Reg. Date:	07/10/2016 (Man. Year: 2016)	Odometer:	391030 km
Colour:	Metallic Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Ceat 8 mm	Rear Left Side:	Ceat 8 mm
Front Right Side:	Ceat 8 mm	Rear Right Side:	Ceat 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,545.12	1,534.88	4,010.24	72.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	470.00	1,130.00	70.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,145.12	2,004.88	5,140.24	71.94
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	7,145.12	1,600.00	5,545.12	77.61
+ GST 9.00/9.00% (S\$)	643.06	144.00	499.06	77.61
Nett Amount (S\$)	7,788.18	1,744.00	6,044.18	77.61
+ Car Rental (2.0 x S\$80.00/day) (S\$)		160.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		1,931.25		
Global Sum Settlement (S\$)		1,500.00		

INSPECTION

Date of Assignment:	11/07/2024	
Date Inspected:	11/07/2024	Inspected At: Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT HEADLAMP	Serviceable	3,569.00 FL	*- FL
2	2		*FRONT HEADLAMP TOP BRACKET	Serviceable	70.00 FL	*- FL
3	1		*FRONT HEADLAMP LOWER BRACKET	N/S Cracked	90.00 FL	*45.00 FL
4	1		*FRONT CENTRE GRILLE BASE	Cracked	495.00 FL	*495.00 FL
5	1		*FRONT CENTRE GRILLE BRACKET	Repair	75.00 FL	*- FL
6	1		*FRONT CENTRE GRILLE OUTER GARNISH	Serviceable	380.00 FL	*- FL
7	1		*FRONT CENTRE GRILLE HONDA LOGO	Necessary	37.40 FL	*37.40 FL
8	1		*FRONT BUMPER	Mtg Cracked	951.70 FL	*566.00 FL
9	10		*FRONT BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
10	2		*FRONT BUMPER SIDE RETAINER	Distorted	51.20 FL	*51.20 FL
11	1		*FRONT BUMPER LOWER LID	Dented	450.30 FL	*352.60 FL
12	1		*FRONT BUMPER LOWER GRILLE	Serviceable	280.50 FL	*- FL
13	1		*FRONT BUMPER REINFORCEMENT	Bent	368.80 FL	*321.40 FL
14	1		*SET FRONT BUMPER PLATE & CASING	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,918.90	1,918.60
- List Item Discount on L Items 20.00/20.00% (\$)	1,373.78	383.72
Total Parts (\$)	5,545.12	1,534.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING	New	800.00	220.00
2	LABOUR CHARGES	New	800.00	250.00
Gross Labour Cost (\$\$)			1,600.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >