

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24070205/UPA3Q2

Date: 19/09/2024

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D24MFL0003820
Claimant Vehicle No :	SNN4304H	Insured Vehicle No :	GBM1380D
Date of Loss:	11/07/2024	Nature of Claim:	TP
		Claim No:	MFL2024D0009332

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNN4304H		
Make & Model:	TOYOTA VOXY HYBRID, 1.8 (A)	Engine No:	2ZR2V53906
Reg. Date:	07/12/2023 (Man. Year: 2023)	Chassis No:	ZWR900101664
Colour:	Grey	Odometer:	54047 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Toyo 6 mm	Rear Left Side:	Blackhawk 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Blackhawk 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,033.80	9,569.45	19,464.35	67.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,190.00	1,860.00	1,330.00	41.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,223.80	11,429.45	20,794.35	64.53
Approved Total (Overridden) (S\$)		9,100.00		
Nett Amount (S\$)	32,223.80	9,100.00	23,123.80	71.76
+ Loss of Use (6.0 x S\$80.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		9,582.18		
Global Sum Settlement (S\$)		9,500.00		

INSPECTION

Date of Assignment:	11/07/2024	
Date Inspected:	11/07/2024 Inspected At:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Aug 2024)
Parts:	M1-MPV	TOYOTA VOXY HYBRID 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNN4304H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER O/S	Repair	1,145.10 F	*- FL
2	1		*FRONT FENDER INNER SHIELD O/S	Not Necessary	299.20 F	*- FL
3	1		*SET FRONT FENDER INNER SHIELD CLIPS O/S	Not Necessary	50.00 F	*- FL
4	1		*FRONT DOOR O/S	Dented / Bent	3,645.10 F	*2,637.10 FL
5	1		*FRONT DOOR OUTER PROTECTOR O/S	Deformed / Torn	855.10 F	*455.20 FL
6	1		*FRONT DOOR GLASS OUTER MOULDING O/S	Not Necessary	182.40 F	*- FL
7	1		*FRONT DOOR GLASS REGULATOR O/S	Bent	847.90 F	*381.20 FL
8	1		*FRONT DOOR GLASS REGULATOR MOTOR O/S	Serviceable	1,150.10 F	*- FL
9	2		*FRONT DOOR HINGES	Serviceable	210.00 F	*- FL
10	1		*FRONT DOOR CHECKER O/S	Not Necessary	151.00 F	*- FL
11	1		*FRONT DOOR INNER LOCK O/S	Serviceable	683.20 F	*- FL
12	1		*FRONT DOOR INNER TRIM BOARD O/S	Deformed / Twisted	1,980.20 F	*1,527.90 FL
13	1		*SET FRONT DOOR INNER TRIM BOARD CLIPS O/S	Necessary	50.00 F	*50.00 FL
14	1		*SET FRONT DOOR FRAME BLACK STICKER O/S	Necessary	115.00 F	*80.00 FL
15	1		*FRONT DOOR SPEAKER O/S	Not Necessary	288.90 F	*- FL
16	1		*FRONT DOOR INNER RUBBER O/S	Not Necessary	366.50 F	*- FL
17	1		*FRONT DOOR MIRROR ASSY O/S	Damaged	1,805.20 F	*1,405.20 FL
18	1		*SLIDING DOOR O/S	Dented / Bent	3,866.20 F	*2,666.80 FL
19	1		*SLIDING DOOR FRONT RUBBER O/S	Cut	322.20 F	*281.50 FL
20	1		*SET SLIDING DOOR FRAME BLACK STICKER O/S	Necessary	180.00 F	*80.00 FL
21	1		*SLIDING DOOR OUTER PROTECTOR O/S	Twisted / Torn	4,885.10 F	*466.20 FL
22	1		*SLIDING DOOR LOWER BRACKET O/S	Serviceable	450.10 F	*- FL
23	1		*REAR FENDER O/S	Repair	1,945.10 F	*- FL
24	1		*REAR FENDER OUTER PROTECTOR O/S	Cut / Torn	355.10 F	*291.50 FL
25	1		*REAR BUMPER	Cut / Torn	2,255.10 F	*1,650.00 FL
26	1		*SET DOOR VISOR O/S	Necessary	100.00 FS	*60.00 FS
27	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
28	1		*REAR SPORT RIM O/S	Cut	800.00 FS	*500.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	29,033.80	12,562.60
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	2,993.15
Total Parts (S\$)	29,033.80	9,569.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
3	TO DISMANTLE & REFIX FRONT DOOR MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REFIX SLIDING DOOR MECHANISM	New	100.00	60.00
5	TO SPRAY RUST PROOFING	New	120.00	60.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	500.00
7	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,100.00
Gross Labour Cost (\$\$)			3,190.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >