8/1/24, 11:04 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

Our File No: CS/CTI24070208/EQP3M4

Singapore 079909 Date: 01/08/2024

REFERENCE

Insured/Claimant: UNCLE LIN TRANSPORT Policy No: DMB1SNW00003032401

Date of Loss: 09/07/2024 Nature of Claim: OD Claim No: SNM24D203934/C01/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: CB356C

 Make & Model:
 TOYOTA HIACE, 2.8 D DX (A)
 Engine No:
 1GD9029962

 Reg. Date:
 23/03/2023 (Man. Year: 2022)
 Chassis No:
 GDH2012030308

Colour: Silver Odometer: 0 km

Engine Capacity: 2754 cc Market Value/New Car Price: \$\$52,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	0.00	2,000.00	-2,000.00	
Nett Amount (S\$)	0.00	-2,000.00	2,000.00	

INSPECTION

Date of Assignment: 10/07/2024 Present Location: Jin Auto Services Pte Ltd (Defu)

Jin Auto Services Pte Ltd (Defu)

Date Inspected: 11/07/2024 Inspected At: Blk 14 Defu Lane 10, #01-410/412

Singapore 539195

Estimated Period of Repair: 0.0 days

Adjuster: CHEN TSUE YEE Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value: \$ 52,000.00 to \$56,000.00

OMV: \$ 30,608.00

PARF Rebate (1): \$ 0.00

Quota Premium Paid: \$ 0.00

COE Rebate (2): \$ 0.00

Total Rebate (1) + (2) =: \$ 0.00

The total amount incurred will be Market Value \$52,000.00 to \$56,000.00 minus Total Rebate \$0.00 = \$52,000.00 to \$56,000.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Aug 2024)

Parts: 213 TOYOTA HIACE 2.8 D DX (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for CB356C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >