## Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Jenny Lew Date: 16 Jul 2024

## **Preliminary Advice**

Vehicle No : CB356C **Accident Date** : 09/07/2024

Make : TOYOTA HIACE Policy No.

DMB1SNW00003032401

: S\$2,000.00 Assignment Date : 10/07/2024 Excess

Est. Duration of Repair Date of Inspection : 11/07/2024 : 0

Inspection At : JIN AUTO SERVICES PTE LTD (DEFU)

BLK 14 DEFU LANE 10, #01-410/412

SINGAPORE 539195

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ **TOTAL LOSS TOTAL LOSS** 

**Revised Amount** :S\$

Check Items (Estimated) :S\$ Total :S\$

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 103,000.00 COE / PARF Rebate :S\$ 0.00

Salvage Value :S\$

Margin for Repair :S\$ 103,000.00

### Remarks

(	,	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(	X	)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: