

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 18 Jul 2024

Preliminary Advice

Insured Vehicle No	: FBU3464R	Accident Date	: 09/07/2024
TP Vehicle No	: SNF5415G	Assignment Date	: 11/07/2024
Make	: TOYOTA SIENTA	Est. Duration of Repair	: 5
Date of Inspection	: 12/07/2024		
Inspection At	: 1ST AUTOMOTIVE SERVICES PTE LTD (PAYA UBI) (HQ) 53 UBI AVE 1 #01-09 PAYA UBI INDUSTRIAL SINGAPORE 408934		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,939.49
Revised Amount	:S\$	4,759.13
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,759.13
Lump Sum Repair	:S\$	3,800.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	103,000.00
COE / PARF Rebate	:S\$	45,346.00
Salvage Value	:S\$	
Margin for Repair	:S\$	57,654.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.
 Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.