



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBT 1810T

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR MUDGUARD	NOT NECESSARY	\$210.00	\$0.00
1	REAR MUDGUARD REFLECTOR	NOT NECESSARY	\$16.00	\$0.00
1	AIR CLEANER BOX COVER	CUT	\$126.00	\$126.00
1	REAR EXHAUST PIPE	NOT NECESSARY	\$650.00	\$0.00
1	REAR EXHAUST PIPE PROTECTOR	CUT	\$177.00	\$123.00
1	FRONT WING MIRROR	O/S CUT	\$52.00	\$26.00
1	BRAKE LEVER	NOT NECESSARY	\$38.00	\$0.00
1	BALANCER	NOT NECESSARY	\$35.00	\$0.00
1	HEADLAMP	CRACKED	\$683.00	\$683.00
1	HEADLAMP COWLING	CUT	\$335.00	\$335.00
1	HEADLAMP COWLING SIDE COVER	CUT	\$189.00	\$189.00
1	HEADLAMP COWLING SIGNAL LAMP	CRACKED	\$240.00	\$240.00
1	STEP BOARD	CUT	\$192.00	\$192.00
1	STEP BOARD UNDERCOVER	NOT NECESSARY	\$290.00	\$0.00
1	STEP BOARD SIDE GARNISH (SILVER)	CUT	\$85.00	\$85.00
1	FRONT FORK ASSY	NOT NECESSARY	\$1,320.00	\$0.00
1	FRONT FORK UNDER BRACKET	NOT NECESSARY	\$280.00	\$0.00
1	STEERING STEM	NOT NECESSARY	\$295.00	\$0.00
	LESS 10.00% DISCOUNT		(\$521.30)	(\$199.90)
			\$4,691.70	\$1,799.10
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	\$20.00	\$0.00
1	REAR BOX (SN)	CUT	\$280.00	\$150.00
1	REAR STORAGE BAG (SN)	NOT NECESSARY	\$300.00	\$0.00
1	HEADLAMP COWLING STICKERS (SN)	NECESSARY	\$50.00	\$30.00
1	FRONT FORK OIL (SN)	NOT NECESSARY	\$30.00	\$0.00
1	FRONT FORK OIL SEAL (SN)	NOT NECESSARY	\$50.00	\$0.00
1	STEERING CONE & BEARING (SN)	NOT NECESSARY	\$90.00	\$0.00
			\$820.00	\$180.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR		\$400.00	\$200.00
	SPRAY PAINTING		\$400.00	\$200.00
	WIRING		\$50.00	\$30.00
	TO REMOVE EXHAUST PIPE	NOT NECESSARY	\$80.00	\$0.00
	TO STRAIGHTEN BODY CHASSIS	NOT NECESSARY	\$250.00	\$0.00
			\$1,180.00	\$430.00
GRAND TOTAL			\$6,691.70	\$2,409.10
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,900.00
Report Ref No: CS/LIP24070212/Avh3				

MARKET VALUE: \$12,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$6,548.00=NETT VALUE: \$5,452.00

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.