



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBF 8027R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT RH DOOR	DENTED	\$2,245.20	\$1,890.00
1	FRONT RH DOOR CHECKER	NOT NECESSARY	\$96.50	\$0.00
1	FRONT RH DOOR HINGE (LOWER)	NOT NECESSARY	\$199.40	\$0.00
1	FRONT RH DOOR HINGE (TOP)	NOT NECESSARY	\$199.40	\$0.00
1	FRONT RH DOOR INNER ARCH GARNISH	NOT NECESSARY	\$95.70	\$0.00
1	FRONT RH DOOR INNER TRIM BOARD	CRACKED	\$852.70	\$790.00
1	FRONT RH DOOR MECHANISM LOCK	NOT NECESSARY	\$613.30	\$0.00
1	FRONT RH DOOR SIDE MIRROR ASSY	CUT	\$1,492.90	\$1,290.00
1	FRONT RH DOOR WEATHER STRIP	NOT NECESSARY	\$249.40	\$0.00
1	FRONT RH DOOR WEATHER STRIP (ARCH)	NOT NECESSARY	\$55.20	\$0.00
1	FRONT RH DOOR WINDOW REGULATOR WITH MOTOR	DAMAGED	\$347.70	\$347.70
1	FRONT RH DOOR WIRE HARNESS	NOT NECESSARY	\$526.70	\$0.00
1	FRONT RH DOOR WIRE HARNESS COVER	NOT NECESSARY	\$867.50	\$0.00
1	FRONT RH HEADLAMP	NOT NECESSARY	\$791.40	\$0.00
1	FRONT RH STEP GARNISH	CUT	\$175.40	\$175.40
1	FRONT RH STEP PANEL	TO REPAIR SEE LABOUR	\$78.90	\$0.00
	<b>LESS 25.00% DISCOUNT</b>		(\$2,221.83)	(\$1,123.28)
			<b>\$6,665.47</b>	<b>\$3,369.82</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT RH DOOR 3D ART WORK STICKER (SN)	NECESSARY	\$450.00	\$200.00
1	FRONT RH DOOR COMPANY DETAIL STICKER (SN)	NECESSARY	\$25.00	\$25.00
1	SET FRONT RH DOOR INNER TRIM BOARD CLIPS (SN)	NECESSARY	\$50.00	\$30.00
			<b>\$525.00</b>	<b>\$255.00</b>

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSSING. (TO FR)		\$80.00	\$30.00
	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE		\$120.00	\$60.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT		\$800.00	\$500.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT RH STEP PANEL		\$750.00	\$300.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL		\$80.00	\$30.00
			\$1,830.00	\$920.00
GRAND TOTAL			\$9,020.47	\$4,544.82
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$3,600.00
Report Ref No: CS/INC24070213/Aqh3e2				

TOTAL FOR SPARE PARTS: \$ 7,190.47 \$ 3,624.82  
TOTAL FOR LABOUR : \$ 1,830.00 \$ 920.00  
TOTAL REPAIR COST: \$ 9,020.47 \$ 4,544.82

**LWP**

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.