



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMG 9854C

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BOOT LID	BENT	\$1,582.00	\$1,297.00
1	REAR BOOT LID KIA LOGO	NECESSARY	\$68.00	\$68.00
1	REAR BOOT LID CERATO EMBLEM	NECESSARY	\$62.00	\$62.00
1	REAR LAMP RH	MTG CRACKED	\$695.00	\$695.00
1	REAR BUMPER	CRACKED	\$688.00	\$688.00
1	REAR BUMPER DIFFUSER	CRACKED	\$395.00	\$395.00
1	REAR BUMPER LAMP RH	MTG CRACKED	\$285.00	\$285.00
1	REAR BUMPER SIDE RETAINER RH	DISTORTED	\$110.00	\$110.00
1	REAR BUMPER REINFORCEMENT	CRACKED	\$445.00	\$445.00
1	REAR BUMPER REINFORCEMENT STAY RH	BENT	\$230.00	\$230.00
1	REAR BUMPER TOP BRACKET RH	SERVICEABLE	\$28.00	\$0.00
1	REAR BUMPER LOWER BRACKET RH	CRACKED	\$84.00	\$84.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	\$535.00	\$0.00
1	REAR END PANEL TOP GARNISH	SERVICEABLE	\$182.00	\$0.00
1	REAR BOOT WEATHERSTRIP	SERVICEABLE	\$166.00	\$0.00
1	REAR FENDER LOWER GARNISH	CRACKED	\$132.00	\$132.00
	<b>LESS 10.00% DISCOUNT</b>		(\$568.70)	(\$449.10)
			\$5,118.30	\$4,041.90

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	\$45.00	\$45.00
1	SET END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	\$35.00	\$0.00
1	SET REVERSE SENSOR (SN)	DENTED/SCRATCHED	\$280.00	\$200.00
			\$360.00	\$245.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE & REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS		\$80.00	\$20.00
	TO REMOVE & REPLACE UPHOLSTRY, TRIM GARNISHES TO FACILITATE REPAIRS		\$120.00	\$50.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, TRANSFER BOOT LID COMPOPONENTS		\$100.00	\$50.00
	TO REMOVE, REPAIR & REPLACE DAMAGED BODYPARTS, REALIGN BODYWORK AND WHERE CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR END PANEL		\$1,000.00	\$500.00
	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS		\$800.00	\$600.00
	TO REMOVE & RENEW REVERSE SENSOR		\$100.00	\$50.00
	RUST PROOFING ON AFFECTED PORTIONS		\$100.00	\$30.00
			\$2,300.00	\$1,300.00
<b>GRAND TOTAL</b>			<b>\$7,778.30</b>	<b>\$5,586.90</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>\$4,450.00</b>
Report Ref No: CS/AGI24070214/Kqp3e2				

## KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.