

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24060053/UUA3Q2
Date: 12/09/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002582_01
Claimant Vehicle No : FBN1676X Insured Vehicle No : SLJ2383L
Date of Loss: 23/05/2024 Nature of Claim: TP Claim No: MFL2024D0006457

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBN1676X
Make & Model: YAMAHA NMAX155, 155cc ABS Engine No: G3H6E0009657
Reg. Date: 27/07/2018 (Man. Year: 2018) Chassis No: MH3SG431000007448
Colour: White Odometer: 133463 km
Engine Capacity: 155 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110-70-13 Rear Tyre Size: 130-70-13
Front Left Side: EUROGRIP 4 mm Rear Left Side: EUROGRIP 4 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,485.00	1,002.90	482.10	32.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	725.00	600.00	125.00	17.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,210.00	1,602.90	607.10	27.47
Approved Total (Overridden) (S\$)		1,250.00		
(S\$)	2,210.00	1,250.00	960.00	43.44
+ GST 9.00/9.00% (S\$)	198.90	112.50	86.40	43.44
Nett Amount (S\$)	2,408.90	1,362.50	1,046.40	43.44
+ Loss of Use (3.0 x S\$20.00/day) (S\$)		60.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		1,449.75		

INSPECTION

Date of Assignment: 13/06/2024
Date Inspected: 13/06/2024 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)
Industrial City
Singapore 533758
Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 Jul 2024)	
Parts:	N/A	YAMAHA NMAX155 155cc ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN1676X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BELLY PAN	Cut	37.00 F	*37.00 FL
2	1		*BOARD FOOTREST LH	Cut	58.00 F	*58.00 FL
3	1		*BOX FILTER AIR OUTER	Cut	19.00 F	*19.00 FL
4	1		*BOX FILTER AIR OUTER FRONT	Not Necessary	12.00 F	*- FL
5	1		*BOX REAR (GIVI) B45NM	Cut	272.00 F	*272.00 FL
6	1		*COVER CLUTCH OUTER	Cut	31.00 F	*31.00 FL
7	1		*COVER CLUTCH OUTER DAMPER 1	Cut	13.00 F	*13.00 FL
8	1		*COVER CLUTCH OUTER DAMPER 2	Necessary	8.00 F	*8.00 FL
9	1		*COVER CLUTCH OUTER DAMPER 3	Necessary	8.00 F	*8.00 FL
10	1		*COVER CLUTCH OUTER DAMPER 4	Necessary	13.00 F	*13.00 FL
11	1		*COVER FRONT UPPER (WHITE)	Cut	40.00 F	*40.00 FL
12	1		*COVER SIDE LH (GREY)	Cut	42.00 F	*42.00 FL
13	1		*COVER SIDE LOWER LH (WHITE)	Cut	24.00 F	*24.00 FL
14	1		*COVER SIDE REAR LH (WHITE)	Cut	33.00 F	*33.00 FL
15	1		*COWLING FRONT LH (WHITE)	Cut	36.00 F	*36.00 FL
16	1		*LAMP SIGNAL FRONT LH	Cracked	39.00 F	*39.00 FL
17	1		*MIRROR LH	Missing	33.00 F	*33.00 FL
18	1		*MUDGUARD FRONT (WHITE)	Repair	51.00 F	*- FL
19	1		*OBU TYRE B (12V) NEW (CUT)	Not Consistent With The Impact	341.00 F	*- FL
20	1		*PANEL 1 (SILVER) LH	Cut	24.00 F	*24.00 FL
21	7		*RIVET	Necessary	21.00 F	*21.00 FL
22	1		*SCREW (WINDSHIELD) (MISSING)	Not Consistent With The Impact	3.00 F	*- FL
23	1		*STICKER (CISCO DIAMOND GRADE) COWLING FRONT LH	Necessary	45.00 FS	*45.00 FS
24	1		*STICKER (CISCO DIAMOND GRADE) COWLING REAR LH	Necessary	40.00 FS	*40.00 FS
25	1		*STICKER (CISCO DIAMOND GRADE) MUDGUARD FRT	Necessary	48.00 FS	*48.00 FS
26	1		*STICKER (CISCO DIAMOND GRADE) SIDE BOTTOM COWL LH	Necessary	57.00 FS	*57.00 FS
27	1		*STICKER (CISCO) COVER CENTRE LH	Necessary	40.00 FS	*40.00 FS
28	1		*STICKER (CISCO) COWLING FRONT LH	Necessary	40.00 FS	*40.00 FS
29	1		*STICKER (CISCO) LINING COVER REAR RH	Necessary	17.00 FS	*17.00 FS
30	1		*STICKER (CISCO) MUDGUARD FRONT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,485.00	1,078.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	75.10
Total Parts (S\$)	1,485.00	1,002.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	425.00	300.00
2	SPRAY LACQUER	New	300.00	300.00
Gross Labour Cost (S\$)			725.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >