



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

INDIA INTERNATIONAL INSURANCE P.L.
64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711

NO. : 46747

DATE : 28/05/2024
CLAIM NO. : 12501
POLICY NO. : MC/01008824/02
FROM : RAYMOND

VEHICLE NO. : FBN1676X
MAKE/MODEL : YAM / NMAX155 ABS

*Not Authorised
13/6/24
d/s #12501
3 days
the ph...*

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BELLY PAN P/N: 58094 (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	37.00
2	BOARD FOOTREST LH P/N: 59588 (REPORTED BY MECHANIC)	REPLACE	1.00	\$58.00	58.00
3	BOX FILTER AIR OUTER P/N: 58141 (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	19.00
4	BOX FILTER AIR OUTER FRONT P/N: 58164 (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
5	BOX REAR (GIVI) B45NM P/N: 79580 (REPORTED BY MECHANIC)	REPLACE	1.00	\$272.00	272.00
6	COVER CLUTCH OUTER P/N: 58147 (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00
7	COVER CLUTCH OUTER DAMPER 1 P/N: 58111 (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	13.00
8	COVER CLUTCH OUTER DAMPER 2 P/N: 58172 (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	8.00
9	COVER CLUTCH OUTER DAMPER 3 P/N: 58107 (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	8.00

*46747 *



bizSAFE



S/N	Description	Action	Qty	Unit Price	Amount
10	COVER CLUTCH OUTER DAMPER 4 P/N: 58140 - (REPORTED BY MECHANIC)	REPLACE <i>new</i>	1.00	\$13.00 ✓	13.00
11	COVER FRONT UPPER (WHITE) P/N: 59585 - (REPORTED BY MECHANIC)	REPLACE <i>CU</i>	1.00	\$40.00 ✓	40.00
12	COVER SIDE LH (GREY) P/N: 60877 - (REPORTED BY MECHANIC)	REPLACE <i>CU</i>	1.00	\$42.00 ✓	42.00
13	COVER SIDE LOWER LH (WHITE) P/N: 58097 - (REPORTED BY MECHANIC)	REPLACE <i>CU</i>	1.00	\$24.00 ✓	24.00
14	COVER SIDE REAR LH (WHITE) P/N: 58170 - (REPORTED BY MECHANIC)	REPLACE <i>CU</i>	1.00	\$33.00 ✓	33.00
15	COWLING FRONT LH (WHITE) P/N: 58179 - (REPORTED BY MECHANIC)	REPLACE <i>new</i>	1.00	\$36.00 ✓	36.00
16	LABOUR P/N: 06766 - (REPORTED BY MECHANIC)	* REPLACE	5.00	\$85.00 <i>300</i>	425.00
17	LAMP SIGNAL FRONT LH P/N: 59587 - (REPORTED BY MECHANIC)	REPLACE <i>CU</i>	1.00	\$39.00 ✓	39.00
18	MIRROR LH P/N: 58099 - (REPORTED BY MECHANIC)	REPLACE <i>new</i>	1.00	\$33.00 ✓	33.00
19	MUDGUARD FRONT (WHITE) P/N: 58087 - (REPORTED BY MECHANIC)	REPLACE <i>n</i>	1.00	\$51.00 X	51.00
20	OBV TYPE B (12V) NEW P/N: 82490 - (REPORTED BY MECHANIC)	REPLACE <i>CU n/c</i>	1.00	\$341.00 X <i>old type</i>	341.00
21	PANEL 1 (SILVER) LH P/N: 60905 - (REPORTED BY MECHANIC)	REPLACE <i>CU</i>	1.00	\$24.00 ✓	24.00
22	RIVET P/N: 56583 - (REPORTED BY MECHANIC)	REPLACE <i>new</i>	7.00	\$3.00 ✓	21.00 ✓
23	SCREW (WINDSHIELD) P/N: 62053 - (REPORTED BY MECHANIC)	REPLACE <i>new</i>	1.00	\$3.00 <i>n/c</i> X	3.00
24	SPARY LACQUER - (REPORTED BY MECHANIC)	<i>labour</i> * REPLACE	<i>500</i> 1.00	<i>300</i> \$0.00	0.00

*46747 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
25	STICKER (CISCO DIAMOND GRADE) COWLING FRONT LH P/N: 79323 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$45.00	45.00
26	STICKER (CISCO DIAMOND GRADE) COWLING REAR LH P/N: 79321 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
27	STICKER (CISCO DIAMOND GRADE) MUDGUARD FRT P/N: 79325 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$48.00	48.00
28	STICKER (CISCO DIAMOND GRADE) SIDE BOTTOM COWL LH P/N: 79324 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$57.00	57.00
29	STICKER (CISCO) COVER CENTRE LH P/N: 58614 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
30	STICKER (CISCO) COWLING FRONT LH P/N: 58616 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
31	STICKER (CISCO) LINING COVER REAR RH P/N: 58613 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00
32	STICKER (CISCO) MUDGUARD FRONT P/N: 58618 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00

SUB TOTAL

\$1,910.00

GST @ 9 %

\$171.90

GRAND TOTAL (SGD)

\$2,081.90

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*46747 *

bizSAFE₃