

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24070223/AMA3Q2
Date: 06/01/2025**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002571_01
Claimant Vehicle No : GBM333Y **Insured Vehicle No :** SLD2297J
 Date of Loss: 11/07/2024 Nature of Claim: TP Claim No: MFL2024D0008851

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBM333Y**
 Make & Model: BYD T3, (A) Engine No: HIDDEN
 Reg. Date: 15/06/2021 (Man. Year: 2021) Chassis No: LC0CE4DB3M0011670
 Colour: White Odometer: 230151 km
 Engine Capacity: 0 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/60 R16 Rear Tyre Size: 195/60 R16
 Front Left Side: Grenlander 6 mm Rear Left Side: Grenlander 6 mm
 Front Right Side: Grenlander 6 mm Rear Right Side: Grenlander 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	27,945.31	18,649.16	9,296.15	33.27	
Miscellaneous Items	0.00	0.00	0.00		
Labour	4,250.00	2,600.00	1,650.00	38.82	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	32,195.31	21,249.16	10,946.15	34.00	
Approved Total (Overridden) (S\$)		17,000.00			
	(S\$)	32,195.31	17,000.00	15,195.31	47.20
+ GST 9.00/9.00% (S\$)	2,897.58	1,530.00	1,367.58	47.20	
Nett Amount (S\$)	35,092.89	18,530.00	16,562.89	47.20	
+ Car Rental (10.0 x S\$105.00/day + 9.00% GST) (S\$)		1,144.50			
+ Doc/Search Fee (S\$)		27.25			
	Nett Liability (S\$)	19,701.75			
	Global Sum Settlement (S\$)	19,650.00			

INSPECTION

Date of Assignment: 12/07/2024
 Date Inspected: 12/07/2024 Inspected At: N-51 Automotive Pte Ltd (HQ)
 BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT
 AUTOHUB
 Singapore 417921
 Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Nov 2024)
Parts: M1-MPV	BYD T3 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBM333Y)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	2,069.10 FL	*1,890.00 FL
2	1		*REAR BUMPER CENTER LAMP	Cracked	469.00 FL	*469.00 FL
3	1		*REAR BUMPER CENTER LAMP COVER	Missing	259.00 FL	*259.00 FL
4	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	820.00 FL	*410.00 FL
5	4		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary (2 PCS ONLY)	240.00 FL	*50.00 FL
6	2		*REAR BUMPER SIDE RETAINER L/R	Cracked	290.00 FL	*290.00 FL
7	1		*REAR END PANEL (INNER)	Distorted	1,769.40 FL	*1,100.00 FL
8	1		*REAR END PANEL (OUTER)	Distorted	1,298.00 FL	*905.00 FL
9	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	295.00 FL	*- FL
10	1		*REAR END PANEL INNER TOP GARNISH	Deformed	326.40 FL	*326.40 FL
11	1		*REAR FLOOR PANEL	Repair	4,370.00 FL	*- FL
12	1		*REAR TAILGATE	Distorted	9,687.00 FL	*9,687.00 FL
13	1		*REAR TAILGATE BYD EMBLEM	Necessary	205.00 FL	*205.00 FL
14	1		*REAR TAILGATE T3 EMBLEM	Necessary	189.00 FL	*189.00 FL
15	2		*REAR TAILGATE HINGES L/R	Not Necessary	538.00 FL	*- FL
16	1		*REAR TAILGATE INNER PULL HANDLE	Cracked	105.00 FL	*105.00 FL
17	1		*REAR TAILGATE INNER TRIM BOARD	Cracked	788.00 FL	*788.00 FL
18	1		*REAR TAILGATE LOCK COVER	Cracked	80.00 FL	*80.00 FL
19	1		*REAR TAILGATE MECHANISM LOCK	Damaged	480.00 FL	*480.00 FL
20	2		*REAR TAILGATE NUMBER PLATE LAMP L/R	Not Necessary	230.00 FL	*- FL
21	1		*REAR TAILGATE OUTER CHROME HANDLE	Cracked	699.00 FL	*520.00 FL
22	1		*REAR TAILGATE WEATHERSTRIP	Cut	369.00 FL	*369.00 FL
23	2		*REAR TAILLAMP L/R	Cracked	1,780.00 FL	*1,510.00 FL
24	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
25	1		*REAR FLOOR PANEL TOP ALUMINIUM PLATE	Bent	2,800.00 FS	*800.00 FS
26	1		*REAR TAILGATE 6 PAX STICKER	Necessary	25.00 FS	*15.00 FS
27	1		*REAR TAILGATE 70KM STICKER	Necessary	25.00 FS	*15.00 FS
28	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
29	1		*REAR TAILGATE NUMBER PLATE	Not Necessary	25.00 FS	*- FS
30	1		*REAR TAILGATE NUMBER PLATEHOLDER	Not Necessary	50.00 FS	*- FS
31	1		*SET REAR TAILGATE OUTER CHROME HANDLE CLIPS	Necessary	50.00 FS	*20.00 FS
32	1		*REAR TAILGATE WINDSCREEN SEAL	Necessary	80.00 FS	*40.00 FS
33	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS
34	2		*SET REAR TAILLAMP CLIPS L/R	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	30,680.90	20,612.40
- List Item Discount on L Items 10.00/10.00% (\$)	2,735.59	1,963.24
Total Parts (\$)	27,945.31	18,649.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESET SYSTEM AFTER REPAIR WORKS	New	400.00	0.00
2	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
3	TO REMOVE ,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
4	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET TO FR	New	100.00	60.00
5	TO RESPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,300.00	800.00
6	TO PROVIDE LABOUR WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND REALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	2,000.00	1,400.00
7	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	140.00	80.00
8	TO REMOVE ,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	60.00
Gross Labour Cost (\$\$)			4,250.00	2,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >