

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURAN	CE LTD	Ref:	CS/INC24070225/Anh3e2	
	75 BRAS BASAH RO	OAD SINGAPORE 189557	Date:	06/11/2024	
	INCOME CENTRE	SINGAPORE 169557	Code:	INC	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	PA 8705C	Veh. Inspected	SGA 5333T	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1284101-002	Excess	\$0.00	
	Assign From	YEE PEI LI	Assign Date	11/07/2024	
2.	2. Vehicle Details				
	Make & Model	TOYOTA VELLFIRE	C.C	2362	
	Engine No.	2AZH553844	Year of Reg.	19/10/2010	
	Chassis No.	ANH208133265	Colour	WHITE	
	Odometer	- KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	255/35 R19	GITI	6	
	L/H Front Tyre	255/35 R19	GITI	6	
	R/H Rear Tyre	255/35 R19	GITI	6	
	L/H Rear Tyre	255/35 R19	GITI	6	
4.	Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S, FRONT N/S PORTION AND UNDERCARRIAGE.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	01/07/2024	Inspection Date	12/07/2024 (13:55)	
	Survey held at	AUTO UNITED SG PTE LTD - 1 KAKI BUKIT AVENUE 6, #01-92, AUTOBAY@KAKI BUKIT, SINGAPORE 417883			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
FOTIMATED NORMAL DEDICE FOR DEDAID: 20 Working David					

ESTIMATED NORMAL PERIOD FOR REPAIR: 28 Working Days