

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING

SINGAPORE 048581

INV No. : SAC2401345

INV Date : 12-11-2024

Reference CD/FCI24060054/Uma3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLG 6681R
Insured Veh. SHC 7287H
Claim No. D24005156MFCT/CCPL/TPD
Policy No. D-24101860MFCT
Accident Date 09/06/2024
Inspection Date 24/06/2024

Description	Amount
Third Party Express Settlement	300.00
Sub-Total	300.00
GST (9%)	27.00
Grand Total	327.00

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CD/FCI24060054/Uma3q2
16 RAFFLES QUAY	Date:	12/11/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SHC 7287H	Veh. Inspected	SLG 6681R
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24005156MFCT/CCPL/TPD	Excess	\$0.00
Assign From	-	Assign Date	12/06/2024

2. Vehicle Details

Make & Model	HONDA CIVIC 1.6 (A)	C.C	1597
Engine No.	R16B21600523	Year of Reg.	10/10/2016
Chassis No.	MRHFC5650GT000427	Colour	BLUE
Odometer	127644 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55R16	MICHELIN	6
L/H Front Tyre	205/55R16	MICHELIN	6
R/H Rear Tyre	205/55R16	MICHELIN	6
L/H Rear Tyre	205/55R16	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/06/2024	Inspection Date	24/06/2024
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT)		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLG 6681R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRT FENDER RH	DENTED / BENT	\$482.30	\$482.30
1	FRT FENDER INNER COWLING RH	TWISTED / TORN	\$82.50	\$82.50
10	INNER COWLING CLIPS @\$3.50	NECESSARY	\$35.00	\$35.00
1	FRT BUMPER	CUT	\$670.50	\$670.50
1	FRT BUMPER RETAINER RH	NECESSARY	\$27.10	\$27.10
10	FRT BUMPER CLIPS @\$3.50	NECESSARY	\$35.00	\$35.00
1	HEADLAMP RH	HOLDER CRACKED	\$882.70	\$882.70
1	FRT FENDER SIDE SIGNAL LAMP RH	CRACKED	\$184.90	\$184.90
	LESS 20.00% DISCOUNT		(\$480.00)	(\$480.00)
			\$1,920.00	\$1,920.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	WIRE CHECKING		\$30.00	\$20.00
	LABOUR CHARGE		\$600.00	\$300.00
	SPRAY PAINTING		\$600.00	\$400.00
			\$1,230.00	\$720.00

GRAND TOTAL	\$3,150.00	\$2,640.00
--------------------	-------------------	-------------------

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$2,100.00
---	--	-------------------

Report Ref No: CD/FCI24060054/Uma3q2

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SLG 6681R



PHOTOGRAPHS FOR VEHICLE NO. : SLG 6681R



PHOTOGRAPHS FOR VEHICLE NO. : SLG 6681R



PHOTOGRAPHS FOR VEHICLE NO. : SLG 6681R



PHOTOGRAPHS FOR VEHICLE NO. : SLG 6681R



PHOTOGRAPHS FOR VEHICLE NO. : SLG 6681R



PHOTOGRAPHS FOR VEHICLE NO. : SLG 6681R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 8 of 16)


PHOTOGRAPHS FOR VEHICLE NO. : SLG 6681R




PHOTOGRAPHS FOR VEHICLE NO. : SLG 6681R





PHOTOGRAPHS FOR VEHICLE NO. : SLG 6681R



PHOTOGRAPHS FOR VEHICLE NO. : SLG 6681R



PHOTOGRAPHS FOR VEHICLE NO. : SLG 6681R



PHOTOGRAPHS FOR VEHICLE NO. : SLG 6681R



PHOTOGRAPHS FOR VEHICLE NO. : SLG 6681R



PHOTOGRAPHS FOR VEHICLE NO. : SLG 6681R



PHOTOGRAPHS FOR VEHICLE NO. : SLG 6681R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SLG 6681R

