

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNE 6769J

REPLACEMENT OF PARTS						
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	FRONT BUMPER	TO REPAIR SEE LABOUR	\$1,341.00	\$0.00		
2	FRONT BUMPER SIDE HOLDER @\$96.00	NOT NECESSARY	\$192.00	\$0.00		
	LESS 10.00% DISCOUNT		(\$153.30)	\$0.00		
			\$1,379.70	\$0.00		

Special Nett						
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	\$50.00	\$0.00		
1	FRONT BUMPER LOWER GARNISH (SN)	CHIPPED	\$1,000.00	\$650.00		
		\$1,050.00	\$650.00			

Labour					
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
	PANEL BEATING, REMOVE AND REFIT PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER		\$400.00	\$200.00	
	SPRAY PAINTING TO AFFECTED AREA		\$400.00	\$200.00	
	WIRING CHECK	NOT NECESSARY	\$50.00	\$0.00	
	TO REMOVE FRONT BUMPER SENSOR	NOT NECESSARY	\$100.00	\$0.00	
		\$950.00	\$400.00		

GRAND TOTAL	\$3,379.70	\$1,050.00	
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		\$800.00	
Report Ref No: CS/INC24070226/Avh3m4			

TOTAL FOR SPARE PARTS: \$ 2,429.70 \$ 650.00

TOTAL FOR LABOUR: \$ 950.00 \$ 400.00

TOTAL REPAIR COST: \$ 3,379.70 \$ 1,050.00

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.