

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24070227/ENP3E2**Date:** 18/07/2024REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MZC00697	
Claimant Vehicle No :	SHC8652E	Insured Vehicle No :	GBE7288R	
Date of Loss:	12/07/2024	Nature of Claim:	TP	Claim No: M2403931

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC8652E	Engine No:	G4LEKU429289
Make & Model:	HYUNDAI IONIQ, 1.6 (A)	Chassis No:	KMHC851CVLU194612
Reg. Date:	31/08/2021 (Man. Year: 2019)	Odometer:	235928 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 5 mm	Rear Left Side:	Davanti 5 mm
Front Right Side:	Davanti 5 mm	Rear Right Side:	Davanti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,441.08	746.12	694.96	48.22
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	780.00	680.00	100.00	12.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,233.08	1,438.12	794.96	35.60
+ GST 9.00/9.00% (\$\$)	200.98	129.43	71.55	35.60
Nett Amount (\$\$)	2,434.06	1,567.55	866.51	35.60

INSPECTION

Date of Assignment:	15/07/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	15/07/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jul 2024)
Parts:	143	HYUNDAI IONIQ 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC8652E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Broken	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	Cut	451.25 FL	*451.25 FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Not Necessary	138.10 FL	*- FL
6	1		*REAR BUMPER REFLECTOR LH	Not Necessary	55.00 FL	*- FL
7	1		*REAR BUMPER SIDE BRACKET LH	Not Necessary	55.80 FL	*- FL
8	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	180.00 F	*- F
					Sub Total (\$\$)	1,756.35 932.65
					- List Item Discount on L Items 20.00/20.00% (\$\$)	315.27 186.53
					Total Parts (\$\$)	1,441.08 746.12

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	380.00
2	SPRAY PAINTING CHARGE	New	300.00	280.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	20.00
Gross Labour Cost (\$)			780.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >