

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/AIG24070230/APA3Q2**Date:** 17/01/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7220091026  
**Claimant Vehicle No :** SJW8422Z **Insured Vehicle No :** SFT8833J  
 Date of Loss: 09/07/2024 Nature of Claim: TP Claim No: 2361368225SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJW8422Z**  
 Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 1NZY078341  
 Reg. Date: 23/04/2010 (Man. Year: 2010) Chassis No: MR053HY9305160949  
 Colour: Silver Odometer: 174982 km  
 Engine Capacity: 1497 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15  
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 7,516.97          | 2,675.50          | 4,841.47          | 64.41         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 4,860.00          | 1,610.00          | 3,250.00          | 66.87         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>12,376.97</b>  | <b>4,285.50</b>   | <b>8,091.47</b>   | <b>65.38</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>3,400.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 12,376.97         | 3,400.00          | 8,976.97          | 72.53         |
| <b>+ GST 9.00/9.00% (S\$)</b>                   | 1,113.93          | 306.00            | 807.93            | 72.53         |
| <b>Nett Amount (S\$)</b>                        | <b>13,490.90</b>  | <b>3,706.00</b>   | <b>9,784.90</b>   | <b>72.53</b>  |
| <b>+ Loss of Use (7.0 x S\$60.00/day) (S\$)</b> |                   | 420.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 27.25             |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>4,153.25</b>   |                   |               |

INSPECTION

Date of Assignment: 11/07/2024  
 Date Inspected: 11/07/2024 Inspected At: HD Perfect Autowork Pte Ltd (HQ)  
 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit  
 Singapore 415875  
 Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                              | Condition     | Repairer's | Amount     |
|-----|-----|----------|------------------------------------------|---------------|------------|------------|
| 1   | 1   |          | *BOOT LID                                | Dented        | 575.00 FL  | *575.00 FL |
| 2   | 1   |          | *BOOT LID LOGO                           | Necessary     | 70.00 FL   | *70.00 FL  |
| 3   | 1   |          | *BOOT LID EMBLEM VIOS                    | Necessary     | 65.00 FL   | *65.00 FL  |
| 4   | 1   |          | *BOOT LID EMBLEM E                       | Necessary     | 55.00 FL   | *55.00 FL  |
| 5   | 1   |          | *BOOT LID OUTER MOULDING                 | Not Necessary | 190.00 FL  | *- FL      |
| 6   | 2   |          | *BOOT LID NUMBER PLATE LAMP              | Not Necessary | 84.00 FL   | *- FL      |
| 7   | 1   |          | *BOOT LID TOP LOCK                       | Not Necessary | 155.00 FL  | *- FL      |
| 8   | 1   |          | *BOOT LID LOWER LOCK                     | Not Necessary | 25.00 FL   | *- FL      |
| 9   | 1   |          | *BOOT LID KEY LOCK                       | Not Necessary | 225.00 FL  | *- FL      |
| 10  | 1   |          | *BOOT LID WEATHERSTRIP                   | Cut           | 205.00 FL  | *205.00 FL |
| 11  | 2   |          | *BOOT LID HINGE                          | Not Necessary | 140.00 FL  | *- FL      |
| 12  | 1   |          | *REAR BUMPER                             | Distorted     | 495.00 FL  | *495.00 FL |
| 13  | 1   |          | *REAR BUMPER REFLECTOR                   | O/S Cracked   | 210.00 FL  | *105.00 FL |
| 14  | 2   |          | *REAR BUMPER BRACKET                     | Not Necessary | 178.00 FL  | *- FL      |
| 15  | 2   |          | *REAR BUMPER SIDE RETAINER (FRONT)       | Not Necessary | 210.00 FL  | *- FL      |
| 16  | 2   |          | *REAR BUMPER SIDE RETAINER (REAR)        | Not Necessary | 110.00 FL  | *- FL      |
| 17  | 1   |          | *TAIL LAMP                               | O/S Cracked   | 690.00 FL  | *345.00 FL |
| 18  | 2   |          | *REAR FENDER INNER COWLING               | Not Necessary | 350.00 FL  | *- FL      |
| 19  | 2   |          | *REAR FENDER INNER TRIM                  | Not Necessary | 590.00 FL  | *- FL      |
| 20  | 1   |          | *REAR CHASSIS MEMBER RH                  | Repair        | 694.30 FL  | *- FL      |
| 21  | 1   |          | *REAR END PANEL                          | Dented        | 439.00 FL  | *439.00 FL |
| 22  | 1   |          | *REAR END PANEL TOP GARNISH              | Deformed      | 230.00 FL  | *230.00 FL |
| 23  | 1   |          | *REAR FLOOR PANEL TOP BOARD              | Torn          | 175.00 FL  | *175.00 FL |
| 24  | 1   |          | *REAR FLOOR PANEL TOP SPONGE (SIDE)      | O/S Deformed  | 550.00 FL  | *275.00 FL |
| 25  | 4   |          | *REAR EXHAUST MOUNTING                   | Not Necessary | 180.00 FL  | *- FL      |
| 26  | 1   |          | *SET REAR EXHAUST GASKET                 | Not Necessary | 60.00 FL   | *- FL      |
| 27  | 1   |          | *SET REAR EXHAUST INSULATOR              | Not Necessary | 89.00 FL   | *- FL      |
| 28  | 1   |          | *REAR EXHAUST PIPE WITH BOX              | Not Necessary | 690.00 FL  | *- FL      |
| 29  | 1   |          | *REAR NUMBER PLATE                       | Not Necessary | 50.00 FS   | *- FS      |
| 30  | 1   |          | *SET REAR BUMPER CLIPS                   | Necessary     | 50.00 FS   | *30.00 FS  |
| 31  | 1   |          | *SET BOOT LID OUTER MOULDING CLIP        | Not Necessary | 30.00 FS   | *- FS      |
| 32  | 2   |          | *REAR FENDER SEALANT                     | Not Necessary | 300.00 FS  | *- FS      |
| 33  | 1   |          | *SET REAR FENDER INNER COWLING CLIPS     | Not Necessary | 80.00 FS   | *- FS      |
| 34  | 1   |          | *SET REAR FENDER INNER TRIM CLIPS        | Not Necessary | 80.00 FS   | *- FS      |
| 35  | 1   |          | *SET TAIL LAMP CLIPS                     | Not Necessary | 30.00 FS   | *- FS      |
| 36  | 1   |          | *SET REAR END PANEL TOP GARNISH CLIPS    | Necessary     | 30.00 FS   | *10.00 FS  |
| 37  | 1   |          | *REAR END PANEL INSULATION SEAL          | Necessary     | 150.00 FS  | *60.00 FS  |
| 38  | 1   |          | *REAR EXHAUST CHROME PIPE (SPECIAL TYPE) | Dented        | 250.00 FS  | *100.00 FS |
| 39  | 1   |          | *REVERSE CAMERA                          | Not Necessary | 450.00 FS  | *- FS      |
| 40  | 1   |          | *REVERSE SENSOR                          | Damaged       | 220.00 FS  | *200.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                 |                 |
|----------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>9,449.30</b> | <b>3,434.00</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$)</b> | 1,932.33        | 758.50          |
| <b>Total Parts (\$)</b>                                  | <b>7,516.97</b> | <b>2,675.50</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                    | Lab.Type | Repairer's      | Amount          |
|---------------------------------|------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                                |          |                 |                 |
| 1                               | TO PANEL BEAT ,WELD ,CUT ,KNOCK GRAZE ADJUST REPLACE NEW PARTS                                 | New      | 1,800.00        | 700.00          |
| 2                               | TO PUTTY ,SPRAY PAINT POLISH ,WAX ADJACENT PANELS                                              | New      | 1,600.00        | 600.00          |
| 3                               | TUFF COAT                                                                                      | New      | 250.00          | 60.00           |
| 4                               | WIRING BULB CHECKING                                                                           | New      | 80.00           | 30.00           |
| 5                               | REMOVE AND REFIX CUSHION SEAT / UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR                | New      | 200.00          | 60.00           |
| 6                               | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING                                           | New      | 80.00           | 50.00           |
| 7                               | REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING                                           | New      | 80.00           | 50.00           |
| 8                               | REMOVE AND REFIX REAR EXHAUST                                                                  | New      | 180.00          | 0.00            |
| 9                               | TRANSFER BOOT LID MECHANISM                                                                    | New      | 80.00           | 60.00           |
| 10                              | TO CONDUCT WATER LEAKAGE TEST                                                                  | New      | 80.00           | 0.00            |
| 11                              | REAR CHASSIS MEMBER ALIGNMENT                                                                  | New      | 250.00          | 0.00            |
| 12                              | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC | New      | 180.00          | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                |          | <b>4,860.00</b> | <b>1,610.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >