

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG24070234/EQP3M4
Date: 28/08/2024

REFERENCE

Insured/Claimant: CECILIA YUSMAN @ CECILIA Policy No: 7240111976
Date of Loss: 13/07/2024 Nature of Claim: OD Claim No: 1856889995SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNR8427P
Make & Model: AUDI A3, 999cc SEDAN 1.0 TFSI S TRONIC (A) Engine No: DLAU35391
Reg. Date: 09/07/2024 (Man. Year: 2024) Chassis No: WAUZZZGY9RA137049
Colour: Grey Odometer: 263 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$185,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17
Front Left Side: Nexen 8 mm Rear Left Side: Nexen 8 mm
Front Right Side: Nexen 8 mm Rear Right Side: Nexen 8 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,634.00	6,686.48	4,947.52	42.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,352.00	3,222.00	3,130.00	49.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,986.00	9,908.48	8,077.52	44.91
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	17,686.00	9,608.48	8,077.52	45.67
+ GST 9.00/9.00% (S\$)	1,591.74	864.76	726.98	45.67
Nett Amount (S\$)	19,277.74	10,473.24	8,804.50	45.67

INSPECTION

Date of Assignment: 15/07/2024
Date Inspected: 17/07/2024 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,889.00 FS	*1,511.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	311.00 FS	*- FS
3	1		*FRONT BUMPER BRACKET - RH	Not Necessary	145.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	486.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	298.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE - RH	Not Necessary	75.00 FS	*- FS
7	1		*FRONT BUMPER COVER TRIM - RH	Not Necessary	117.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cut	192.00 FS	*153.60 FS
9	1		*BUMPER AIR GUIDE GRILLE SENSOR SUPPORT - RH	Not Necessary	48.00 FS	*- FS
10	1		*FRONT PARKING AID SENSOR	Not Necessary	300.00 FS	*- FS
11	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	57.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	61.00 FS	*- FS
13	1		*LED HEADLIGHT - RH	Cut	4,583.00 FS	*3,666.40 FS
14	1		*LIFT CYLINDER - RH	Not Necessary	230.00 FS	*- FS
15	1		*LIFT CYLINDER HOSE	Not Necessary	118.00 FS	*- FS
16	1		*FRONT FENDER - RH	Dented	1,318.00 FS	*1,054.40 FS
17	1		*FRONT FENDER CLOSING ELEMENT - RH	Bent	36.00 FS	*28.40 FS
18	3		*FRONT FENDER RIVET RH	Necessary	13.00 FS	*10.08 FS
19	1		*FRONT FENDER BRACKET - RH	Not Necessary	56.00 FS	*- FS
20	1		*FRONT FENDER BRACKET - RH	Not Necessary	56.00 FS	*- FS
21	1		*FRONT FENDER BRACKET - RH	Not Necessary	45.00 FS	*- FS
22	1		*FRONT FENDER BRACE - RH	Bent	122.00 FS	*97.20 FS
23	1		*FRONT FENDER ATTACHMENT PARTS - RH	Not Necessary	135.00 FS	*- FS
24	1		*FRONT WHEEL HOUSING LINER - RH	Torn	204.00 FS	*162.80 FS
25	1		*FRONT WHEEL HOUSING LINER ATTACHMENT - RH	Not Necessary	139.00 FS	*- FS
26	1		*SUNDRIES	Necessary	600.00 FS	*2.40 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 11,634.00 6,686.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	350.00
3	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND INSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR	New	280.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,450.00	1,000.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR	New	2,500.00	1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$\$)			6,352.00	3,222.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >