

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24070236/UVP3E2
Date: 10/10/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	FBS5488U	Insured Vehicle No :	SLL9149R
Date of Loss:	05/07/2024	Nature of Claim:	TP
		Claim No:	DMPC2400842H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBS5488U	Engine No:	G3L8E0522891
Make & Model:	YAMAHA NMAX155, 155cc ABS	Chassis No:	MH3SG5680MK074543
Reg. Date:	25/05/2021 (Man. Year: 2021)	Odometer:	46714 km
Colour:	White		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110-70-13	Rear Tyre Size:	130-70-13
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,829.00	4,907.80	921.20	15.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,878.00	1,035.00	1,843.00	64.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,707.00	5,942.80	2,764.20	31.75
Approved Total (Overridden) (\$\$)		4,750.00		
(\$\$)	8,707.00	4,750.00	3,957.00	45.45
+ GST 9.00/9.00% (\$\$)	783.63	427.50	356.13	45.45
Nett Amount (\$\$)	9,490.63	5,177.50	4,313.13	45.45

INSPECTION

Date of Assignment:	15/07/2024	Ban Hock Hin Co. Pte Ltd (HQ)
Date Inspected:	15/07/2024 Inspected At:	BLK 8 Defu South Street 1, #04-28 JTC Defu Industrial City
Estimated Period of Repair:	5.0 days	Singapore 533758

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Oct 2024)	
Parts:	N/A	YAMAHA NMAX155 155cc ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBS5488U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AXLE FRONT WHEEL	Bent	19.00 F	*19.00 FL
2	1		*BAR HANDLE	Bent	68.00 F	*68.00 FL
3	2		*BEARING 6300-2NS (NACHI)	Necessary	32.00 F	*32.00 FL
4	1		*BELLY PAN	Distorted	37.00 F	*37.00 FL
5	1		*BOARD FOOTREST LH	Cut	37.00 F	*37.00 FL
6	1		*BOARD FOOTREST RH	Cut	37.00 F	*37.00 FL
7	4		*BOLT MUDGUARD	Necessary	52.00 F	*52.00 FL
8	2		*BOLT, FLANGE DEEP RECESS	Necessary	10.00 F	*10.00 FL
9	1		*BRAKE DISK FRONT	Bent	78.00 F	*78.00 FL
10	1		*CALIPER ASSY (RIGHT)	Damaged	109.00 F	*109.00 FL
11	1		*CARPET PAPAN ALLOY FOOTBOARD (BLACK)	Damaged	85.00 F	*85.00 FL
12	1		*CAST WHEEL, FRONT	Warped	249.00 F	*249.00 FL
13	1		*CLAMP	Necessary	6.00 F	*6.00 FL
14	7		*CLAMP	Not Necessary	35.00 F	*- FL
15	10		*CLIP NUT SPRING	Necessary	20.00 F	*20.00 FL
16	1		*COVER CARBON FIBER	Cut	651.00 F	*651.00 FL
17	1		*SET COVER	Cracked	496.00 F	*496.00 FL
18	1		*COVER, METER	Twisted	28.00 F	*28.00 FL
19	2		*DAMPER PLATE (1)	Necessary	12.00 F	*12.00 FL
20	2		*DAMPER, PLATE (2)	Necessary	10.00 F	*10.00 FL
21	1		*DAMPER, PLATE (3)	Necessary	8.00 F	*8.00 FL
22	2		*DAMPER, PLATE (4)	Necessary	10.00 F	*10.00 FL
23	1		*EMBLEM	Necessary	5.00 F	*5.00 FL
24	2		*EMBLEM (YAMAHA) LOGO	Necessary	32.00 F	*32.00 FL
25	2		*EMBLEM 3D	Necessary	94.00 F	*94.00 FL
26	2		*EMBLEM ABS	Necessary	16.00 F	*16.00 FL
27	1		*EMBLEM PANEL FRONT	Necessary	10.00 F	*10.00 FL
28	1		*FENDER INNER	Twisted	37.00 F	*37.00 FL
29	2		*FORK FRONT ASSY LH & RH	Bent / Twisted	485.00 F	*485.00 FL
30	1		*FRONT FLASHER LIGHT ASSY 2	Cracked	27.00 F	*27.00 FL
31	2		*GRAPHIC 1	Necessary	12.00 F	*12.00 FL
32	1		*HEADLAMP ASSY	Broken	411.00 F	*411.00 FL
33	1		*HOLDER, BRAKE HOSE 1	Twisted	8.00 F	*8.00 FL
34	1		*HOLDER, BRAKE HOSE 2	Twisted	5.00 F	*5.00 FL
35	1		*HOLDER, BRAKE HOSE 5	Twisted	5.00 F	*5.00 FL
36	1		*HORN	Twisted	31.00 F	*31.00 FL
37	1		*LAMP SIGNAL FRONT LH	Cracked	27.00 F	*27.00 FL
38	1		*LEG SHIELD	Cut	37.00 F	*37.00 FL
39	1		*LEG SHIELD 2	Cut	37.00 F	*37.00 FL
40	1		*LEVER BRAKE LH	Cut	19.00 F	*19.00 FL
41	1		*LEVER BRAKE RH	Cut	25.00 F	*25.00 FL
42	1		*MAIN STAND PAD	Damaged	63.00 F	*63.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*OBU TYRE B (12V) NEW	Not Necessary	341.00 F	*- FL
44	1		*PANEL 1 LH	Cut	37.00 F	*37.00 FL
45	1		*PANEL 2 RH	Cut	31.00 F	*31.00 FL
46	1		*PANEL CONSOLE METER	Cut	25.00 F	*25.00 FL
47	1		*PANEL INNER 1	Cut	25.00 F	*25.00 FL
48	1		*PANEL, CONSOLE 2	Cut	22.00 F	*22.00 FL
49	1		*PROTECTOR MUFFLER	Scratched	44.00 F	*44.00 FL
50	1		*REFLECTOR ASSY REAR	Not Necessary	5.00 F	*- FL
51	1		*RIVET (35PCS)	Necessary	105.00 F	*105.00 FL
52	1		*ROTOR SENSOR	Damaged	31.00 F	*31.00 FL
53	2		*SCREW	Necessary	12.00 F	*12.00 FL
54	6		*SCREW TAPPING	Necessary	12.00 F	*12.00 FL
55	2		*SCREW TAPPING (2)	Necessary	4.00 F	*4.00 FL
56	2		*SCREW WITH WASHER	Necessary	10.00 F	*10.00 FL
57	1		*SEAL	Necessary	3.00 F	*3.00 FL
58	3		*SEAL 1	Necessary	15.00 F	*15.00 FL
59	2		*SEAL OIL FRONT RIM 20X35X7	Necessary	12.00 F	*12.00 FL
60	1		*SIDE MIRROR	Damaged	94.00 F	*94.00 FL
61	1		*SIDE STAND PAD	Cut	63.00 F	*63.00 FL
62	1		*SPEEDOMETER ASSY	Damaged	373.00 F	*373.00 FL
63	1		*STAY FRONT COWLING	Bent	94.00 F	*94.00 FL
64	1		*SET STEERING CONE	Necessary	71.00 F	*71.00 FL
65	1		*STICKER COWLING (WHITE COVER)	Necessary	8.00 FS	*8.00 FS
66	1		*STICKER COWLING (WHITE COVER)	Necessary	8.00 FS	*8.00 FS
67	1		*STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	Necessary	30.00 FS	*30.00 FS
68	1		*STOPPER	Necessary	8.00 F	*8.00 FL
69	1		*SWITCH, SIDE STAND	Damaged	44.00 F	*44.00 FL
70	1		*VALVE TYRE 11.3MM BLACK (RACING VALVE)	Damaged	41.00 F	*41.00 FL
71	1		*VISOR AFTERMARKET	Cracked	155.00 F	*155.00 FL
72	2		*WASHER, PLATE	Necessary	4.00 F	*4.00 FL
73	1		*WHEEL SENSOR ASSY, FRONT	Damaged	50.00 F	*50.00 FL
74	1		*WIRE HARNESS ASSY	Cracked / Damaged	559.00 F	*559.00 FL
75	6		*SCREW, TAPPING (3)	Necessary	18.00 F	*18.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,829.00	5,448.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	540.20
Total Parts (\$)	5,829.00	4,907.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	BODY ALIGNMENT	New	775.00	0.00
2	LABOUR	New	2,040.00	1,000.00
3	TRANSPORT CHARGES	New	63.00	35.00
Gross Labour Cost (\$)			2,878.00	1,035.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >