



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2501567

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 17/03/2025
Reference CD/CTI24070237/Dua3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 3808G
Insured Veh. PC 7496B
Claim No. SNM24D204047C02
Policy No. DMB1SNW00013862305
Accident Date 14/07/2024
Inspection Date 16/07/2024

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (9%)	36.00
Grand Total	436.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS CHINA TAIPING INSURANCE (S) PTE LTD	Ref:	CD/CTI24070237/Dua3q2
3 ANSON ROAD #16-00	Date:	17/03/2025
SPRINGLEAF TOWER SINGAPORE 079909	Code:	CTI

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	PC 7496B	Veh. Inspected	SHC 3808G
Policy No.	DMB1SNW00013862305	Coverage	0
Claim No.	SNM24D204047C02	Excess	\$0.00
Assign From	IRENE TAY	Assign Date	15/07/2024

2. Vehicle Details

Make & Model	TOYOTA PRUIS	C.C	1798
Engine No.	2ZRLTA2302313	Year of Reg.	05/12/2019
Chassis No.	JTDKB3FU303089043	Colour	BLUE
Odometer	- KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R19	WESTLAKE	5
L/H Front Tyre	195/65R19	WESTLAKE	5
R/H Rear Tyre	195/65R19	WESTLAKE	5
L/H Rear Tyre	195/65R19	WESTLAKE	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/07/2024	Inspection Date	16/07/2024
Survey held at	59 LOYANG DRIVE LEVEL 4 ROOM 7 SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SHC 3808G

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR TRUNK LID COVER	BENT	\$1,577.24	\$1,577.24
1	REAR TRUNK LID LOCK	DAMAGED	\$641.06	\$641.06
1	REAR TRUNK LID LOCK COVER	NOT NECESSARY	\$129.80	\$0.00
1	REAR TRUNK LID LOCK SWITCH	NOT NECESSARY	\$468.90	\$0.00
1	REAR TRUNK LID COVER TRIM BOARD	NOT NECESSARY	\$303.10	\$0.00
1	REAR TRUNK LID RUBBER	DEFORMED	\$511.28	\$511.28
1	REAR TRUNK LID LAMP G5	NOT NECESSARY	\$891.52	\$0.00
1	REAR TRUNK LID GLASS (BLACK COLOR)	NOT NECESSARY	\$2,197.58	\$0.00
1	BOARD ASSY ,BACK DOOR TRIM	NOT NECESSARY	\$356.16	\$0.00
1	GARNISH SUB-ASSY ,BACK DOOR OUTSIDE	CRACKED / CUT	\$1,845.58	\$1,054.71
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	\$85.12	\$85.12
1	REAR TRUNK LID LOGO HYBRID	NECESSARY	\$73.36	\$73.36
1	REAR TRUNK LID LOGO TOYOTA STAR	NECESSARY	\$74.06	\$74.06
1	THIRD BRAKEL LIGHT	NOT NECESSARY	\$552.58	\$0.00
1	REAR TRUNK LID STRIKER	NOT NECESSARY	\$138.18	\$0.00
2	REAR TRUNK LID HINGE LH/RH @\$265.30	NOT NECESSARY	\$530.60	\$0.00
2	REAR TRUNK LID ABSORBER LH/RH @\$402.50	NOT NECESSARY	\$805.00	\$0.00
2	REAR TRUNK LID ABSORBER BRACKET LH/RH @\$179.06	NOT NECESSARY	\$358.12	\$0.00
2	REAR TRUNK LID STOPPER LH/RH @\$118.72	NOT NECESSARY	\$237.44	\$0.00
1	SPOILERSUB-ASSY REAR	NOT NECESSARY	\$1,335.18	\$0.00
1	REAR BUMPER	BROKEN	\$642.04	\$642.04
1	REAR BUMPER REINFORCEMENT	DENTED	\$446.32	\$446.32
1	REAR BUMPER UNDER COVER	NOT NECESSARY	\$773.64	\$0.00
2	REAR BUMPER SIDE RETAINER @\$157.78	NOT NECESSARY	\$315.56	\$0.00
1	REAR BUMPER UNDER CENTRE COVER	DEFORMED	\$773.64	\$773.64
1	REAR BUMPER TOWING COVER	MTG DEFORMED	\$115.78	\$115.78
1	REAR BUMPER CLIPS	NECESSARY	\$30.80	\$30.80
2	REAR BUMPER SIDE CLIP @\$35.00	NOT NECESSARY	\$70.00	\$0.00
2	REAR BUMPER UPPER STOPPER @\$106.96	NOT NECESSARY	\$213.92	\$0.00
1	ARM SUB-ASSY REAR BUMPER RH	NOT NECESSARY	\$195.44	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER UNDER SIDE COVER (RH)	NOT NECESSARY	\$324.80	\$0.00
1	RETAINER REAR BUMPER SIDE RH	NOT NECESSARY	\$132.72	\$0.00
2	RETAINER REAR BUMPER UPPER SIDE LH/RH @\$42.98	NOT NECESSARY	\$85.96	\$0.00
1	RETAINER REAR BUMPER SIDE LH	NOT NECESSARY	\$132.72	\$0.00
1	REAR BUMPER UNDER SIDE COVER (LH)	NOT NECESSARY	\$324.80	\$0.00
1	ARM SUB-ASSY REAR BUMPER LH	NOT NECESSARY	\$195.44	\$0.00
1	REAR BUMPER LOWER COVER GARNISH G5	BROKEN	\$963.63	\$963.63
2	TAIL LAMP ASSY (UPPER) G5 @\$942.90	NOT NECESSARY	\$1,885.80	\$0.00
2	TAIL LAMP ASSY LOWER G5 @\$860.58	NOT NECESSARY	\$1,721.16	\$0.00
2	TAIL LAMP QUARTER PANEL @\$302.40	NOT NECESSARY	\$604.80	\$0.00
1	REAR END PANEL GARNISH COVER	NOT NECESSARY	\$138.90	\$0.00
2	TAIL LAMP SIDE COVER @\$358.40	NOT NECESSARY	\$716.80	\$0.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	\$842.94	\$0.00
1	REAR END PANEL GARNISH	NOT NECESSARY	\$294.80	\$0.00
1	REAR SPARE TYRE PANEL	NOT NECESSARY	\$960.80	\$0.00
1	REAR SPARE TYRE CUSHION (FLR BOARD CENTRE)	NOT NECESSARY	\$668.90	\$0.00
1	REAR FIBER TOOL BOX TRIM	NOT NECESSARY	\$557.20	\$0.00
1	SPARE TYRE LOCK NUT	NOT NECESSARY	\$123.76	\$0.00
1	REAR EXHAUST PIPE RH	NOT NECESSARY	\$1,628.76	\$0.00
1	REAR EXHAUST PIPE HANGER	NOT NECESSARY	\$56.98	\$0.00
1	REAR EXHAUST PIPE INSULATOR	NOT NECESSARY	\$440.44	\$0.00
1	REAR WINDSCREEN GLASS W/MOULDING	NOT NECESSARY	\$2,489.62	\$0.00
1	REAR WINDSCREEN SEALANT	NECESSARY	\$64.40	\$64.40
	LESS 20.00 / 25.00% DISCOUNT		(\$6,409.03)	(\$1,763.36)
			\$25,636.10	\$5,290.08
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR TRUNK LOWER W/S MOULDING (SN)	NOT NECESSARY	\$180.00	\$0.00
1	REAR LOWER W/S SEALANT (SN)	NECESSARY	\$46.00	\$46.00
1	REAR NO PLATE WITH TRIM COVER (SN)	NOT NECESSARY	\$140.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR TRUNK LID APPS STICKER (SN)	NECESSARY	\$56.00	\$56.00
1	REAR TRUNK LID COMFORT & TEL NO STICKER (SN)	NECESSARY	\$84.00	\$84.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	\$189.98	\$189.98
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	\$70.00	\$50.00
			\$765.98	\$425.98
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		\$2,000.00	\$600.00
	SPRAY PAINTING CHARGE		\$1,600.00	\$700.00
	WIRING CHARGE	NOT NECESSARY	\$100.00	\$0.00
	TUFF KOTE		\$100.00	\$20.00
	TOWING CHARGE	NOT NECESSARY	\$80.00	\$0.00
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR		\$150.00	\$80.00
	REMOVE /REFIX REAR WINDSCREEN GLASD		\$240.00	\$80.00
	REMOVE/REFIX EXHAUST PIPE	NOT NECESSARY	\$80.00	\$0.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	NOT NECESSARY	\$550.00	\$0.00
			\$4,900.00	\$1,480.00
GRAND TOTAL			\$31,302.08	\$7,196.06
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$5,750.00
Report Ref No: CD/CTI24070237/Dua3q2				

ABT

ANG BRYAN TANI

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.


PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G



PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G



PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G



PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G



PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G



PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G



PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G



PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G



PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G



PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G



PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G



PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G



PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G



PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 15 of 17)

PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G



PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G



PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G



PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G



PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G



PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G



PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SHC 3808G

