

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CS/AIG24070239/ANP3E2  
**Date:** 04/02/2025REFERENCE

|                   |                |                  |            |                        |
|-------------------|----------------|------------------|------------|------------------------|
| Insured/Claimant: | CHOW WAI THONG | Policy No:       | 7210150861 |                        |
| Date of Loss:     | 13/07/2024     | Nature of Claim: | OD         | Claim No: 6553600301SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                              |             |                   |
|-----------------------------|----------------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SNE898J</b>                               |             |                   |
| Make & Model:               | AUDI Q3, 1.5 SB TFSI S TRONIC (LED REAR) (A) | Engine No:  | CZDC54183         |
| Reg. Date:                  | 16/12/2021 (Man. Year: 2021)                 | Chassis No: | WAUZZZF31N1038709 |
| Colour:                     | Blue                                         | Odometer:   | 45578 km          |
| Engine Capacity:            | 1395 cc                                      |             |                   |
| Market Value/New Car Price: | S\$160,000.00                                |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>            |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 215/65 R17   | Rear Tyre Size:  | 215/65 R17   |
| Front Left Side:  | Pirelli 6 mm | Rear Left Side:  | Pirelli 6 mm |
| Front Right Side: | Pirelli 6 mm | Rear Right Side: | Pirelli 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 29,514.00         | 10,382.56         | 19,131.44         | 64.82         |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 10,787.00         | 5,752.00          | 5,035.00          | 46.68         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>40,301.00</b>  | <b>16,134.56</b>  | <b>24,166.44</b>  | <b>59.96</b>  |
| <b>+ GST 9.00/9.00% (S\$)</b> | 3,627.09          | 1,452.11          | 2,174.98          | 59.96         |
| <b>Nett Amount (S\$)</b>      | <b>43,928.09</b>  | <b>17,586.67</b>  | <b>26,341.42</b>  | <b>59.96</b>  |

INSPECTION

|                             |            |               |                                   |
|-----------------------------|------------|---------------|-----------------------------------|
| Date of Assignment:         | 15/07/2024 |               | Premium Automobiles Pte Ltd (UBI) |
| Date Inspected:             | 18/07/2024 | Inspected At: | 55 Ubi Road 1<br>Singapore 408699 |
| Estimated Period of Repair: | 5.0 days   |               |                                   |

**Adjuster:** ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                                          | Condition     | Repairer's  | Amount       |
|-----|-----|----------|------------------------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                                        | Deformed      | 1,784.00 FS | *1,426.80 FS |
| 2   | 1   |          | *FRONT BUMPER FIXING PARTS                           | Not Necessary | 463.00 FS   | *- FS        |
| 3   | 1   |          | *FRONT BUMPER CLOSING ELEMENT - LH                   | Not Necessary | 74.00 FS    | *- FS        |
| 4   | 1   |          | *FRONT BUMPER TRIM - MANHATTAN GREY                  | Not Necessary | 443.00 FS   | *- FS        |
| 5   | 1   |          | *FRONT BUMPER TRIM - CENTER                          | Not Necessary | 272.00 FS   | *- FS        |
| 6   | 1   |          | *FRONT PARKING AID SENSOR SUPPORT - LH               | Not Necessary | 32.00 FS    | *- FS        |
| 7   | 1   |          | *FRONT BUMPER CLOSING ELEMENT                        | Not Necessary | 238.00 FS   | *- FS        |
| 8   | 1   |          | *FRONT BUMPER SPOILER                                | Deformed      | 956.00 FS   | *764.40 FS   |
| 9   | 1   |          | *FRONT BUMPER LOWER BRACKET - LH                     | Not Necessary | 27.00 FS    | *- FS        |
| 10  | 1   |          | *FRONT BUMPER AIR GUIDE GRILLE - LH                  | Cut           | 192.00 FS   | *153.60 FS   |
| 11  | 1   |          | *FRONT PARKING AID SENSOR SUPPORT - LH               | Not Necessary | 32.00 FS    | *- FS        |
| 12  | 1   |          | *FRONT PARKING AID SENSOR                            | Not Necessary | 286.00 FS   | *- FS        |
| 13  | 4   |          | *FRONT PARKING AID SENSOR SEAL RING                  | Not Necessary | 11.00 FS    | *- FS        |
| 14  | 1   |          | *RADIATOR GRILLE                                     | Not Necessary | 2,367.00 FS | *- FS        |
| 15  | 1   |          | *RADIATOR GRILLE STRIKER PLATE                       | Not Necessary | 303.00 FS   | *- FS        |
| 16  | 1   |          | *RADIATOR GRILLE COVER                               | Not Necessary | 303.00 FS   | *- FS        |
| 17  | 1   |          | *LED HEADLIGHT - LH                                  | Cracked       | 6,696.00 FS | *5,356.80 FS |
| 18  | 1   |          | *LED HEADLIGHT SPACER - LH                           | Necessary     | 50.00 FS    | *39.84 FS    |
| 19  | 1   |          | *LED HEADLIGHT POWER MODULE                          | Not Necessary | 904.00 FS   | *- FS        |
| 20  | 1   |          | *LED HEADLIGHT MOUNTING - LH                         | Not Necessary | 147.00 FS   | *- FS        |
| 21  | 1   |          | *LIFT CYLINDER - LH                                  | Not Necessary | 244.00 FS   | *- FS        |
| 22  | 1   |          | *LIFT CYLINDER HOSE - LH                             | Not Necessary | 102.00 FS   | *- FS        |
| 23  | 1   |          | *FRONT FENDER - LH                                   | Buckled       | 1,537.00 FS | *1,229.60 FS |
| 24  | 1   |          | *FRONT FENDER ATTACHMENT PARTS - LH                  | Not Necessary | 74.00 FS    | *- FS        |
| 25  | 1   |          | *FRONT FENDER BRACE - LH                             | Bent          | 127.00 FS   | *101.60 FS   |
| 26  | 1   |          | *FRONT FENDER BRACKET - LH                           | Bent          | 58.00 FS    | *46.32 FS    |
| 27  | 1   |          | *FRONT FENDER CLOSING ELEMENT - LH                   | Not Necessary | 42.00 FS    | *- FS        |
| 28  | 1   |          | *FRONT FENDER DAMPER - LH UPPER                      | Not Necessary | 40.00 FS    | *- FS        |
| 29  | 1   |          | *FRONT FENDER SEAL - LH                              | Not Necessary | 45.00 FS    | *- FS        |
| 30  | 1   |          | *FRONT WHEEL HOUSING LINER - LH                      | Not Necessary | 289.00 FS   | *- FS        |
| 31  | 1   |          | *FRONT WHEEL HOUSING LINER ATTACHMENT - LH           | Not Necessary | 111.00 FS   | *- FS        |
| 32  | 2   |          | *FRONT WHEEL ARCH COVER - LH / RH                    | Necessary     | 1,278.00 FS | *1,022.40 FS |
| 33  | 1   |          | *BONNET                                              | Not Necessary | 3,746.00 FS | *- FS        |
| 34  | 1   |          | *BONNET ATTACHMENT PARTS                             | Not Necessary | 321.00 FS   | *- FS        |
| 35  | 2   |          | *BONNET STRIKER - LH / RH                            | Not Necessary | 260.00 FS   | *- FS        |
| 36  | 2   |          | *BONNET HINGE - LH / RH                              | Not Necessary | 210.00 FS   | *- FS        |
| 37  | 1   |          | *BONNET IMPACT PROTECTION - CENTER                   | Not Necessary | 36.00 FS    | *- FS        |
| 38  | 1   |          | *BONNET LID LOCK                                     | Not Necessary | 246.00 FS   | *- FS        |
| 39  | 1   |          | *WING MIRROR MOUNT - LH                              | Not Necessary | 2,560.00 FS | *- FS        |
| 40  | 1   |          | *WING MIRROR GLASS - LH                              | Not Necessary | 1,038.00 FS | *- FS        |
| 41  | 1   |          | *WING MIRROR CAP - LH                                | Repair        | 269.00 FS   | *- FS        |
| 42  | 1   |          | *FRONT DOOR COVER - LH                               | Repair        | 438.00 FS   | *- FS        |
| 43  | 1   |          | *SUNDRIES                                            | Not Necessary | 500.00 FS   | *- FS        |
| 44  | 1   |          | *FRONT NO PLATE                                      | Not Necessary | 60.00 FS    | *- FS        |
| 45  | 1   |          | *FRONT BUMPER TRIM - LH (MANHATTAN GREY)             | Cut           | 204.00 FS   | *162.80 FS   |
| 46  | 1   |          | *HEADLIGHT COMPENSATING PIECE LHS<br>(SUPPLEMENTARY) | Necessary     | 50.00 FS    | *39.84 FS    |
| 47  | 1   |          | *GUIDE SECTION LHS<br>(SUPPLEMENTARY)                | Necessary     | 49.00 FS    | *38.56 FS    |

F=Franchise part. S=SpcNett.

**Total Parts (S\$) 29,514.00 10,382.56**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                                                                                                | Lab.Type | Repairer's       | Amount          |
|---------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------------|-----------------|
| <b>Labour Items</b>             |                                                                                                                                                                            |          |                  |                 |
| 1                               | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID                                  | New      | 480.00           | 480.00          |
| 2                               | TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE                                                                                                         | New      | 400.00           | 250.00          |
| 3                               | TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND INSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR                                      | New      | 280.00           | 280.00          |
| 4                               | TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED                      | New      | 3,600.00         | 1,000.00        |
| 5                               | TO RESPRAY FRONT BUMPER, FRONT BUMPER SPOILER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR, BOTH FRONT WHEEL ARCH TRIMS, LHS FRONT DOOR LOWER COVER AND LHS WING MIRROR COVER | New      | 5,700.00         | 3,450.00        |
| 6                               | TO SUPPLY AND RE-APPLY STONE GUARD FILM FOR HEADLIGHT                                                                                                                      | New      | 35.00            | 0.00            |
| 7                               | TO CARRY OUT DIAGNOSTIC CHECK                                                                                                                                              | New      | 292.00           | 292.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                                                                            |          | <b>10,787.00</b> | <b>5,752.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >