

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG24070239/ANP3E2**Date:** 04/02/2025REFERENCE

Insured/Claimant:	CHOW WAI THONG	Policy No:	7210150861	
Date of Loss:	13/07/2024	Nature of Claim:	OD	Claim No: 6553600301SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNE898J		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17") (A)	Engine No:	CZDC54183
Reg. Date:	16/12/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF31N1038709
Colour:	Blue	Odometer:	45578 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$160,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,514.00	10,382.56	19,131.44	64.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,787.00	5,752.00	5,035.00	46.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	40,301.00	16,134.56	24,166.44	59.96
+ GST 9.00/9.00% (\$\$)	3,627.09	1,452.11	2,174.98	59.96
Nett Amount (\$\$)	43,928.09	17,586.67	26,341.42	59.96

INSPECTION

Date of Assignment:	15/07/2024		Premium Automobiles Pte Ltd (UBI)
Date Inspected:	18/07/2024	Inspected At:	55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,784.00 FS	*1,426.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	463.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	74.00 FS	*- FS
4	1		*FRONT BUMPER TRIM - MANHATTAN GREY	Not Necessary	443.00 FS	*- FS
5	1		*FRONT BUMPER TRIM - CENTER	Not Necessary	272.00 FS	*- FS
6	1		*FRONT PARKING AID SENSOR SUPPORT - LH	Not Necessary	32.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	238.00 FS	*- FS
8	1		*FRONT BUMPER SPOILER	Deformed	956.00 FS	*764.40 FS
9	1		*FRONT BUMPER LOWER BRACKET - LH	Not Necessary	27.00 FS	*- FS
10	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Cut	192.00 FS	*153.60 FS
11	1		*FRONT PARKING AID SENSOR SUPPORT - LH	Not Necessary	32.00 FS	*- FS
12	1		*FRONT PARKING AID SENSOR	Not Necessary	286.00 FS	*- FS
13	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	11.00 FS	*- FS
14	1		*RADIATOR GRILLE	Not Necessary	2,367.00 FS	*- FS
15	1		*RADIATOR GRILLE STRIKER PLATE	Not Necessary	303.00 FS	*- FS
16	1		*RADIATOR GRILLE COVER	Not Necessary	303.00 FS	*- FS
17	1		*LED HEADLIGHT - LH	Cracked	6,696.00 FS	*5,356.80 FS
18	1		*LED HEADLIGHT SPACER - LH	Necessary	50.00 FS	*39.84 FS
19	1		*LED HEADLIGHT POWER MODULE	Not Necessary	904.00 FS	*- FS
20	1		*LED HEADLIGHT MOUNTING - LH	Not Necessary	147.00 FS	*- FS
21	1		*LIFT CYLINDER - LH	Not Necessary	244.00 FS	*- FS
22	1		*LIFT CYLINDER HOSE - LH	Not Necessary	102.00 FS	*- FS
23	1		*FRONT FENDER - LH	Buckled	1,537.00 FS	*1,229.60 FS
24	1		*FRONT FENDER ATTACHMENT PARTS - LH	Not Necessary	74.00 FS	*- FS
25	1		*FRONT FENDER BRACE - LH	Bent	127.00 FS	*101.60 FS
26	1		*FRONT FENDER BRACKET - LH	Bent	58.00 FS	*46.32 FS
27	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	42.00 FS	*- FS
28	1		*FRONT FENDER DAMPER - LH UPPER	Not Necessary	40.00 FS	*- FS
29	1		*FRONT FENDER SEAL - LH	Not Necessary	45.00 FS	*- FS
30	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	289.00 FS	*- FS
31	1		*FRONT WHEEL HOUSING LINER ATTACHMENT - LH	Not Necessary	111.00 FS	*- FS
32	2		*FRONT WHEEL ARCH COVER - LH / RH	Necessary	1,278.00 FS	*1,022.40 FS
33	1		*BONNET	Not Necessary	3,746.00 FS	*- FS
34	1		*BONNET ATTACHMENT PARTS	Not Necessary	321.00 FS	*- FS
35	2		*BONNET STRIKER - LH / RH	Not Necessary	260.00 FS	*- FS
36	2		*BONNET HINGE - LH / RH	Not Necessary	210.00 FS	*- FS
37	1		*BONNET IMPACT PROTECTION - CENTER	Not Necessary	36.00 FS	*- FS
38	1		*BONNET LID LOCK	Not Necessary	246.00 FS	*- FS
39	1		*WING MIRROR MOUNT - LH	Not Necessary	2,560.00 FS	*- FS
40	1		*WING MIRROR GLASS - LH	Not Necessary	1,038.00 FS	*- FS
41	1		*WING MIRROR CAP - LH	Repair	269.00 FS	*- FS
42	1		*FRONT DOOR COVER - LH	Repair	438.00 FS	*- FS
43	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS
44	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
45	1		*FRONT BUMPER TRIM - LH (MANHATTAN GREY)	Cut	204.00 FS	*162.80 FS
46	1		*HEADLIGHT COMPENSATING PIECE LHS (SUPPLEMENTARY)	Necessary	50.00 FS	*39.84 FS
47	1		*GUIDE SECTION LHS (SUPPLEMENTARY)	Necessary	49.00 FS	*38.56 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **29,514.00** **10,382.56**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND INSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR	New	280.00	280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,600.00	1,000.00
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER SPOILER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR, BOTH FRONT WHEEL ARCH TRIMS, LHS FRONT DOOR LOWER COVER AND LHS WING MIRROR COVER	New	5,700.00	3,450.00
6	TO SUPPLY AND RE-APPLY STONE GUARD FILM FOR HEADLIGHT	New	35.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$\$)			10,787.00	5,752.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >