

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24070240/KPA3Q2
Date: 03/04/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002618_001
Claimant Vehicle No : SNK1422K Insured Vehicle No : SNE7329P
Date of Loss: 15/07/2024 Nature of Claim: TP Claim No: MFL2024D0008397

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNK1422K
Make & Model: HONDA ODYSSEY E-HEV, 2.0 ABSOLUTE 7 SEATER (A) Engine No: LFA2149190
Reg. Date: 22/03/2023 (Man. Year: 2021) Chassis No: RC41309190
Colour: Metallic Black Odometer: 112470 km
Engine Capacity: 1993 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17
Front Left Side: LAUFENN 7 mm Rear Left Side: LAUFENN 7 mm
Front Right Side: LAUFENN 7 mm Rear Right Side: LAUFENN 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,365.76	3,528.40	2,837.36	44.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,740.00	2,320.00	420.00	15.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,105.76	5,848.40	3,257.36	35.77
+ GST 9.00/9.00% (S\$)	819.52	526.36	293.16	35.77
Nett Amount (S\$)	9,925.28	6,374.76	3,550.52	35.77
+ Loss of Use (8.0 x S\$80.00/day) (S\$)		640.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		7,042.01		

INSPECTION

Date of Assignment: 15/07/2024
Date Inspected: 16/07/2024 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761
Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jan 2025)
Parts:	M1-MPV	HONDA ODYSSEY E-HEV 2.0 ABSOLUTE 7 SEATER (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNK1422K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,328.60 FL	*1,328.60 FL
2	1		*TAILGATE EMBLEM ODYSSEY	Necessary	49.70 FL	*49.70 FL
3	1		*TAILGATE EMBLEM ABSOLUTE	Necessary	68.50 FL	*68.50 FL
4	1		*TAILGATE EMBLEM E:HEV	Necessary	70.50 FL	*70.50 FL
5	1		*TAILGATE INNER RUBBER	Dented / Distorted	145.80 FL	*145.80 FL
6	1		*TAILGATE INNER LOCK	Dented	210.90 FL	*210.90 FL
7	1		*REAR BUMPER	Bent	1,270.50 FL	*1,270.50 FL
8	6		*REAR BUMPER CLIP	Necessary	23.40 FL	*23.40 FL
9	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	140.30 FL	*140.30 FL
10	1		*REAR END PANEL OUTER	Repair	604.70 FL	*- FL
11	1		*REAR END PANEL INNER TOP GARNISH	Dented	188.60 FL	*188.60 FL
12	1		*REAR SMART KEY SENSOR	Dented	88.70 FL	*88.70 FL
13	1		*REAR BUZZER SENSOR	Dented	85.00 FL	*85.00 FL
14	2		*REAR CENTRE REVERSE SENSOR	Scratched	590.00 FL	*590.00 FL
15	1		*SET REAR REVERSE SENSOR WIRE HARNESS	Serviceable	1,401.00 FL	*- FL
16	1		*REAR RH FENDER INNER GARNISH	Serviceable	649.80 FL	*- FL
17	1		*REAR SPARE TYRE COMPARTMENT	Repair	791.20 FL	*- FL
18	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
19	2		*REAR COMPARTMENT COATING	Necessary	160.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,907.20	4,380.50
- List Item Discount on L Items 20.00/20.00% (S\$)	1,541.44	852.10
Total Parts (S\$)	6,365.76	3,528.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	100.00	100.00
2	REMOVE & REFIX REAR BUMPER ASSY ,TAILGATE & ATTACHMENTS REAR LOCK ASSY ,REFLECTORS TOP SPOILER ,TO RENEW REAR END PANEL ,REAR SPARE TYRE COMPARTMENT KNOCKING & REPAIR RH CHASSIS & REALIGN THE SAME	New	1,200.00	1,000.00
3	REMOVE & REFIX SEAT ,CARPET ,GARNISH ETC	New	80.00	80.00
4	PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT REAR END PANEL ,REAR BUMPER ,TAILGATE REAR RH FENDER & ALL AFFECTED AREAS	New	1,200.00	1,000.00
5	REMOVE & REFIX SMART KEY SENSOR ,BUZZER SENSOR ,REVERSE CAMERA & REVERSE SENSOR & RESET SYSTEM	New	100.00	80.00
6	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (\$\$)			2,740.00	2,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >