

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III24060056/UVH3E2

Date: 12/07/2024

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549_04
Claimant Vehicle No :	GBJ4658A	Insured Vehicle No :	YQ1876Y
Date of Loss:	16/05/2024	Nature of Claim:	TP
		Claim No:	MFL2024D0006312

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ4658A	Engine No:	K9KE628D665199
Make & Model:	NISSAN NV200, 1.5 MT (M)	Chassis No:	VSKYBAM20Z0177460
Reg. Date:	27/04/2019 (Man. Year: 2019)	Odometer:	87186 km
Colour:	Silver		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Goodride 5 mm	Rear Left Side:	Goodride 5 mm
Front Right Side:	Goodride 5 mm	Rear Right Side:	Goodride 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,704.01	3,177.26	20,526.75	86.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,410.00	1,210.00	3,200.00	72.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,114.01	4,387.26	23,726.75	84.39
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	28,114.01	3,500.00	24,614.01	87.55
+ GST 9.00/9.00% (S\$)	2,530.26	315.00	2,215.26	87.55
Nett Amount (S\$)	30,644.27	3,815.00	26,829.27	87.55

INSPECTION

Date of Assignment:	12/06/2024	
Date Inspected:	18/06/2024	Inspected At: HUP LIAN HUAT ENGINEERING WORKS (HQ) 39 DEFU LANE 9 Singapore 539278
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Jul 2024)	
Parts:	N/A	NISSAN NV200 1.5 MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ4658A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent / Dented	1,443.45 FN	*846.20 FN
2	1		*FRONT BONNET BUMPER	No such part	573.00 FN	*- FN
3	2		*FRONT BONNET HINGE - LH / RH	Not Necessary	194.40 FN	*- FN
4	1		*FRONT BONNET LOCK ASSY	Twisted	87.10 FN	*87.10 FN
5	1		*FRONT BONNET LOCK STAY	Not Necessary	93.44 FN	*- FN
6	1		*FRONT BONNET INSULATION PAD	Not Necessary	179.55 FN	*- FN
7	6		*FRONT BONNET INSULATION PAD CLIP	Not Necessary	54.00 FN	*- FN
8	1		*FRONT BONNET ROD SUPPORT	Not Necessary	234.00 FN	*- FN
9	1		*FRONT BONNET GROMMET SUPPORT ROD	Not Necessary	18.00 FN	*- FN
10	1		*FRONT BUMPER	Distorted	2,465.55 FN	*541.20 FN
11	2		*FRONT BUMPER SIDE BRACKET - LH / RH	Not Necessary	138.00 FN	*- FN
12	2		*FRONT BUMPER FASCIA FINISHER - LH / RH	No such part	323.70 FN	*- FN
13	1		*FRONT BUMPER ENERGY ABSORBER	Torn	495.90 FN	*326.50 FN
14	1		*FRONT BUMPER REINFORCEMENT	Repair	1,265.25 FN	*- FN
15	2		*FRONT HEADLAMP LOWER GARNISHS	Torn	1,490.40 FN	*732.00 FN
16	1		*FRONT BUMPER LOWER APRON BRACKET	No such part	437.10 FN	*- FN
17	1		*FRONT GRILLE	Cracked	595.50 FN	*366.00 FN
18	10		*FRONT GRILLE CLIPS	Not Necessary	80.00 FN	*- FN
19	1		*FRONT GRILLE NISSAN LOGO	Scratched	108.30 FN	*102.50 FN
20	1		*FRONT RADIATOR GRILLE MOULDING ASSY	No such part	283.50 FN	*- FN
21	1		*FRONT HEADLAMP ASSY - LH / RH	N/S Not Necessary /O/S Cracked	1,793.70 FN	*489.90 FN
22	2		*FRONT HEADLAMP SOCKET - LH / RH	Not Necessary	96.30 FN	*- FN
23	2		*FRONT HEADLAMP PANEL - LH / RH	Repair	225.00 FN	*- FN
24	2		*FRONT FOG LAMP - LH / RH	Not Necessary	669.00 FN	*- FN
25	2		*FRONT FOG LAMP GARNISH - LH / RH	Not Necessary	907.30 FN	*- FN
26	1		*RADIATOR CORE SUPPORT UPPER	Repair	1,371.00 FN	*- FN
27	2		*RADIATOR CORE SUPPORT UPPER - LH / RH	Not Necessary	192.00 FN	*- FN
28	2		*RADIATOR CORE SIDE SUPPORT - LH / RH	Not Necessary	196.00 FN	*- FN
29	1		*RADIATOR CORE LOWER SUPPORT ASSY	Not Necessary	832.50 FN	*- FN
30	6		*RADIATOR CORE SUPPORT CLIPS	Not Necessary	60.00 FN	*- FN
31	1		*FRONT AIR GUIDE UPPER	Not Necessary	92.10 FN	*- FN
32	1		*FRONT AIR GUIDE LOWER	Not Necessary	92.10 FN	*- FN
33	2		*FRONT AIR GUIDE - LH / RH	Not Necessary	186.20 FN	*- FN
34	1		*FRONT CENTER AIR BAG SENSOR	Not Necessary	658.35 FN	*- FN
35	1		*FRONT CENTER AIR BAG SENSOR BRACKET	Not Necessary	72.00 FN	*- FN
36	1		*OIL PRESSURE SWITCH ASSY	Not Necessary	81.15 FN	*- FN
37	1		*ELECTRIC HIGH HORN ASSY	Not Necessary	167.55 FN	*- FN
38	1		*WINDSHIELD WASHER TANK ASSY	Not Necessary	436.35 FN	*- FN
39	1		*WASHER PUMP ASSY	Not Necessary	259.50 FN	*- FN
40	3		*WASHER HOSE	Not Necessary	121.50 FN	*- FN
41	1		*RADIATOR ASSY	Not Necessary	1,199.55 FN	*- FN
42	1		*RADIATOR UPPER HOSE	Not Necessary	216.30 FN	*- FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*RADIATOR LOWER HOSE	Not Necessary	186.00 FN	*- FN
44	4		*RADIATOR HOSE CLIPS	Not Necessary	40.00 FN	*- FN
45	2		*RADIATOR RUBBER MOUNTING UPPER	Not Necessary	52.80 FN	*- FN
46	2		*RADIATOR RUBBER MOUNTING LOWER	Not Necessary	55.80 FN	*- FN
47	1		*RADIATOR SHROUD ASSY	Not Necessary	364.35 FN	*- FN
48	1		*RADIATOR FAN MOTOR RESISTANCE	Not Necessary	234.30 FN	*- FN
49	1		*RADIATOR FAN & MOTOR ASSY	Not Necessary	1,036.65 FN	*- FN
50	1		*RADIATOR RESERVOIR TANK ASSY	Not Necessary	160.65 FN	*- FN
51	1		*RADIATOR RESERVOIR TANK CAP	Not Necessary	33.60 FN	*- FN
52	1		*AIRCOND COMPRESSOR ASSY	Not Necessary	1,620.60 FN	*- FN
53	1		*AIRCOND CONDENSOR	Not Necessary	981.00 FN	*- FN
54	1		*TURBO FRONT HOSE	Not Necessary	290.10 FN	*- FN
55	1		*AIR CLEANER FRONT AIR DUST HOSE	Not Necessary	220.50 FN	*- FN
56	1		*FRONT NUMBER PLATE	Bent	80.00 FS	*35.00 FS
57	1		*FRONT NUMBER PLATE BRACKET	Not fitted	50.00 FS	*- FS
58	1		*AIRCOND DRIER	Not Necessary	431.40 FN	*- FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	26,323.34	3,526.40
- Nett Item Discount on N Items 10.00/10.00% (S\$)	2,619.33	349.14
Total Parts (S\$)	23,704.01	3,177.26

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT AIRCOND CONDENSOR, PIPE, HOSE & TOP UP GAS	New	180.00	0.00
2	LABOUR TO REMOVE & REFIT RADIATOR, HOSE, MOTOR, FAN, ETC	New	200.00	0.00
3	LABOUR TO REMOVE & REFIT HEADLAMP, FOG LAMP & REFOCUS LIGHT	New	100.00	30.00
4	LABOUR TO REMOVE & REFIT FRONT WIRING, HOSE, PIPE, GARNISH TO CARRY OUT REPAIR JOBS	New	150.00	0.00
5	LABOUR CHARGE TO CUT & WELD & DISMANTLE & REMOVE & REFIT ALL ABOVE PARTS	New	1,800.00	500.00
6	LABOUR TO RUST PROOFING AT ACCIDENT AFFECTED AREA	New	480.00	30.00
7	TO SPRAY & PAINTING AT ACCIDENT AFFECTED AREA	New	1,500.00	650.00
Gross Labour Cost (\$\$)			4,410.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >