7/12/24, 9:11 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III24060056/UVH3E2

Date: 12/07/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_04

Claimant Vehicle

One GBJ4658A

Insured Vehicle No: YQ1876Y

Date of Loss: 16/05/2024 Nature of Claim: TP Claim No: MFL2024D0006312

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBJ4658A

 Make & Model:
 NISSAN NV200, 1.5 MT (M)
 Engine No:
 K9KE628D665199

 Reg. Date:
 27/04/2019 (Man. Year: 2019)
 Chassis No:
 VSKYBAM20Z0177460

Colour: Silver Odometer: 87186 km

Engine Capacity: 1461 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14
Front Left Side: Goodride 5 mm Rear Left Side: Goodride 5 mm
Front Right Side: Goodride 5 mm
Rear Right Side: Goodride 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		23,704.01	3,177.26	20,526.75	86.60
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,410.00	1,210.00	3,200.00	72.56
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	28,114.01	4,387.26	23,726.75	84.39
	Approved Total (Overridden) (S\$)		3,500.00		
	(S\$)	28,114.01	3,500.00	24,614.01	87.55
	+ GST 9.00/9.00% (S\$)	2,530.26	315.00	2,215.26	87.55
	Nett Amount (S\$)	30,644.27	3,815.00	26,829.27	87.55

INSPECTION

Date of Assignment: 12/06/2024

NO.38 DEFU LANE 9 SINGAPORE 539278

Date Inspected: 18/06/2024 Inspected At: REPAIRER: HUP LIAN HUAT ENGINEERING WORKS

(HQ)

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

7/12/24, 9:11 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 08 Jul 2024)

Parts: N/A NISSAN NV200 1.5 MT (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBJ4658A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particula	ars	Condition	Repairer's	Amount
1	1	*FRONT	BONNET	Bent / Dented	1,443.45 FN	*846.20 FN
2	1	*FRONT	BONNET BUMPER	No such part	573.00 FN	*- FN
3	2	*FRONT	BONNET HINGE - LH / RH	Not Necessary	194.40 FN	*- FN
4	1	*FRONT	BONNET LOCK ASSY	Twisted	87.10 FN	*87.10 FN
5	1	*FRONT	BONNET LOCK STAY	Not Necessary	93.44 FN	*- FN
6	1	*FRONT	BONNET INSULATION PAD	Not Necessary	179.55 FN	*- FN
7	6	*FRONT	BONNET INSULATION PAD CLIP	Not Necessary	54.00 FN	*- FN
8	1	*FRONT	BONNET ROD SUPPORT	Not Necessary	234.00 FN	*- FN
9	1	*FRONT	BONNET GROMMENT SUPPORT ROD	Not Necessary	18.00 FN	*- FN
10	1	*FRONT	BUMPER	Distorted	2,465.55 FN	*541.20 FN
11	2	*FRONT	BUMPER SIDE BRACKET - LH / RH	Not Necessary	138.00 FN	*- FN
12	2	*FRONT	BUMPER FASCIA FINISHER - LH / RH	No such part	323.70 FN	*- FN
13	1	*FRONT	BUMPER ENERGY ABSORBER	Torn	495.90 FN	*326.50 FN
14	1	*FRONT	BUMPER REINFORCEMENT	Repair	1,265.25 FN	*- FN
15	2	*FRONT	HEADLAMP LOWER GARNISHS	Torn	1,490.40 FN	*732.00 FN
16	1	*FRONT	BUMPER LOWER APRON BRACKET	No such part	437.10 FN	*- FN
17	1	*FRONT	GRILLE	Cracked	595.50 FN	*366.00 FN
18	10	*FRONT	GRILLE CLIPS	Not Necessary	80.00 FN	*- FN
19	1	*FRONT	GRILLE NISSAN LOGO	Scratched	108.30 FN	*102.50 FN
20	1	*FRONT	RADIATOR GRILLE MOULDING ASSY	No such part	283.50 FN	*- FN
21	1	*FRONT	HEADLAMP ASSY - LH / RH	N/S Not Necessary /O/S Cracked	1,793.70 FN	*489.90 FN
22	2	*FRONT	HEADLAMP SOCKET - LH / RH	Not Necessary	96.30 FN	*- FN
23	2	*FRONT	HEADLAMP PANEL - LH / RH	Repair	225.00 FN	*- FN
24	2	*FRONT	FOG LAMP - LH / RH	Not Necessary	669.00 FN	*- FN
25	2	*FRONT	FOG LAMP GARNISH - LH / RH	Not Necessary	907.30 FN	*- FN
26	1	*RADIAT	OR CORE SUPPORT UPPER	Repair	1,371.00 FN	*- FN
27	2	*RADIAT	OR CORE SUPPORT UPPER - LH / RH	Not Necessary	192.00 FN	*- FN
28	2	*RADIAT	OR CORE SIDE SUPPORT - LH / RH	Not Necessary	196.00 FN	*- FN
29	1	*RADIAT	OR CORE LOWER SUPPORT ASSY	Not Necessary	832.50 FN	*- FN
30	6	*RADIAT	OR CORE SUPPORT CLIPS	Not Necessary	60.00 FN	*- FN
31	1	*FRONT	AIR GUIDE UPPER	Not Necessary	92.10 FN	*- FN
32	1	*FRONT	AIR GUIDE LOWER	Not Necessary	92.10 FN	*- FN
33	2	*FRONT	AIR GUIDE - LH / RH	Not Necessary	186.20 FN	*- FN
34	1	*FRONT	CENTER AIR BAG SENSOR	Not Necessary	658.35 FN	*- FN
35	1	*FRONT	CENTER AIR BAG SENSOR BRACKET	Not Necessary	72.00 FN	*- FN
36	1	*OIL PRE	ESSURE SWITCH ASSY	Not Necessary	81.15 FN	*- FN
37	1	*ELECTF	RIC HIGH HORN ASSY	Not Necessary	167.55 FN	*- FN
38	1	*WINDSI	HIELD WASHER TANK ASSY	Not Necessary	436.35 FN	*- FN
39	1	*WASHE	R PUMP ASSY	Not Necessary	259.50 FN	*- FN
40	3	*WASHE	R HOSE	Not Necessary	121.50 FN	*- FN
41	1	*RADIAT	OR ASSY	Not Necessary	1,199.55 FN	*- FN
42	1	*RADIAT	OR UPPER HOSE	Not Necessary	216.30 FN	*- FN
			Report was unsubmitted d	luring this print-out.		

No.	Qty	Part No.	Particulars	Condition		Repairer's	Amount
43	1		*RADIATOR LOWER HOSE	Not Necessary		186.00 FN	*- FN
44	4		*RADIATOR HOSE CLIPS	Not Necessary		40.00 FN	*- FN
45	2		*RADIATOR RUBBER MOUNTING UPPER	Not Necessary		52.80 FN	*- FN
46	2		*RADIATOR RUBBER MOUNTING LOWER	Not Necessary		55.80 FN	*- FN
47	1		*RADIATOR SHROUD ASSY	Not Necessary		364.35 FN	*- FN
48	1		*RADIATOR FAN MOTOR RESISTANCE	Not Necessary		234.30 FN	*- FN
49	1		*RADIATOR FAN & MOTOR ASSY	Not Necessary		1,036.65 FN	*- FN
50	1		*RADIATOR RESERVOIR TANK ASSY	Not Necessary		160.65 FN	*- FN
51	1		*RADIATOR RESERVOIR TANK CAP	Not Necessary		33.60 FN	*- FN
52	1		*AIRCOND COMPRESSOR ASSY	Not Necessary		1,620.60 FN	*- FN
53	1		*AIRCOND CONDENSOR	Not Necessary		981.00 FN	*- FN
54	1		*TURBO FRONT HOSE	Not Necessary		290.10 FN	*- FN
55	1		*AIR CLEANER FRONT AIR DUST HOSE	Not Necessary		220.50 FN	*- FN
56	1		*FRONT NUMBER PLATE	Bent		80.00 FS	*35.00 FS
57	1		*FRONT NUMBER PLATE BRACKET	Not fitted		50.00 FS	*- FS
58	1		*AIRCOND DRIER	Not Necessary		431.40 FN	*- FN
F=Fra	anchise	part. S=Spc	:Nett. N=NettItemDisc.		Sub Total (S\$)	26.323.34	3,526.40

- Nett Item Discount on N Items 10.00/10.00% (S\$) 2,619.33 349.14 **Total Parts (S\$)** 23,704.01 3,177.26

Report was unsubmitted during this print-out.

7/12/24, 9:11 AM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR TO REMOVE & REFIT AIRCOND CONDENSOR, PIPE, HOSE & TOP UP GAS	New	180.00	0.00
2	LABOUR TO REMOVE & REFIT RADIATOR, HOSE, MOTOR, FAN, ETC	New	200.00	0.00
3	LABOUR TO REMOVE & REFIT HEADLAMP, FOG LAMP & REFOCUS LIGHT	New	100.00	30.00
4	LABOUR TO REMOVE & REFIT FRONT WIRING, HOSE, PIPE, GARNISH TO CARRY OUT REPAIR JOBS) New	150.00	0.00
5	LABOUR CHARGE TO CUT & WELD & DISMANTLE & REMOVE & REFIT ALL ABOVE PARTS	New	1,800.00	500.00
6	LABOUR TO RUST PROOFING AT ACCIDENT AFFECTED AREA	New	480.00	30.00
7	TO SPRAY & PAINTING AT ACCIDENT AFFECTED AREA	New	1,500.00	650.00
	Gross Labour	r Cost (S\$)	4,410.00	1,210.00
	Report was unsubmitted during this pri	nt-out.		

< END OF ESTIMATES >