

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS24070247/KVP3E2  
**Date:** 08/08/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
<b>Claimant Vehicle No :</b>	GBG5010C	<b>Insured Vehicle No :</b>	SLN9940L
Date of Loss:	12/07/2024	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBG5010C</b>	Engine No:	DFS219720
Make & Model:	VOLKSWAGEN CADDY TDI, 2.0 D (M)	Chassis No:	WV1ZZZ2KZXH162112
Reg. Date:	22/08/2017 (Man. Year: 2017)	Odometer:	143905 km
Colour:	Red		
Engine Capacity:	1968 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,583.68	3,583.68	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	940.00	800.00	140.00	14.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,523.68</b>	<b>4,383.68</b>	<b>140.00</b>	<b>3.09</b>
<b>+ GST 9.00/9.00% (S\$)</b>	407.13	394.53	12.60	3.09
<b>Nett Amount (S\$)</b>	<b>4,930.81</b>	<b>4,778.21</b>	<b>152.60</b>	<b>3.09</b>

INSPECTION

Date of Assignment:	17/07/2024	
Date Inspected:	19/07/2024	Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	3.0 days	

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 08 Aug 2024)	
Parts:	N/A	VOLKSWAGEN CADDY TDI 2.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG5010C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONTBUMPER	Buckled / Cracked	1,380.28 FL	*1,380.28 FL
2	1		*FRONT BUMPER RETAINER LH	Cracked	158.42 FL	*158.42 FL
3	1		*FRONT FENDER LH	Bent	1,193.84 FL	*1,193.84 FL
4	1		*FRONT FENDER INNER SHIELD LH	Cracked	199.47 FL	*199.47 FL
5	1		*FRONT HEADLAMP LH	Cracked	1,049.86 FL	*1,049.86 FL
					Sub Total (S\$)	3,981.87
					- List Item Discount on L Items 10.00/10.00% (S\$)	398.19
					Total Parts (S\$)	3,583.68

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	COMPUTERISED WHEEL ALIGNMENT	New	60.00	0.00
2	TO KNOCK DENTS ON FRONT FENDER BRACKET LH AND RENEW PARTS	New	400.00	360.00
3	TO SPRAY PAINT	New	400.00	360.00
4	TO CHECK / CLEAR FAULT CODES AFTER REPAIR	New	80.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>940.00</b>	<b>800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >