

REF:

ASSIGNMENT

From: _____ Date: _____

Estim: ~~Estim~~ _____OD / ~~TP~~ / TP RES / OD RES / EVA / INV / MVTo In ~~Vehicle~~ No: _____at W/O ~~Estim~~ / m/s _____

ci _____

Insured: _____

Policy No _____

Claim's No _____

Sum ENSURE _____ Excess: _____

(Client's Record)

Make of Veh _____

(Policy Condition)

Remark: Veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMN184A Yr Regn: 2019, JulyType: M. Car / M. Cycle / Bus / Ven / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Sienta Hybrid C.D. 1496Colour: White A/C: Insured / Std / NI / NASp. Reading: 178824 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NHP1707071436Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60R15R: 185/60R15

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. _____

D.O.I. 16/07/24Survey held at BifrostDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Claim

COE Expiry :

Estimate given during : Yes (✓)

1st Survey : No ()

MV : 89KPV : 28KNett : 61K

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: _____

1)

☐

Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Inve (\$

Survey Fee:

Transportation:

B + RS \$

Photos

Others

Report Format:

Report Form: F.R.P. (C)

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Vehicle number: SMN184A

Make & Model: Toyota Sienta Hybrid

Chassis number: NHP170701436

No.	Description of spare parts	Qty	Amount S\$	
1	Tailgate	1	\$ 1,786.10	+
2	Tailgate centre emblem	1	\$ 86.60	+
3	Tailgate glass RH rubber moulding	1	\$ 55.00	+
4	Tailgate glass LH rubber moulding	1	\$ 55.00	+
5	Tailgate windscreen glass upper rubber moulding	1	\$ 55.00	+
6	Tailgate windscreen glass lower rubber moulding	1	\$ 55.00	+
7	Tailgate RH lamp	1	\$ 303.10	+
8	Tailgate RH lamp sponge gasket	1	\$ 45.60	+
9	Tailgate lock	1	\$ 599.10	+
10	Tailgate lock catch	1	\$ 45.60	+
11	Tailgate weatherstrip	1	\$ 476.50	+
12	Tailgate inner trim	1	\$ 489.30	+
13	Tailgate inner trim clips	1set	\$ 70.00	+
14	Rear bumper	1	\$ 506.10	+
15	Rear bumper clips	1set	\$ 75.00	+
16	Rear bumper RH side reflector garnish	1	\$ 165.20	+
17	Rear bumper RH side reflector	1	\$ 77.20	+
18	Rear bumper centre garnish	1	\$ 243.00	+
19	Rear bumper RH retainer	1	\$ 95.40	+
20	Rear bumper LH retainer	1	\$ 95.40	+
21	End panel (outer)	1	\$ 588.10	+
22	End panel (inner)	1	\$ 944.10	+
23	End panel garnish	1	\$ 291.80	+
24	End panel garnish clips	1set	\$ 70.00	+
25	RH taillamp assy	1	\$ 516.80	+
26	RH taillamp sponge gasket	1	\$ 55.90	+
27	RH taillamp panel	1	\$ 167.40	+
28	RH taillamp lock clips	1set	\$ 35.00	+
29	Rear RH fender	1	\$ 1,508.90	+
30	Rear RH fender glass with rubber moulding	1	\$ 799.30	+
31	Rear RH fender splash shield	1	\$ 129.10	+
32	Rear RH fender splash shield clips	1set	\$ 50.00	+
33	Rear RH fender inner trim board	1	\$ 709.80	+
34	Rear RH fender inner trim board clips	1set	\$ 70.00	+
35	Rear RH sport rim (Original)	1	\$ 936.00	+

36	Rear RH wheel bearing	1	\$	403.10	✓
37	Rear RH shock absorber	1	\$	189.00	+
38	Rear axle beam	1	\$	2,033.00	+
39	Rear Door RH	1	\$	1,931.50	✓
40	Rear Door Protector RH	1	\$	152.60	✓

\$ 13,090.40
 Parts less 25% \$ 3,272.60
 Total: \$ 9,817.80

No.	Special Nett Items	Qty	Amount S\$
1	Rear RH tyre 2 of	1	\$ 500.00
2	Brake fluid 1 m	1	\$ 70.00
3	Tailgate windscreen glass sealant 2	1	\$ 80.00
4	Tailgate windscreen glass inner seal	1	\$ 60.00
5	End panel joint sealant (outer) 1 of	1	\$ 80.00
6	End panel joint sealant (inner) 1 m	1	\$ 80.00
7	RH taillamp panel joint sealant	1	\$ 40.00
8	Rear RH fender joint sealant	1	\$ 80.00

Total: \$ 990.00

No.	Labour and painting	Amount S\$	
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,600.00	2w
2	Spray painting on affected areas and panels	\$ 1,400.00	2w
3	Check wiring and lighting system on affected areas	\$ 60.00	✗
4	Apply rust coating chemical on affected areas and panels	\$ 70.00	✗
5	Remove and reinstall tailgate windscreen glass to assist repair	\$ 220.00	✗
6	Transfer and replace tailgate inner mechanism to new tailgate	\$ 180.00	✗
7	Remove and replace tailgate reverse camera to assist repair	\$ 100.00	✗
8	Remove and replace rear bumper reverse sensors to assist repair	\$ 100.00	✗
9	Remove and replace rear inner trims, garnish and boards to assist repair	\$ 300.00	✗

10	Remove and reinstall roof lining, seats and carpet to assist repair	\$	450.00	+
11	Test drive and adjust wheel alignment system	\$	120.00	+
12	Remove and replace rear undercarriage parts to assist repair	\$	500.00	+

Total: \$ 3,500.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 9,817.80

Special Nett: \$ 990.00

Labour: \$ 3,500.00

Total: \$ 14,307.80

Adrian Cj

L/S 16/07/24.

03 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: