

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	MS FIRST CAPITAL INSURANCE LTD		Ref:	CS3/FCI24070253/Enp3e2	
	16 RAFFLES QUAY		Date:	18/07/2024	
	#42-01 HONG LEONG BUILDING		Code:	FCI2	
1.	Policy Particulars :- PRE-REPAIR SURVEY				
	Insured Veh.	SHA 7868S	Veh. Inspected	GBG 5782H	
	Policy No.	D-24101861MFCT	Coverage	0	
	Claim No.	D24006118MFCT	Excess	\$0.00	
	Assign From	BETTY	Assign Date	16/07/2024	
2. Vehicle Details					
	Make & Model	TOYOTA HIACE	C.C	2982	
	Engine No.	1KD2751758	Year of Reg.	14/09/2017	
	Chassis No.	JTFHT02PX00233783	Colour	BLACK	
	Odometer	192372 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s) RIMS: STANDARD ALLOY RIM				
3.	3. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	195 R15C	TOURADOR	5	
	L/H Front Tyre	195 R15C	TOURADOR	5	
	R/H Rear Tyre	195 R15C	TOURADOR	5	
	L/H Rear Tyre	195 R15C	TOURADOR	5	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5.	General Information				
	Accident Date Survey held at	10/07/2024	Inspection Date	16/07/2024 (01:06PM)	
	Survey field at	YAP LEE MOTOR BLK 1 KAKI BUKIT AVE 6 #01-26 AUTOBAY@KAKI BUKIT SINGAPORE 417883			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$46,000.00 (EST) E)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000					
5b. Estimate Days of Repair					
ESTI	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				

## CTY

## CHEN TSUE YEE