

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24070254/KQP3E2
Date: 11/10/2024**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1003393163
Claimant Vehicle No :	SKQ3905A	Insured Vehicle No :	SKT9909J
Date of Loss:	13/07/2024	Nature of Claim:	TP
		Claim No:	366919

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ3905A	Engine No:	PE20579560
Make & Model:	MAZDA 6, 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A)	Chassis No:	JM6GJ1071F0147312
Reg. Date:	26/11/2014 (Man. Year: 2014)	Odometer:	134779 km
Colour:	Metallic Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,737.31	4,753.06	11,984.25	71.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,200.00	2,020.00	2,180.00	51.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,937.31	6,773.06	14,164.25	67.65
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	20,937.31	5,000.00	15,937.31	76.12

INSPECTION

Date of Assignment:	16/07/2024	BLK 5034 ANG MO KIO INDUSTRIAL PARK 2 #01-341
Date Inspected:	16/07/2024 Inspected At:	SINGAPORE 569537
Estimated Period of Repair:	7.0 days	REPAIRER: JD MOTORSPORTS PTE LTD

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jul 2024)
Parts:	143	MAZDA 6 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ3905A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Mtg Cracked	2,172.20 F	*1,120.17 FL
2	1		*REAR BUMPER RH SIDE RETAINER	Distorted	67.95 F	*67.95 FL
3	1		*REAR RH FENDER	Bent	2,392.05 F	*1,254.40 FL
4	1		*REAR RH INNER SHIELD	Cracked	324.70 F	*118.20 FL
5	1		*REAR RH FENDER INNER PANEL	Repair	2,238.90 F	*- FL
6	1		*REAR RH FENDER INNER TRIM BOARD	Serviceable	1,038.00 F	*- FL
7	1		*REAR RH DOOR	Bent / Warped	2,424.60 F	*1,312.10 FL
8	1		*REAR RH DOOR INNER LOCK	Repair	438.80 F	*- FL
9	1		*REAR RH DOOR CATCH HOOK	Repair	37.45 F	*- FL
10	1		*REAR RH DOOR INNER PANEL BOARD	Serviceable	685.30 F	*- FL
11	1		*REAR RH DOOR WEATHERSTRIP	Serviceable	314.75 F	*- FL
12	1		*REAR RH WHEEL BEARING	Bent	566.10 F	*280.50 FL
13	1		*REAR RH KNUCKLER	Bent	913.45 F	*482.30 FL
14	1		*REAR RH LOWER ARM	Serviceable	203.30 F	*- FL
15	1		*REAR RH UPPER ARM	Serviceable	352.10 F	*- FL
16	1		*REAR RH TRAILING ARM	Serviceable	406.60 F	*- FL
17	1		*REAR RH ABSORBER	Bent	699.76 F	*308.20 FL
18	1		*REAR RH SUSPENSION ARM	Serviceable	203.30 F	*- FL
19	5		*REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
20	8		*REAR RH INNER SHIELD CLIP	Necessary	48.00 FS	*48.00 FS
21	1		*REAR RH RIM	Dented	850.00 FS	*680.00 FS
22	1		*REAR RH TYRES	Serviceable	250.00 FS	*- FS
23	1		*WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,737.31	5,741.82
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	988.76
Total Parts (\$\$)	16,737.31	4,753.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	New	1,500.00	800.00
2	TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA	New	1,000.00	660.00
3	TO SUPPLY LABOUR TO REMOVE AND REFIX REAR WINDSCREEN	New	250.00	120.00
4	TO SUPPLY LABOUR TO DISMANTLE AND REFIX UNDER CARRIAGE	New	300.00	120.00
5	TO SUPPLY LABOUR TO DISMANTLE REAR DOOR FACILITATE THE DOOR	New	250.00	60.00
6	TO SUPPLY LABOUR TO DISMANTLE REAR FENDER INNER PANEL UPHOLSTERY	New	250.00	100.00
7	TO SUPPLY LABOUR TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
8	TO SUPPLY LABOUR TO CONDUCT WHEEL BALANCING	New	50.00	20.00
9	TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL	New	250.00	60.00
10	TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	New	200.00	20.00
Gross Labour Cost (\$\$)			4,200.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >