

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070255/AUA3Q2**Date:** 13/12/2024REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7220042233-02
Claimant Vehicle No : SMF3518T **Insured Vehicle No :** GBG679G
 Date of Loss: 16/07/2024 Nature of Claim: TP Claim No: 9029995157SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF3518T**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 Standard (A) Engine No: 1ZR0C55877
 Reg. Date: 05/11/2018 (Man. Year: 2018) Chassis No: MR053REH604592210
 Colour: Grey Odometer: 110528 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,172.77	4,624.62	5,548.15	54.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	1,460.00	1,590.00	52.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,222.77	6,084.62	7,138.15	53.98
Approved Total (Overridden) (S\$)		4,800.00		
Nett Amount (S\$)	13,222.77	4,800.00	8,422.77	63.70
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		5,127.25		

INSPECTION

Date of Assignment: 17/07/2024
 Date Inspected: 17/07/2024 Inspected At: Fong Motors (HQ)
 1 Kaki Bukit Ave 6 #01-45, Autobay@ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR NUMBER PLATE LAMP	Not Necessary	174.00 FL	*- FL
2	1		*BOOTLID	Dented	859.60 FL	*859.60 FL
3	1		*BOOTLID INSULATOR	Not Necessary	176.40 FL	*- FL
4	2		*BOOTLID LAMP	Cut	684.00 FL	*684.00 FL
5	1		*BOOTLID OUTER MOULDING (CHROME)	Cracked	426.00 FL	*426.00 FL
6	1		*BOOTLID DETECTOR	Not Necessary	385.00 FL	*- FL
7	1		*BOOTLID LOGO	Necessary	85.00 FL	*85.00 FL
8	1		*BOOTLID EMBLEM COROLLA	Necessary	70.00 FL	*70.00 FL
9	1		*BOOTLID EMBLEM ALTIS	Necessary	70.00 FL	*70.00 FL
10	2		*BOOT LID HINGE	Not Necessary	140.00 FL	*- FL
11	1		*BOOTLID TOP LOCK	Damaged	318.10 FL	*318.10 FL
12	1		*BOOTLID LOWER LOCK	Not Necessary	20.00 FL	*- FL
13	1		*BOOTLID WEATHERSTRIP	Cut	195.00 FL	*195.00 FL
14	1		*REAR BOOTLID OUTER SWITCH BUTTON	Not Necessary	328.00 FL	*- FL
15	2		*TAILLAMP	Cut	930.00 FL	*930.00 FL
16	2		*TAILLAMP LOWER BRACKET	Not Necessary	230.20 FL	*- FL
17	2		*TAILLAMP PANEL	Not Necessary	396.00 FL	*- FL
18	2		*REAR FENDER INNER TRIM	Not Necessary	701.20 FL	*- FL
19	1		*REAR END PANEL	Repair	695.30 FL	*- FL
20	1		*REAR END PANEL TOP GARNISH	Deformed	250.10 FL	*250.10 FL
21	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	271.10 FL	*- FL
22	1		*REAR FLOOR PANEL	Repair	940.20 FL	*- FL
23	1		*REAR BUMPER	Deformed	581.90 FL	*581.90 FL
24	1		*REAR BUMPER REINFORCEMENT	Dented	386.60 FL	*386.60 FL
25	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	174.60 FL	*- FL
26	2		*REAR BUMPER REFLECTOR	Not Necessary	150.20 FL	*- FL
27	2		*REVERSE SENSOR	Damaged	622.20 FL	*622.20 FL
28	1		*REVERSE CAMERA	Damaged	740.02 FS	*450.00 FS
29	2		*REVERSE SENSOR RING	Necessary	21.00 FL	*21.00 FL
30	1		*REVERSE SENSOR WIRE HARNESS	Not Necessary	437.50 FL	*- FL
31	1		*REAR SPARE TYRE BOLT	Not Necessary	40.10 FL	*- FL
32	1		*REAR EXHAUST PIPE	Not Necessary	781.10 FL	*- FL
33	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	38.90 FL	*- FL
34	1		*REAR EXHAUST PIPE GASKET	Not Necessary	35.60 FL	*- FL
35	1		*REAR EXHAUST PIPE HEAT SHIELD	Not Necessary	122.10 FL	*- FL
36	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
37	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
38	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
39	1		*SET BOOTLID INSULATOR CLIP	Not Necessary	30.00 FS	*- FS
40	2		*SET TAILLAMP CLIPS	Not Necessary	30.00 FS	*- FS
41	2		*TAILLAMP PANEL SEALANT	Not Necessary	60.00 FS	*- FS
42	2		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
43	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
44	1		*REAR END PANEL INSULATION SEAL	Not Necessary	60.00 FS	*- FS
45	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	200.00 FS	*- FS
46	1		*REAR FLOOR PANEL SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,107.02	5,999.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,934.25	1,374.88
Total Parts (\$\$)	10,172.77	4,624.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	600.00
2	TO SPRAY PAINT	New	1,000.00	600.00
3	TUFF COAT	New	150.00	30.00
4	WIRING CHECK	New	50.00	30.00
5	REMOVE UPHOLSTERY	New	150.00	40.00
6	REMOVE REVERSE SENSOR	New	100.00	50.00
7	REMOVE REAR CAMERA	New	100.00	50.00
8	TRANSFER BOOTLID MECHANISM	New	150.00	60.00
9	REMOVE REAR EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (\$\$)			3,050.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >