

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070256/AMA3Q2**Date:** 09/12/2024**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900231461
Claimant Vehicle No : GBJ7773E **Insured Vehicle No :** GBG6148H
 Date of Loss: 13/07/2024 Nature of Claim: TP Claim No: 0784918534SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ7773E**
 Make & Model: NISSAN NV200, 1.6 VANETTE DX (A) Engine No: HR16147984D
 Reg. Date: 02/08/2019 (Man. Year: 2019) Chassis No: VM20135575
 Colour: White Odometer: 107225 km
 Engine Capacity: 1597 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R14 Rear Tyre Size: 185/65 R14
 Front Left Side: ZEXTOUR 6 mm Rear Left Side: ZEXTOUR 6 mm
 Front Right Side: ZEXTOUR 6 mm Rear Right Side: ZEXTOUR 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,575.70	4,760.20	4,815.50	50.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,160.00	1,630.00	530.00	24.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,735.70	6,390.20	5,345.50	45.55
Approved Total (Overridden) (S\$)		5,100.00		
(S\$)	11,735.70	5,100.00	6,635.70	56.54
+ GST 9.00/9.00% (S\$)	1,056.21	459.00	597.21	56.54
Nett Amount (S\$)	12,791.91	5,559.00	7,232.91	56.54
+ Car Rental (9.0 x S\$105.00/day) (S\$)		945.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		6,531.25		
Global Sum Settlement (S\$)		6,520.00		

INSPECTION

Date of Assignment: 16/07/2024
 Date Inspected: 16/07/2024 Inspected At: KAI MOTOR TRADING (HQ)
 Estimated Period of Repair: 7.0 days BLK 3007 UBI ROAD 1, #01-440
 Singapore 408701

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT COVER	Dented	2,200.00 FN	*2,031.00 FN
2	2		*REAR BOOT COVER HINGE	Not Necessary	172.00 FN	*- FN
3	1		*REAR BOOT LOCK	Damaged	366.00 FN	*287.00 FN
4	1		*REAR BOOT RUBBER	Not Necessary	115.00 FN	*- FN
5	1		*REAR BOOT INNER TRIM	Deformed	288.00 FN	*213.00 FN
6	1		*REAR BOOT NISSAN LOGO	Necessary	97.00 FN	*97.00 FN
7	1		*REAR BOOT NV 200 LOGO	Necessary	145.00 FN	*145.00 FN
8	1		*REAR BOOT HANDLE	Not Necessary	115.00 FN	*- FN
9	1		*REAR BOOT GARNISH	Not Necessary	388.00 FN	*- FN
10	2		*TAIL LAMP LH & RH	Not Necessary	854.00 FN	*- FN
11	1		*REAR BUMPER	Deformed	665.00 FN	*665.00 FN
12	1		*REAR END PANEL OUTER	Dented	227.00 FN	*227.00 FN
13	1		*REAR END PANEL INNER	Repair	668.00 FN	*- FN
14	2		*REAR SIDE RETAINER LH & RH	Not Necessary	118.00 FN	*- FN
15	1		*REAR WIPER MOTOR	Damaged	448.00 FN	*448.00 FN
16	1		*FRONT BUMPER	Deformed	665.00 FN	*665.00 FN
17	1		*FRONT BUMPER SPONGE	Not Necessary	388.00 FN	*- FN
18	2		*FRONT BUMPER SIDE RETAINER LH & RH	Not Necessary	64.00 FN	*- FN
19	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	1,170.00 FN	*- FN
20	2		*REVERSE SENSORS	Damaged	576.00 FS	*200.00 FS
21	1		*REAR WINDSCREEN INNER SEAL	Necessary	226.00 FS	*120.00 FS
22	1		*REAR WINDSCREEN SEALANT	Necessary	226.00 FS	*60.00 FS
23	20		*FRONT & REAR BUMPER CLIPS	Necessary	200.00 FS	*30.00 FS
24	1		*FRONT AND REAR NUMBER PLATE	Front Damaged	110.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	10,491.00	5,238.00
- Nett Item Discount on N Items 10.00/10.00% (S\$)	915.30	477.80
Total Parts (S\$)	9,575.70	4,760.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGE PARTS PANEL BEAT WHERE NECESSARY	New	850.00	800.00
2	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTE PORTION	New	900.00	600.00
3	TO REMOVE AND REFIX REAR WINDSCREEN	New	180.00	120.00
4	TO REMOVE REVERSE SENSOR	New	150.00	50.00
5	TO CHECK WIRING FUNCTIONS	New	80.00	60.00
Gross Labour Cost (\$\$)			2,160.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >