

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING

SINGAPORE 048581

INV No. : SAC2400931

INV Date : 11-10-2024

Reference CD/FCI24070260/Uma3

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. FBV 9635U
Insured Veh. SHD 7285H
Claim No. D24006134MFCT/CTPL/TPD2/KT
Policy No. D-24101861MFCT
Accident Date 10/07/2024
Inspection Date 16/07/2024

Description	Amount
Third Party Express Settlement	350.00
Sub-Total	350.00
GST (9%)	31.50
Grand Total	381.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Ref: CD/FCI24070260/Uma3

Date: 11/10/2024

Code: FCI2

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SHD 7285H	Veh. Inspected	FBV 9635U
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24006134MFCT/CTPL/TPD2/KT	Excess	\$0.00
Assign From	KAREN TAN	Assign Date	15/07/2024

2. Vehicle Details

Make & Model	YAMAHA T155	C.C	155
Engine No.	G3R9E002576	Year of Reg.	15/01/2024
Chassis No.	RLCUG1610PY002575	Colour	WHITE
Odometer	4932 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	FRT 90-80-17 REAR 120-70-17	PIRELLI	8
L/H Front Tyre	FRT 90-80-17 REAR 120-70-17	PIRELLI	8
R/H Rear Tyre	FRT 90-80-17 REAR 120-70-17	PIRELLI	8
L/H Rear Tyre	FRT 90-80-17 REAR 120-70-17	PIRELLI	8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S & N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/07/2024	Inspection Date	16/07/2024
Survey held at	ERZAT LEE MOTOR TRADING PTE LTD 25 KAKI BUKIT ROAD 4, #03-37, SYNERGY @ KB, SINGAPORE 417800		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBV 9635U

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SETFORK	SERVICEABLE	\$350.00	\$0.00
1	FORK UNDER BRACKET	NOT NECESSARY	\$280.00	\$0.00
1	STEERING CONE	NOT NECESSARY	\$180.00	\$0.00
1	FRONT TYRES SHAFT	SERVICEABLE	\$120.00	\$0.00
1	FRONT FENDER BRACKET R	SERVICEABLE	\$80.00	\$0.00
1	FRONT FENDER L	CUT	\$80.00	\$80.00
1	HANDLE BAR	BENT	\$280.00	\$160.00
1	HANDLE BALANCER	CUT / TWISTED	\$150.00	\$90.00
1	BRAKE LEVER	TO REPAIR SEE LABOUR	\$100.00	\$0.00
1	CLUTH LEVER	CUT	\$100.00	\$95.00
1	SET MIRROR	BROKEN	\$150.00	\$150.00
1	IU UNIT	NOT NECESSARY	\$155.80	\$0.00
1	IU BRACKET	TO REPAIR SEE LABOUR	\$50.00	\$0.00
1	FRONT PANEL COVER	CUT	\$120.00	\$120.00
1	INNER PANEL	CUT	\$180.00	\$180.00
1	EXHAUST COVER	CUT	\$150.00	\$115.00
1	EXHAUST CAP	CUT	\$120.00	\$80.00
1	SET FRONT FOOTREST	TWISTED	\$150.00	\$100.00
1	FRONT FOOTREST BAR	BENT	\$220.00	\$145.00
1	GEAR PEDAL	CUT	\$180.00	\$150.00
1	REAR SWING ARM	CUT	\$600.00	\$600.00
1	REAR SWING ARM COVER	CUT	\$80.00	\$60.00
1	REAR BOX	CUT	\$450.00	\$380.00
1	REAR RACK	SERVICEABLE	\$300.00	\$0.00
1	SET COVER	CRACKED	\$550.00	\$550.00
	LESS 10.00% DISCOUNT		(\$517.58)	(\$305.50)
			\$4,658.22	\$2,749.50



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE (SN)	CUT	\$18.00	\$10.00
			\$18.00	\$10.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR.INCLUSIVE OF THE REPAIR OF BRAKE LEVER AND IU BRACKET.		\$500.00	\$300.00
			\$500.00	\$300.00
GRAND TOTAL			\$5,176.22	\$3,059.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$2,400.00
Report Ref No: CD/FCI24070260/Uma3				

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U




PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U




PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U




PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U




PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U




PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 7 of 7)

PHOTOGRAPHS FOR VEHICLE NO. : FBV 9635U

