

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG24070263/AVP3M4**Date:** 07/10/2024REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7240043811		
Claimant Vehicle No :	SKN89R	Insured Vehicle No :	SFG211A		
Date of Loss:	15/07/2024	Nature of Claim:	TP	Claim No:	1467624520SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN89R	Engine No:	B4204T187542907
Make & Model:	VOLVO XC40, 2.0 T5 R-DESIGN (A)	Chassis No:	LYVXZ16ACML390499
Reg. Date:	27/10/2020 (Man. Year: 2020)	Odometer:	70502 km
Colour:	Blue		
Engine Capacity:	1969 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/50R19	Rear Tyre Size:	235/50R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,672.31	15,200.96	15,471.35	50.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,500.00	1,690.00	1,810.00	51.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,172.31	16,890.96	17,281.35	50.57
Approved Total (Overridden) (S\$)		13,500.00		
Nett Amount (S\$)	34,172.31	13,500.00	20,672.31	60.49
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	16/07/2024	
Date Inspected:	17/07/2024 Inspected At:	HUA MENG SPRAY PAINTING WORKSHOP (HQ) NO 1 KAKI BUKIT AVENUE 6, #01-61 AUTOBAY@KAKI BUKIT SINGAPORE 417883
Estimated Period of Repair:	7.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Distorted	3,118.34 FL	*2,945.00 FL
2	2		*REAR TAILGATE HINGE	Not Necessary	705.64 FL	*- FL
3	2		*REAR TAILGATE SHOCK ABSORBER	Not Necessary	2,386.48 FL	*- FL
4	1		*REAR TAILGATE UPPER LOCK	Damaged	673.21 FL	*529.00 FL
5	1		*REAR TAILGATE LOWER CATCH	Not Necessary	277.84 FL	*- FL
6	1		*REAR TAILGATE HANDLE	Damaged	588.57 FL	*328.00 FL
7	1		*REAR TAILGATE HANDLE GARNISH	Deformed	345.80 FL	*345.80 FL
8	1		*REAR TAILGATE CAMERA	Not Necessary	2,143.60 FL	*- FL
9	1		*REAR TAILGATE XC40 EMBLEM	Necessary	158.70 FL	*158.70 FL
10	1		*REAR TAILGATE T5 EMBLEM	Necessary	159.39 FL	*159.39 FL
11	1		*REAR TAILGATE AWD R DESIGN EMBLEM	Necessary	159.39 FL	*159.39 FL
12	1		*REAR TAILGATE VOLVO EMBLEM	Necessary	159.39 FL	*159.39 FL
13	1		*REAR TAILGATE WEATHER STRIP	Cut	327.52 FL	*327.52 FL
14	1		*REAR END PANEL	Dented	2,044.35 FL	*1,418.00 FL
15	1		*REAR END PANEL TOP GARNISH	Not Necessary	539.12 FL	*- FL
16	1		*REAR LAMP	O/S Cut	2,182.82 FL	*1,096.41 FL
17	2		*REAR LAMP LOWER COVER	Not Necessary	1,121.71 FL	*- FL
18	1		*REAR BUMPER	Deformed	2,227.20 FL	*1,910.00 FL
19	2		*REAR BUMPER SIDE REFLECTOR	Cracked	537.05 FL	*220.00 FL
20	1		*REAR BUMPER REVERSE SENSOR 4PCS	Damaged (2Pcs Only)	1,364.80 FL	*640.00 FL
21	1		*REAR BUMPER TOWING HOOK COVER	Deformed	103.73 FL	*103.73 FL
22	1		*REAR BUMPER REINFORCEMENT	Dented	2,241.92 FL	*1,080.00 FL
23	1		*REAR BUMPER LOWER LIP	Deformed	3,071.99 FL	*950.00 FL
24	2		*REAR BUMPER BRACKET	Not Necessary	225.86 FL	*- FL
25	1		*REAR BUMPER CLIPS	Necessary	11.50 FL	*11.50 FL
26	1		*REAR NUMBER PLATE LAMP	Cracked	139.84 FL	*139.84 FL
27	1		*REAR EXHAUST PIPE	Not Necessary	537.85 FL	*- FL
28	1		*REAR EXHAUST PIPE COVER	Crumpled	340.74 FL	*215.00 FL
29	1		*REAR SPARE TYRE TOP BOARD	Deformed	435.39 FL	*435.39 FL
30	1		*REAR KICKING SENSOR	Damaged	765.72 FL	*425.00 FL
31	1		*REAR TAILGATE INNER BOARD	Cracked	1,972.02 FL	*1,259.00 FL
32	1		*REAR BUMPER UNDERCOVER	Deformed	481.00 FL	*481.00 FL
33	1		*REAR BUMPER UNDERCOVER CLIPS	Necessary	30.00 FL	*30.00 FL
34	1		*REAR KICKING SENSOR BRACKET	Cracked	295.00 FL	*295.00 FL
35	1		*REAR NUMBER PLATE	Cut	100.00 FN	*30.00 F
36	1		*REAR NUMBER PLATE HOLDER	Deformed	50.00 FN	*30.00 F
37	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
38	1		*REAR END PANEL INNER SEALANT	Necessary	200.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	32,273.48	15,992.06
- List Item Discount on L Items 5.00/5.00% (\$\$)	1,593.67	791.10
- Nett Item Discount on N Items 5.00/0.00% (\$\$)	7.50	0.00
Total Parts (\$\$)	30,672.31	15,200.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE + REINSTALL REAR WINDSCREEN	New	200.00	120.00
2	REMOVE + REINSTALL REVERSE SENSOR	New	200.00	50.00
3	REMOVE + REINSTALL BOOTLID INNER GARNISH	New	200.00	60.00
4	REMOVE + REINSTALL EXHAUST PIPE	New	300.00	0.00
5	REMOVE, REPLACE + REPAIR CONSISTENT TO THE ACCIDENT	New	1,400.00	800.00
6	RESPRAY PAINTING	New	1,100.00	600.00
7	TUFF KOTE	New	100.00	60.00
Gross Labour Cost (\$\$)			3,500.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >