

HUA MENG SPRAY PAINTING WORKSHOP

1, KAKI BUKIT AVENUE 6, BLK C #01-61 / 01-34, SINGAPORE 417883

AUTOBAY @ KAKI BUKIT

TEL : 6747 8064 , 6746 5519 / 9666 9680 FAX : 6743 4896

ESTIMATE

T? A19.
Veron.

VEHICLE NO : SKN 89 R

CHASSIS NO : LYVXZ16ACML390499

MAKE / MODEL : VOLVO XC40

ACCIDENT DATE : 15.07.2024

NO	DESCRIPTION	QTY	AMOUNT (\$\$)
LIST ITEMS			
1	Rear tailgate <i>Distorted</i>	1	\$ 3118.34
2	Rear tailgate hinge @ \$352.82 <i>new</i>	2	\$ 705.64
3	Rear tailgate shock absorber @ \$1193.24 <i>new</i>	2	\$ 2386.48
4	Rear tailgate upper lock <i>Dist.</i>	1	\$ 673.21
5	Rear tailgate lower catch <i>new</i>	1	\$ 277.84
6	Rear tailgate inner board <i>cracked</i>	1	\$ 1972.02
7	Rear tailgate handle <i>Dist.</i>	1	\$ 588.57
8	Rear tailgate handle garnish <i>Dist.</i>	1	\$ 345.80
9	Rear tailgate camera <i>new</i>	1	\$ 2143.60
10	Rear tailgate XC40 emblem <i>free</i>	1	\$ 158.70
11	Rear tailgate T5 emblem <i>free</i>	1	\$ 159.39
12	Rear tailgate AWD R DESIGN emblem <i>free</i>	1	\$ 159.39
13	Rear tailgate VOLVO emblem <i>free</i>	1	\$ 159.39
14	Rear tailgate weather strip <i>cut</i>	1	\$ 327.52
15	Rear end panel <i>Dist.</i>	1	\$ 2044.35
16	Rear end panel top garnish <i>new</i>	1	\$ 539.12
17	Rear lamp @ \$1096.41 <i>RH cut</i>	2	\$ 2182.82
18	Rear lamp lower cover @ \$560.85 <i>new</i>	2	\$ 1121.71
19	Rear bumper <i>Dist.</i>	1	\$ 2227.20
20	Rear bumper side reflector @ \$268.52 <i>cracked</i>	2	\$ 220.537.05
21	Rear bumper reverse sensor @ \$341.20 <i>2 pieces damaged</i>	4	\$ 1364.80
22	Rear bumper towing hock cover <i>Dist.</i>	1	\$ 103.73
23	Rear bumper reinforcement <i>Dist.</i>	1	\$ 2241.92
24	Rear bumper lower lip <i>Dist.</i>	1	\$ 2071.99
25	Rear bumper bracket @ \$112.93 <i>new</i>	2	\$ 225.86
26	Rear bumper clips <i>new</i>	1	\$ 11.50
27	Rear number plate <i>cut</i>	1	\$ 100.00
28	Rear number plate holder <i>Dist.</i>	1	\$ 50.00
29	Rear number plate lamp <i>cracked</i>	1	\$ 139.84
30	Rear ethaust pipe <i>new</i>	1	\$ 537.85
31	Rear ethaust pipe cover <i>cracked</i>	1	\$ 340.74
32	Rear spare tyre top board <i>Dist.</i>	1	\$ 435.39
33	Rear kicking sensor <i>Damaged</i>	1	\$ 765.72
			\$ 31217.48
			5% LESS 20% DISC
			\$ 6243.496
			TOTAL \$ 24973.98

Rear Bumper Undercovers *Dist.* 481

Rear Bumper Undercovers Clips *new* 30

Rear Kicking Sensor Bracket *cracked* 295

15822.06

1502055

S-N: 60

HUA MENG SPRAY PAINTING WORKSHOP

1, KAKI BUKIT AVENUE 6, BLK C #01-61 / 01-34, SINGAPORE 417883

AUTOBAY @ KAKI BUKIT

TEL : 6747 8064 , 6746 5519 / 9666 9680 FAX : 6743 4896

ESTIMATE

VEHICLE NO : SKN 89 R

CHASSIS NO : LYVXZ16ACML390499

MAKE / MODEL : VOLVO XC40

ACCIDENT DATE : 15.07.2024

NO	DESCRIPTION	QTY	AMOUNT (\$\$)
LABOUR COST			
1	To supply rear windscreen sealant	1	50.00 ✓
2	To supply rear end panel inner sealant	1	200.00 60
3	Remove + reinstall rear windscreen	1	200.00 120
4	Remove + reinstall reverse sensor	1	200.00 50
5	Remove + reinstall bootlid inner garnish	1	200.00 60
6	Remove + reinstall ethaust pipe	1	300.00 x
7	Remove, replace + repair consistent to the accident	1	1400.00 800
8	Respray painting	1	1100.00 600
9	Tuff kote	1	100.00 60.
TOTAL			\$ 3750.00

1800 GRAND TOTAL \$ 28723.98

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 18890.95

4/5: 13.5k.

06 Days

13.5k