



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. : SAC2401041

INV Date : 17-10-2024

Reference CD/CTI24070265/Kma3q2

Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMS 2525K
Insured Veh. SND 8259G
Claim No. SNM24D203702
Policy No. DMHCSNA00003412400
Accident Date 26/06/2024
Inspection Date 15/07/2024

Description	Amount
Third Party Express Settlement	400.00
Sub-Total	400.00
GST (9%)	36.00
Grand Total	436.00

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER SINGAPORE 079909

Ref: CD/CTI24070265/Kma3q2

Date: 17/10/2024

Code: CTI

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SND 8259G	Veh. Inspected	SMS 2525K
Policy No.	DMHCSNA00003412400	Coverage	0
Claim No.	SNM24D203702	Excess	\$0.00
Assign From	JENNY LEW	Assign Date	16/07/2024

2. Vehicle Details

Make & Model	TOYOTA COROLLA ALTIS 1.6 AUTO	C.C	1598
Engine No.	3ZZ4956913	Year of Reg.	06/01/2010
Chassis No.	MR053ZEE106162854	Colour	METALLIC LIGHT GREEN
Odometer	187261 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	YOKOHAMA	7
L/H Front Tyre	195/65R15	YOKOHAMA	7
R/H Rear Tyre	195/65R15	YOKOHAMA	7
L/H Rear Tyre	195/65R15	YOKOHAMA	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/06/2024	Inspection Date	15/07/2024
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMS 2525K

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	BOOT LID	BENT	\$949.10	\$949.10
1	BOOT LID INNER LOCK	DENTED	\$121.10	\$121.10
1	BOOT LID 1.6 EMBLEM	NECESSARY	\$42.40	\$42.40
1	BOOT LID COROLLA EMBLEM	NECESSARY	\$53.20	\$53.20
1	BOOT LID ALTIS EMBLEM	NECESSARY	\$53.20	\$53.20
1	BOOT LID LOGO	NECESSARY	\$66.90	\$66.90
1	REAR END PANEL	BENT	\$727.70	\$727.70
1	END PANEL TOP GARNISH	DENTED	\$231.60	\$231.60
1	REAR BUMPER FASCIA	CRACKED	\$660.80	\$660.80
1	REAR BUMPER SPONGE	CRACKED	\$153.80	\$153.80
1	REAR N/S BUMPER REFLECTOR	SERVICEABLE	\$46.90	\$0.00
2	REAR BUMPER SIDE RETAINER L @\$78.70	SERVICEABLE	\$157.40	\$0.00
2	REAR BUMPER SIDE RETAINER S @\$37.60	SERVICEABLE	\$75.20	\$0.00
	LESS 25.00% DISCOUNT		(\$834.83)	(\$764.95)
			\$2,504.47	\$2,294.85

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	BOOT LID RUBBER (\$209.90) (50%) (SN)	DISTORTED / DENTED	\$157.43	\$104.95
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	\$300.00	\$200.00
1	SET REAR BUMPER CLIP (SN)	SERVICEABLE	\$30.00	\$0.00
1	REAR BUMPER NO PLATE WITH BOX(SN)	SERVICEABLE	\$50.00	\$0.00
			\$537.43	\$304.95

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS TRIM BOARD AND CARPET		\$60.00	\$60.00
	TO APPLY UNDERSEALING		\$60.00	\$60.00
	TO PUTTY AND SPRAY REPLACED PARTS		\$700.00	\$600.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS		\$600.00	\$600.00
			\$1,420.00	\$1,320.00
GRAND TOTAL			\$4,461.90	\$3,919.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$3,100.00
Report Ref No: CD/CTI24070265/Kma3q2				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SMS 2525K



PHOTOGRAPHS FOR VEHICLE NO. : SMS 2525K



PHOTOGRAPHS FOR VEHICLE NO. : SMS 2525K



PHOTOGRAPHS FOR VEHICLE NO. : SMS 2525K



PHOTOGRAPHS FOR VEHICLE NO. : SMS 2525K



PHOTOGRAPHS FOR VEHICLE NO. : SMS 2525K



PHOTOGRAPHS FOR VEHICLE NO. : SMS 2525K



PHOTOGRAPHS FOR VEHICLE NO. : SMS 2525K

