

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24070266/ANP3E2
Date: 16/08/2024**REFERENCE**

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SGH7532K	Insured Vehicle No :	GBL9763K
Date of Loss:	15/07/2024	Nature of Claim:	TP
		Claim No:	DMCF2400031H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGH7532K	Engine No:	1ZZ2603791
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100312062
Reg. Date:	21/06/2006 (Man. Year: 2006)	Odometer:	253287 km
Colour:	Black		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,909.87	6,251.80	7,658.07	55.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,940.00	1,920.00	3,020.00	61.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,849.87	8,171.80	10,678.07	56.65
Approved Total (Overridden) (S\$)		6,500.00		
Nett Amount (S\$)	18,849.87	6,500.00	12,349.87	65.52

INSPECTION

Date of Assignment:	16/07/2024	Ms Car Auto Pte Ltd (HQ)
Date Inspected:	16/07/2024 Inspected At:	8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT
Estimated Period of Repair:	7.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Aug 2024)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGH7532K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	558.90 FL	*558.90 FL
2	2		*REAR BUMPER SIDE HOLDER	Not Necessary	115.60 FL	*- FL
3	2		*REAR BUMPER IMPACT BRACKET	Dented	136.80 FL	*136.80 FL
4	1		*REAR BUMPER REFLECTOR	N/s Cracked	166.20 FL	*83.10 FL
5	1		*REAR END PANEL OUTER	Distorted	581.10 FL	*581.10 FL
6	1		*REAR END PANEL INNER	Repair	213.90 FL	*- FL
7	1		*REAR END PANEL TOP GARNISH	Deformed	326.20 FL	*326.20 FL
8	2		*TAILLAMP	Cracked	835.80 FL	*835.80 FL
9	2		*TAILLAMP LOWER BRACKET	Not Necessary	85.00 FL	*- FL
10	2		*TAILLAMP PANEL	Dented	594.20 FL	*594.20 FL
11	1		*TAILGATE	Distorted	1,272.90 FL	*1,272.90 FL
12	1		*TAILGATE LOCK	Damaged	497.10 FL	*497.10 FL
13	1		*TAILGATE WEATHERSTRIPE	Torn	276.10 FL	*276.10 FL
14	1		*TAILGATE HANDLE SWITCH	Not Necessary	158.20 FL	*- FL
15	1		*TAILGATE OUTER HROME MOULDING	Cracked	383.80 FL	*383.80 FL
16	1		*TAILGATE INNER TRIM BOARD	Cracked	485.50 FL	*485.50 FL
17	1		*TAILGATE WIPER MOTOR	Not Necessary	576.90 FL	*- FL
18	1		*TAILGATE WIPER ARM	Not Necessary	89.60 FL	*- FL
19	1		*TAILGATE GLASS	Not Necessary	1,291.80 FL	*- FL
20	1		*TAILGATE GLASS MOULDING	Necessary	140.60 FL	*140.60 FL
21	1		*TOYOTA LOGO	Necessary	74.10 FL	*74.10 FL
22	1		*FLOOR PANEL TOP BOARD	Not Necessary	535.70 FL	*- FL
23	2		*FLOOR PANEL SIDE BOARD	Not Necessary	451.00 FL	*- FL
24	2		*REAR FENDER	Repair	1,979.40 FL	*- FL
25	2		*REAR FENDER INNER TRIM BOARD	Cracked	1,476.20 FL	*1,476.20 FL
26	1		*SPARE TYRE LOCK REGULATOR	Not Necessary	388.90 FL	*- FL
27	1		*REAR DOOR	Repair	1,109.50 FL	*- FL
28	1		*REAR DOOR LOCK	Not Necessary	405.20 FL	*- FL
29	1		*REAR EXHAUST PIPE	Not Necessary	971.10 FL	*- FL
30	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	38.90 FL	*- FL
31	1		*REAR EXHAUST PIPE GASKET	Not Necessary	35.20 FL	*- FL
32	1		*REAR EXHAUST PIPE HEAT SHIELD	Not Necessary	215.10 FL	*- FL
33	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
34	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
35	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
36	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
37	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
38	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
39	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
40	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
41	1		*TAILGATE GLASS SOLAR FILM	Not Necessary	280.00 FS	*- FS
42	1		*TAILGATE CAMERA	Not Necessary	480.00 FS	*- FS
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	2		*REAR FENDER SEALANT	Not Necessary	120.00 FS	*- FS
44	2		*REAR FENDER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
45	2		*SET REAR FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*60.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$)	18,026.50
					- List Item Discount on L Items 25.00/25.00% (\$)	4,116.63
					Total Parts (\$)	13,909.87

8,182.40

1,930.60

6,251.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVE AND REFIT PARTS	New	2,000.00	700.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	800.00
3	WIRING CHECK	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	60.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE REAR UPHOLSTERY	New	150.00	60.00
7	TO TRANSFER TAILGATE FITTINGS	New	150.00	50.00
8	TO REMOVE TAILGATE GLASS	New	180.00	120.00
9	TO REMOVE REAR CAMERA	New	100.00	50.00
10	TO REMOVE REAR LH & RH FENDER GLASSES	New	160.00	0.00
11	TO TRANSFER REAR DOOR FITTINGS	New	150.00	0.00
12	TO REMOVE EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (\$\$)			4,940.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >