



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBD 1972T

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
2	TAIL LAMP @\$224.50	NOT NECESSARY	\$449.00	\$0.00
2	TAIL LAMP SUPPORT BRACKET @\$180.00	NOT NECESSARY	\$360.00	\$0.00
1	REAR NUMBER PLATE SUPPORT BRACKET	NOT NECESSARY	\$210.00	\$0.00
2	REAR NUMBER PLATE LAMP @\$59.00	NOT NECESSARY	\$118.00	\$0.00
1	CARGO BED END PANEL	TO REPAIR SEE LABOUR	\$1,274.30	\$0.00
	LESS 25.00% DISCOUNT		(\$602.83)	\$0.00
			\$1,808.47	\$0.00

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	\$50.00	\$0.00
2	REAR BACK OPEN DOOR @\$3,200.00 (SN)	DENTED	\$6,400.00	\$3,200.00
4	REAR BOX BACK DOOR HINGE @\$120.00 (SN)	NOT NECESSARY	\$480.00	\$0.00
2	REAR BOX BACK DOOR STAND HOLDER @\$40.00 (SN)	NOT NECESSARY	\$80.00	\$0.00
2	REAR BOX BACK DOOR LOCK CATCH @\$120.00 (SN)	NOT NECESSARY	\$240.00	\$0.00
2	REAR BOX BACK DOOR LOCK ROD @\$500.00 (SN)	BENT	\$1,000.00	\$600.00
2	REAR BOX BACK DOOR INNER PANEL WOODEN @\$250.00 (SN)	CRACKED	\$500.00	\$200.00
1	REAR BOX OPEN DOOR '70KM/H' (SN)	NECESSARY	\$30.00	\$15.00
1	REAR FLOOR TOP BOARD (WOODEN) (SPECIAL TYPE) (SN)	CRACKED	\$2,800.00	\$500.00
			\$11,580.00	\$4,515.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK. INCLUSIVE OF THE REPAIR OF CARGO BED END PANEL		\$1,600.00	\$400.00
	TO PUTTY, SPRAY PAINT, POLISH WAX		\$1,000.00	\$150.00
	TO SPRAY TUFF COAT	NOT NECESSARY	\$250.00	\$0.00
	WIRING, BULB CHECKING	NOT NECESSARY	\$80.00	\$0.00
	CONDUCT WATER LEAKAGE TEST	NOT NECESSARY	\$80.00	\$0.00
	TRANSFER REAR BACK DOOR MECHANISM X2	NOT NECESSARY	\$180.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	NOT NECESSARY	\$180.00	\$0.00
			\$3,370.00	\$550.00
GRAND TOTAL			\$16,758.47	\$5,065.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$4,050.00
Report Ref No: CS/INC24070269/Anh3m4				

TOTAL FOR SPARE PARTS: \$13,388.47 \$ 4,515.00
TOTAL FOR LABOUR : \$ 3,370.00 \$ 550.00
TOTAL REPAIR COST: \$16,758.47 \$ 5,065.00

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.