

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600**Our File No:** CS/ICS24070272/KQP3E2**Date:** 15/08/2024REFERENCE

Insured/Claimant: CHAN HUI CHONG,JOSEPH (CHEN HUIZHONG) Policy No: MPC24A00044600

Date of Loss: 15/07/2024

Nature of Claim: OD

Claim No: DMPC2400891H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP7935E		
Make & Model:	MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)	Engine No:	P520334832
Reg. Date:	27/01/2016 (Man. Year: 2015)	Chassis No:	JM6BM42A8G0326560
Colour:	Metallic Red	Odometer:	144413 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$25,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,146.00	2,508.00	638.00	20.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	860.00	420.00	440.00	51.16
Paintwork Labour	680.00	400.00	280.00	41.18
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,686.00	3,328.00	1,358.00	28.98
+ GST 9.00/9.00% (S\$)	421.74	299.52	122.22	28.98
Nett Amount (S\$)	5,107.74	3,627.52	1,480.22	28.98

INSPECTION

Date of Assignment: 17/07/2024

Date Inspected: 17/07/2024 Inspected At:

160 Sin Ming Drive #08-09 Sin Ming Autocity
Repairer: Vin's Motor Pte Ltd

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Aug 2024)
Parts:	143	MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP7935E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH HEADLAMP (WCP)	Broken	1,300.00 F	*1,300.00 F
2	1		*FRONT BUMPER (WCP)	Buckled/Dented	480.00 F	*480.00 F
3	1		*FRONT BUMPER RH NOZZIE GUN (WCP)	Cracked	140.00 F	*140.00 F
4	1		*FRONT BUMPER RH NOZZIE GUN COVER (WCP)	Missing	60.00 F	*60.00 F
5	1		*FRONT BUMPER RH SIGNAL LIGHT (WCP)	Serviceable	90.00 F	-
6	1		*FRONT BUMPER RH FOG LAMP (WCP)	Serviceable	200.00 F	-
7	1		*FRONT BUMPER RH FOG LAMP COVER (WCP)	Cut	30.00 F	*30.00 F
8	1		*FRONT BUMPER RH SIDE RETAINER (WCP)	Distorted	10.00 F	*10.00 F
9	1		*FRONT BUMPER REINFORCEMENT (WCP)	Repair	270.00 F	-
10	10		*FRONT BUMPER CLIPS (WCP)	Necessary	20.00 F	*20.00 F
11	1		*WIPER TANK (WCP)	Dented	60.00 F	*60.00 F
12	1		*WIPER TANK CAP (MISSING)(WCP)	Not Consistent With The Impact	20.00 F	-
13	1		*FRONT RH FENDER (WCP)	Buckled	180.00 F	*180.00 F

F=Franchise part.

Sub Total (\$)	2,860.00	2,280.00
+ Margin on L,N Items 10.00/10.00% (\$)	286.00	228.00
Total Parts (\$)	3,146.00	2,508.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO SPRAY PAINTING	New	680.00	400.00
<u>Labour Items</u>				
2	TO RESET HEADLAMP SYSTEM	New	280.00	20.00
3	TO REPAIR DAMAGES	New	580.00	400.00
Gross Labour Cost (S\$)			1,540.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >