



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三
AUTOBAY @ KAKI BUKIT
No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883
TELEPHONE: 6748 2795 FAX: 6747 2373
Registration No. 203165/00D

TP Liberty
Veron.

LKK

SJNFBAJ11U1453002

DATE: 27/07/2024 OUR REF: UAPL1688
REPAIR ESTIMATE YOUR INSURED VEHICLE NISSAN QASHQAI NO: SGP60J
NETT ITEM:-

1 REAR BUMPER ASSY <i>Deformed</i>	\$ 995.80	755
1 REAR BUMPER TOWING COVER <i>Deformed</i>	\$ 34.10	
1 REAR BUMPER INNER BLACK SPONGE <i>Cracked</i>	\$ 277.30	173
1 REAR BUMPER REINFORCEMENT <i>Repair</i>	\$ 869.40	
2 REAR BUMPER REINFORCEMENT BRACKET <i>RH Dented</i>	\$ 314.20	157.10
1 REAR BUMPER R/H REFLECTOR LAMP <i>None</i>	\$ 68.90	
2 REAR BUMPER SIDE RETAINER BRACKET <i>None</i>	\$ 120.80	
10 REAR BUMPER CLIPS <i>New</i>	\$ 50.00	30
1 REAR R/H TAILLAMP ASSY <i>New</i>	\$ 524.80	
1 REAR TAIL END PANEL <i>Dented</i>	\$ 691.60	
1 REAR R/H AIR DUCT <i>None</i>	\$ 75.10	
1 REAR R/H FENDER OUTER GARNISH <i>cracked</i>	\$ 602.30	483.
	\$ 4,624.30	
LESS 10%.....	\$ 462.43	
	\$ 4,161.87	

SPECIAL NETT:-

1 REAR REVERSE SENSOR <i>None</i>	\$ 380.00	
-----------------------------------	-----------	--

LABOUR CHARGES:-

TO DISM/REWIRE REAR DAMAGED PORTION	\$ 100.00	
TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS	\$ 1,200.00	400
TO PUTTY AND RESPRAY DAMAGED PORTION	\$ 1,000.00	400
TO SPRAY UNDERCOATING IN REPAIR	\$ 150.00	60
TO DISM/REFIX REAR SEAT, TRAY ASSY, PILLER LINING, ROOF LINING	\$ 150.00	60
	\$ 7,141.87	

920

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total: 301142

4/5: 24K

04 Days