



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

| | | |
|-------------------------------------|-------|-----------------------|
| MS LIBERTY INSURANCE PTE LTD | Ref: | CS/LIP24070275/Kqh3m4 |
| ONE RAFFLES QUAY #25-01 NORTH TOWER | Date: | 01/10/2024 |
| SINGAPORE 048583 | Code: | LIP |

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|------------|----------------|------------|
| Insured Veh. | SMZ 1102S | Veh. Inspected | GBB 7356T |
| Policy No. | - | Coverage | 0 |
| Claim No. | IVS24/1211 | Excess | \$0.00 |
| Assign From | KAHARUDIN | Assign Date | 16/07/2024 |

2. Vehicle Details

| | | | |
|-----------------|-------------------------|--------------|------------|
| Make & Model | NISSAN CABSTAR 3.0 5M/T | C.C | 2953 |
| Engine No. | ZD30235131K | Year of Reg. | 17/12/2009 |
| Chassis No. | JN1SC2F24Z0801267 | Colour | SILVER |
| Odometer | 529831 KM | Steering | IN ORDER |
| Brakes | IN ORDER | General | GOOD |
| Modification(s) | RIMS: NIL | | |

3. Conditions of Tyres

| | Size | Make | Balance (mm) |
|----------------|--------------|-----------|--------------|
| R/H Front Tyre | 195R15X8 | TRANSMATE | 7 |
| L/H Front Tyre | 195R15X8 | TRANSMATE | 7 |
| R/H Rear Tyre | 165R12X8 (D) | GAMA | 6/6 |
| L/H Rear Tyre | 165R12X8 (D) | GAMA | 6/6 |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|--|-----------------|------------|
| Accident Date | 22/06/2024 | Inspection Date | 23/07/2024 |
| Survey held at | TROPICAL SUCCESS AUTO CARE BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535. | | |

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days