



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBH 1019A

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE PANEL	NOT NECESSARY	\$196.50	\$0.00
2	REAR STOPPER PANEL @\$194.70	NOT NECESSARY	\$389.40	\$0.00
2	TAILLAMP @\$267.50	CRACKED	\$535.00	\$535.00
2	TAILLAMP PANEL @\$149.80	NOT NECESSARY	\$299.60	\$0.00
	LESS 10.00% DISCOUNT		(\$142.05)	(\$53.50)
			\$1,278.45	\$481.50

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	\$30.00	\$0.00
1	SET REVERSE SNESOR (SN)	DAMAGED	\$280.00	\$200.00
1	REAR CAMERA (SN)	DAMAGED	\$480.00	\$380.00
2	REAR STOPPER @\$40.00 (SN)	NOT NECESSARY	\$80.00	\$0.00
2	REAR DOOR @\$1,600.00 (SN)	DENTED	\$3,200.00	\$2,600.00
2	REAR DOOR LOWER HINGE @\$250.00 (SN)	NOT NECESSARY	\$500.00	\$0.00
1	REAR DOOR VERTICAL LOCK BAR (SN)	BENT	\$450.00	\$350.00
2	REAR DOOR VERTICAL LOCK BAR BRACKET @\$150.00 (SN)	BENT (1PC ONLY)	\$300.00	\$150.00
1	REAR DOOR VERTICAL LOCK BAR LOWER STAY (SN)	DAMAGED	\$120.00	\$100.00
2	REAR DOOR LOWER LOCK HOLDER @\$50.00 (SN)	NECESSARY	\$100.00	\$100.00
1	REAR DOOR LOWER ALUMINIUM PLATE (SN)	NOT NECESSARY	\$350.00	\$0.00
2	REAR DOOR SIDE PILLAR @\$1,000.00 (SN)	TO REPAIR SEE LABOUR	\$2,000.00	\$0.00
			\$7,890.00	\$3,880.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING, REMOVE AND REFIT PARTS. INCLUSIVE OF THE REPAIR OF REAR DOOR SIDE PILLAR		\$1,000.00	\$600.00
	SPRAY PAINTING TO AFFECTED AREA		\$500.00	\$200.00
	WIRING CHECK		\$50.00	\$30.00
	TO REMOVE REVERSE SENSOR		\$100.00	\$50.00
	TO REMOVE REAR CAMERA		\$100.00	\$50.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REPAIR & STRAIGHTEN REAR CHASSIS MEMBERS		\$600.00	\$250.00
			\$2,350.00	\$1,180.00
GRAND TOTAL			\$11,518.45	\$5,541.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$4,400.00
Report Ref No: CS/INC24070276/Avh3m4				

TOTAL FOR SPARE PARTS: \$ 9,168.45 \$ 4,361.50
TOTAL FOR LABOUR : \$ 2,350.00 \$ 1,180.00
TOTAL REPAIR COST: \$11,518.45 \$ 5,541.50

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.