

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG24070279/ANP3E2**Date:** 27/09/2024REFERENCE

Insured/Claimant:	SEN SUKANTI	Policy No:	2100441770	
Date of Loss:	16/07/2024	Nature of Claim:	OD	Claim No: 8545462546SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJB9768E		
Make & Model:	AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A)	Engine No:	CZC504756
Reg. Date:	23/12/2015 (Man. Year: 2015)	Chassis No:	WAUZZZ8V5G1050542
Colour:	Maroon	Odometer:	62585 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$32,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,431.00	3,012.16	7,418.84	71.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,552.00	1,702.00	2,850.00	62.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,983.00	4,714.16	10,268.84	68.54
- Excess (\$\$)	300.00	300.00	0.00	0.00
(\$\$)	14,683.00	4,414.16	10,268.84	69.94
+ GST 9.00/9.00% (\$\$)	1,321.47	397.27	924.20	69.94
Nett Amount (\$\$)	16,004.47	4,811.43	11,193.04	69.94

INSPECTION

Date of Assignment:	17/07/2024		
Date Inspected:	19/07/2024	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,670.00 FS	*2,136.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	209.00 FS	*- FS
3	2		*FRONT BUMPER LOWER COVER TRIM - LH / RH	Not Necessary	408.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	196.00 FS	*- FS
5	4		*FRONT BUMPER PULL STRAP	Not Necessary	260.00 FS	*- FS
6	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	49.00 FS	*- FS
7	1		*FRONT BUPER AIR GUIDE GRILLE - LH / RH	O/S Cut	274.00 FS	*109.60 FS
8	1		*RADIATOR GRILLE	Cut	850.00 FS	*679.60 FS
9	1		*RADIATOR STRIKER PLATE	Not Necessary	127.00 FS	*- FS
10	1		*FRONT REINFORCEMENT BEAM COVER	Not Necessary	71.00 FS	*- FS
11	1		*FRONT FOAM FILLER PIECE	Not Necessary	172.00 FS	*- FS
12	1		*FRONT REINFORCEMENT BEAM	Not Necessary	969.00 FS	*- FS
13	1		*HEADLIGHT - LH	Not Necessary	3,044.00 FS	*- FS
14	1		*LIFT CYLINDER - RH	Not Necessary	230.00 FS	*- FS
15	1		*LIFT CYLINDER HOSE	Not Necessary	233.00 FS	*- FS
16	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	78.00 FS	*- FS
17	1		*RADIATOR AIR GUIDE SEAL - RH OUTER	Not Necessary	10.00 FS	*- FS
18	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Not Necessary	21.00 FS	*- FS
19	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
20	1		*SUNDRIES	Necessary	500.00 FS	*26.96 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 10,431.00 3,012.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,750.00	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	1,800.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$)			4,552.00	1,702.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >