

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070285/UMA3Q2**Date:** 12/11/2024**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7220105209
Claimant Vehicle No : GBJ5599E **Insured Vehicle No :** SLU3583L
 Date of Loss: 17/07/2024 Nature of Claim: TP Claim No: 5414863030SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ5599E**
 Make & Model: NISSAN NV200, 1.6 DX (A) Engine No: HR16129857D
 Reg. Date: 07/12/2018 (Man. Year: 2018) Chassis No: VM20126918
 Colour: Silver Odometer: 124635 km
 Engine Capacity: 1597 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14
 Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
 Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,287.50	14,567.31	9,720.19	40.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,750.00	3,810.00	1,940.00	33.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,037.50	18,377.31	11,660.19	38.82
Approved Total (Overridden) (S\$)		14,600.00		
Nett Amount (S\$)	30,037.50	14,600.00	15,437.50	51.39
+ Car Rental (12.0 x S\$80.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		33.18		
Nett Liability (S\$)		15,593.18		
Global Sum Settlement (S\$)		15,500.00		

INSPECTION

Date of Assignment: 18/07/2024
 Date Inspected: 18/07/2024 Inspected At: Zoom Autowerks Pte Ltd (HQ)
 15 Kaki Bukit Road 4, #01-53
 Singapore 417808
 Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	858.60 FN	*858.60 FN
2	2		*FRONT BONNET HINGES	Bent	90.40 FN	*90.40 FN
3	1		*FRONT BONNET LOCK	Bent	67.90 FN	*67.90 FN
4	1		*FRONT BONNET INSULATOR	Not fitted	124.50 FN	*- FN
5	2		*FRONT HEADLAMPS	Holder cracked	1,730.00 FN	*1,241.00 FN
6	2		*FRONT HEADLAMP TOP PANELS	Bent / Buckled	230.40 FN	*230.40 FN
7	2		*FRONT HEADLAMP SIDE PANELS	Bent	270.00 FN	*270.00 FN
8	2		*FRONT HEADLAMP LOWER GARNISHES	Torn	697.20 FN	*697.20 FN
9	1		*FRONT GRILLE	Cracked	507.10 FN	*507.10 FN
10	1		*FRONT GRILLE LOGO	Scratched	75.20 FN	*75.20 FN
11	1		*FRONT BUMPER	Distorted	892.00 FN	*683.20 FN
12	1		*FRONT BUMPER INNER SPONGE	Not fitted	280.70 FN	*- FN
13	1		*FRONT BUMPER REINFORCEMENT	Bent	591.90 FN	*512.20 FN
14	2		*FRONT BUMPER SIDE RETAINERS	Cracked	80.40 FN	*80.40 FN
15	1		*FRONT BUMPER TOW HOOK COVER	Torn	19.40 FN	*19.40 FN
16	1		*FRONT FENDERS	N/S Repair / O/S Buckled	1,097.60 FN	*548.80 FN
17	2		*FRONT FENDER INNER SHIELDS	Not Necessary	154.20 FN	*- FN
18	1		*FRONT SUPPORT PANEL	Bent	325.30 FN	*325.30 FN
19	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	76.80 FN	*- FN
20	1		*FRONT LOWER CROSS MEMBER	Repair	325.00 FN	*- FN
21	2		*HORNS	Not Necessary	176.20 FN	*- FN
22	1		*AIR CON CONDENSER	Bent / Punctured	767.80 FN	*767.80 FN
23	1		*OIL COOLER	Not Necessary	1,657.30 FN	*- FN
24	1		*AIR DUCT	Torn	123.00 FN	*123.00 FN
25	1		*RADIATOR	Bent /Punctured	985.20 FN	*788.20 FN
26	1		*RADIATOR SIDE GARNISHES	Torn	196.00 FN	*196.00 FN
27	1		*RADIATOR FAN ASSY	Dented	572.60 FN	*572.60 FN
28	1		*RADIATOR SPARE TANK	Deformed	81.50 FN	*81.50 FN
29	1		*RADIATOR TOP HOSE	Not Necessary	80.00 FN	*- FN
30	1		*AIR INTAKE DUCT	Repeated	179.00 FN	*- FN
31	1		*FRONT WIPER TANK	Deformed	242.40 FN	*242.40 FN
32	1		*REAR WINDSCREEN INNER SEAL	No such part	85.00 FN	*- FN
33	1		*REAR TAILGATE	Badly Dented	2,201.40 FN	*2,031.20 FN
34	2		*REAR TAILGATE DAMPERS	Not Necessary	360.00 FN	*- FN
35	1		*REAR TAILGATE INNER BOARD	Torn	355.00 FN	*355.00 FN
36	1		*REAR TAILGATE INNER LOCK	Damaged	360.10 FN	*260.80 FN
37	1		*REAR TAILGATE LOGO	Not Necessary	188.30 FN	*- FN
38	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	370.90 FN	*- FN
39	1		*REAR TAILGATE RUBBER	Twisted	200.80 FN	*200.80 FN
40	1		*REAR TAILGATE 70KM/H STICKER	Necessary	25.20 FS	*10.00 FS
41	1		*REAR TAILGATE 6 PAX STICKER	Necessary	25.20 FS	*10.00 FS
42	1		*REAR TAILGATE NV 200 EMBLEM	Necessary	163.50 FN	*115.00 FN
43	1		*REAR TAILLAMPS	N/S Not Necessary /O/S Cracked	569.60 FN	*284.80 FN
44	1		*REAR END PANEL	Badly Dented	642.70 FN	*411.20 FN
45	1		*REAR END PANEL INNER MEMBER	Badly Dented	588.50 FN	*588.50 FN
46	1		*REAR END PANEL INNER GARNISH	Twisted	125.00 FN	*125.00 FN
47	1		*REAR BUMPER	Distorted	624.80 FN	*624.80 FN
48	1		*REAR BUMPER INNER SPONGE	Torn	133.80 FN	*133.80 FN
49	1		*REAR BUMPER SIDE RETAINERS	N/S Not Necessary /O/S Cracked	200.60 FN	*65.00 FN
50	1		*REAR BUMPER TOW HOOK COVER	Cut	48.00 FN	*25.00 FN
51	1		*REAR FLOOR PANEL	Crumpled	1,586.40 FN	*1,586.40 FN
52	1		*REAR SPARE TYRE CARRIAGE	Not Necessary	244.70 FN	*- FN
53	1		*REAR SPARE TYRE LOCK CATCH	Not Necessary	178.50 FN	*- FN
54	1		*REAR SIDE PANEL -RH	Repair	2,435.80 FN	*- FN
55	1		*SET FRONT BONNET INSULATOR CLIP	Not Necessary	45.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SET FRONT GRILLE CLIP	Not Necessary	25.00 FS	*- FS
57	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
58	1		*FRONT NUMBER PLATE WITH HOLDER	Bent	50.00 FS	*40.00 FS
59	2		*SET FRONT FENDER INNER SHIELD CLIPS	Not Necessary	80.00 FS	*- FS
60	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
61	1		*REAR TAILGATE ADVERTISEMENT STICKER	Not Necessary	300.00 FS	*- FS
62	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
63	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS
64	1		*SET REAR REVERSE SENSOR	Cracked	350.00 FS	*200.00 FS
65	1		*REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	26,809.40	16,145.90
- Nett Item Discount on N Items 10.00/10.00% (S\$)	2,521.90	1,578.59
Total Parts (S\$)	24,287.50	14,567.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	20.00
2	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
3	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	0.00
4	TO REMOVE AND REPLACED RAR REVERSE SENSOR AND CAMERA	New	150.00	30.00
5	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	80.00	60.00
6	TO REMOVE,REPLACE AIR-CON CONDENSER ,REFILL GAS & CONDUCT LEAKAGE TEST	New	180.00	100.00
7	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	100.00
8	TO APPLY UNDERCOATING	New	250.00	80.00
9	PANEL BEATING	New	2,400.00	1,800.00
10	TO RESPRAY PAINTING ON THE AFFECTED AREAS	New	2,200.00	1,600.00
Gross Labour Cost (\$\$)			5,750.00	3,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >